



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Ref: CS/AGI22005238/Kty3e2

Date: 21/06/2022

Code: AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGV 7387P	Veh. Inspected	SMN 242R
Policy No.		Coverage (\$)	0.00
Claim No.	C10015481 /JT	Excess (\$)	0.00
Assign From	MAYBIE CHUA	Assign Date	02/06/2022

2. Vehicle Particulars & Condition

Make & Model	RENAULT SCENIC (A)	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	VF1RFA00462704547	Colour	METALLIC SILVER
Odometer	216874 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R20	DAVANTI	4 mm
L/H Front Tyre	195/55 R20	DAVANTI	4 mm
R/H Rear Tyre	195/55 R20	TOURADOR	7 mm
L/H Rear Tyre	195/55 R20	TOURADOR	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/05/2022	Inspection Date	02/06/2022
Survey held at	MUNICH AUTOCARE PTE LTD 60 JALAN LAM HUAT #07-43 CARROS CENTER SINGAPORE 737869		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**