(08/11/13) wef

ASS. REC. BY: Marcus

REF: CS/ U0122005241 / Uvy3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMQ 500E

at Workshop m/s Specialist.

of

Insured: GBG 998K

Policy No.

Claims No. M11D15412206

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: $ 400k.

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 1.3.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMQ 500E Yr Regn: 09/01/20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or CA / LINE M-Hybrid

Make: Mer Benz S500 AMG c.c 2999

Colour Beige A/C: Insured / Std / NI / NA

Sp.Reading 36894 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD 2221602 A514073

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40R20

R: 275/35R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Continental

	Front		Rear	
R/Bal.	6	mm	6	mm
L/Bal.	6	mm	6	mm

D.O.A. 20/05/22 D.O.I. 2/6/22

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Dep 42k.
	SG carmart No 2020 model
27/7/22	P/P $ 3482.50 informed hailing (red 1982.50, 36%)

Date/Time, File Pass to? [ ] : Preli. Report

1) [ ] : Final Report

Date/Time, File Return to?

2) 28/7/22-typist

Report Format : TP

~~Lump Sum~~ / I.B.I: ($ 3482.50)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: [ ] : Site Insp ($) [ ] : Interview ($) [ ] : Tech. Invs ($) [ ] : Weekend ($)

Survey Fee:	210
Transportation:	60
__S + RS, __SI	80
Photos	37
Others	
TOTAL	387