

REF:

ASSIGNMENT

Veh No: FBN 8701K Yr Regn: 2018, Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Supra. C.C. 149

Colour Black A/C: Insured / Std / NI / NA

Sp. Reading 29015 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MH1KB211XJK*079280

Gen. Cond: ~~Good~~ / Fair / Poor / Burnt


Steering: ~~In order~~ / Jammed / Leaked / Burnt or

Brake: ~~inorder~~ / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 99/80 K11.

R: 120/70 R17.

| | |
|---|-----|
|  | |
| N/S | O/S |
| | |

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

ES/DSN/EXNO AT STT/STLZA/MICR/ORT/SS/TH/SSMM/
FORM NAME

TOYO/YOKO or IRC.

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mm

| | | | | | |
|--------|---|----|--------|--|----|
| L/Bal. | | mm | L/Bal. | | mm |
|--------|---|----|--------|--|----|

D.O.A. _____ D.O.I. 15/06/22

Survey held at One Garage.

Des. of Damages: Frt / Rear / O/S / ~~N/S~~ / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-------------|----------------------|
|-------------|----------------------|

TP Budget Direct.

mv :

PV :

Nett:

2630

☐: Prel. Report

Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: : Site Insp (\$

Report Formed :

Lamin. Sum. / LEL: 6

☐ : Site Insp (\$

 Interview (\$)

□: Tech. Invs (3)

Survey Fee:

Transportation:

Phoigs

J. Oliver