

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	GREAT AMERICAN	N INSURANCE COMPANY	Ref:	CS/GAI22005284/Gcy3e2	
	3 TEMASEK AVEN #16-01 CENTENNI SINGAPORE 0391	AL TOWER	Date	: 01/07/2022	
			Code	e: GAI	
1.	. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJR 9776Y	Veh. Inspected	SHA 3522R	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	CLMOMVC000004175	Excess (\$)	0.00	
	Assign From	SHERY WONG	Assign Date	02/06/2022	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA PRIUS	c.c	1798	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	JTDKB3FU403563548	Colour	BLUE	
	Odometer	919009 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
	L/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
	R/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
	L/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
4.	1. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	. General Information				
	Accident Date	02/06/2022	Inspection Date	02/06/2022	
	Survey held at	COMFORTDELGRO ENGINEER	ING PTE LTD		
		59 LOYANG DRIVE SINGAPORE 508969			
5a.					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days			