

**Lump Sum / I.B.I: (\$**



TAN CHONG MOTOR SALES PTE. LTD.  
911, BUKIT TIMAH ROAD  
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : BUKIT TIMAH  
CONTACT NO : 4694091  
REFERENCE : INS/IC/ZHR/0123/2022  
DATE : 10-MAY-2022

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD  
3 ANSON ROAD  
#16-00 SPRINGLEAF TOWER  
S(079909)  
TEL : 63896111  
FAX : 62247175

OWNER'S NAME : MS ZHANG XIA  
ADDRESS : -  
S(-)  
TELEPHONE NO : -

**DIRECT SETTLEMENT**

**OWNER CLAIMING LOSS OF USE / RENTAL**

~~CAR AT WORKSHOP~~ / CAR NOT AT WORKSHOP

**KINDLY REVERT TO ME ASAP**

10.05.2022

**EMAIL : zuhri@tanchong.com**

**OFFICE : 67038916 FAX : 64697472**

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM  
POLICY NO : TP-GW4346Y  
VEHICLE NO : SJY9803R  
MODEL CODE : BMW  
MODEL/YEAR : BMW MODEL  
ENGINE NO : BMW 120I  
CHASSIS NO : WBAUL52020VL55285  
MILEAGE : 1 KM  
DATE IN : 10/05/2022  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : MUHAMMAD ZUHRI  
ACCIDENT DATE : 29/04/2022

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJY9803R

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	CHECK ELECTRONIC	240.00	X
2 ZZ/002	RENEW RH WING MIRROR ASSY	390.00	<del>240</del> 390 /
3 ZZ/003	S/PAINT WING MIRROR COVER	300.00	250 /
4 ZZ/004	REMOVE TRAIMBOARD FINISHER TO ASSIST REPAIR	120.00	/
TOTAL LABOUR CHARGES		1050.00	

TAN CHONG MOTOR SALES PTE. LTD.  
 BUKIT TIMAH W/SHOP  
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJY9803R

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	MIRROR(HEATED) GLASS <i>con /</i>	5116 725 2893			211.00	
2	SUNDRIES <i>u /</i>	NPN			10.00	
3	R/F MIRROR COVER <i>m /</i>	5116 722 9262			116.00	
4	R/F MIRROR ASSY <i>con /</i>	5116 728 2026			626.00	
SUB TOTAL			0.00	0.00	963.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			0.00	0.00	0.00	
GRAND TOTAL			0.00	0.00	963.00	
OVERALL TOTAL			963.00			

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED



TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SJY9803R

TOTAL LABOUR CHARGES	1050.00
TOTAL SPARE PARTS CHARGES	963.00
GRAND TOTAL	2013.00 *

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	: - Rasu - Hy 90010018
SURVEYED DATE	: 01/06/2022 03/06/22 @ 1100
AUTHORIZED DATE	: 01/06/2022 2 days
EXCESS CLAUSE	: 0.00
LIABILITY	: 0.00
REMARKS	: CHINA TAIPING (BASED ON INS. OFFER 50-50)

Resu before paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	30/04/2022 15:28 (SGT)
Date of Accident	29/04/2022 18:10 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	XILIN AVE
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJY9803R
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	TINA CHEOG
NRIC No	SXXXX721E
Email Address	tina_718@icloud.com
Mobile Phone No	(Phone) +65-84887077
Alternative Phone No	(Home) +65-84887077

## VEHICLE PARTICULARS

Manufacturer	BMW
Model	120i
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1199

## INSURANCE COMPANY

Name of Insurance Company	Great Eastern General Insurance Limited
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	2021-V0118933-VDP-E001
Cover Note Number	-

## DRIVER

Name of Driver	TINA CHEOG
NRIC No	SXXXX721E

Date Of Birth	18/07/1973
Occupation	Indoor
Date Of Driving Pass	12/11/2005
Driving experience	16 YEARS AND 5 MONTHS
Gender	Female
Mobile Number	(Phone) +65-84887077
Alt. Phone Number	(Home) +65-84887077
Email Address	tina_718@icloud.com
Address	80 LORONG K TELOK KURAU
Address complement	02-02
Postcode	425710
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER ATTACHED

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GW4346Y
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	MONDAL SOMIR
Contact Number	(Phone) +65-85498763
Address	-
Address complement	-



Postcode  
Insurance Company Name  
Nature Of Damage  
Details of property damaged in accident  
No. Of Passenger (Including Driver)

-  
-  
-  
-  
-

## SKETCH PLAN


### IMPORTANT NOTICE


Vehicle No: S) Y 9803 \*


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

(A) My Vehicle No: SJY 9803R

Accident Location: xilin Ave

Accident Date: 29.04.2022

Time: 6:14 am (pm)

### - Brief Details Of Accident -

I was driving along xilin Ave and suddenly vehicle B overtake and hit my vehicle on RH Front Side Door mirror. And Door mirror is totally damage. I chasing the vehicle around 300 meter to make their stop and change the detail and take some photo.

### - Other Vehicle Involve Details -

(B) Veh No: GW4346Y Hp: 85495763 Pax: Driver Name: Mondal Somir  
(C) Veh No: Hp: Pax: Driver Name:

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	721E
Vehicle No.:	SJY9B03R
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Jun 2022
Vehicle Make:	B.M.W.
Vehicle Model:	120I A/T ABS D/AIRBAG 2WD 2DR SOFTTOP
Primary Colour:	Silver
Manufacturing Year:	2010
Engine No.:	B717I656N46820BD
Chassis No.:	WBAUL52020VL55285
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$38,257.00
Original Registration Date:	20 Oct 2010
First Registration Date:	20 Oct 2010
Transfer Count:	0
Actual ARF Paid:	\$38,257.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	31 Aug 2030
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$32,914.00
COE Rebate Amount:	\$27,109.00
Total Rebate Amount:	\$27,109.00

The information contained herein is correct as at 05 Jun 2022

OK



# BMW 1 Series 120i Cabriolet (COE till 09/2030)

Overview

Financial

Accessories

Similar

Research

Photos

Map

**88** 汽车贸易  
MOTOR TRADING



Price	\$97,830		
Depreciation ⓘ	\$11,760 /yr	Reg Date	28-Sep-2010 (8yrs 3mths 22days COE left)
Mileage	N.A.	Manufactured ⓘ	2010
Road Tax ⓘ	\$1,450 /yr	Transmission	Auto
Dereg Value ⓘ	\$29,058 as of today (change)	OMV ⓘ	\$34,455
COE ⓘ	\$34,935	ARF ⓘ	\$34,455
Engine Cap	1,995 cc	Power	115.0 kW (154 bhp)
Curb Weight ⓘ	1,460 kg	No. of Owners ⓘ	4