ASS. RECORDY: Steve 1 (S) 165 1)	00519143
ASSIG	MMENT
From: Date:	Veh No: SMP 8080C Yr Regn: 03/0/18"
Eslimated Cost:	Type: M.Car / M.Cyclo Novel Van / Lorry I. Taxl / Prime Mover /
OD / TE) WE ITP RES / OD RES / EVA / INV / MV	Truck / Traller or
To Inspect Vehicle No:	Make: Mercentos-Benz GLAIRO c.o. 1595
	Colour Grey AC: Insured / Std / NI / NA
of	Sp.Reading 12316 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	CNO: WDC 1569477747/808.
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder I Jammed I Leaked I Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnit or
Make of Veh:	Modi: NII / SIRVIN / STD A/RIM or
	Tyre Size: F: $0.35/50R/8$
(Policy Condition)	BS I DUN EXNOVA I GY I FS I LIZA I MIC I OHTSU I PIR I SUMI I
Remark: The veh had commenced its N/S O/S	•
repair at the time of inspection.	TOYO / YOKO or Rear
Bal. or Market Value:	R/Bal, S mm R/Bal, S mm
IDAC Accident Rport: Consistent?: Yes or No	UBal. C mm UBal. 5 mm
GIA / PR Seen: Consistent? : Yes or No	D.O.A. 0915/77 D.O.I. 2016/77
Est Repairs: days Res.: Yes or No	O.O. FIOTA Cucle
Lum Sum: % · 3 Val.: Yes or No	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
CA   REV   REP.   24 HRS	
Date: Person Contacted: Vehicle: IN / OU	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time   Action / Instruction	
MY-111K .	
X.	
	Days Of Repair:
Osle/Time, File Pass to? : Prell. Report	Resurvey No. of Trip: Survey Fee:
i) : Final Report	Transportation:
Date/Time, File Return to?	-
. 2) Add	: Interview (\$) Photos
Barried Females	:Tech, Invs (\$) Others
Reper Formet:	: Meel:eud (#
Lump Sun ( l.B.f. ()	TOTAL
A section of the sect	λ.

# ESTIMATE FOR SMP8080C

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

Vehicle & Document Information

**ECICS Limited** 

WIP No 57160

Reg No/Reg Date

SMP8080C / 23/02/2018

Motor Claims Department 10 Eunos Road 8

63374779

Date In/Mileage Chassis No

# to 0 / WDC1569422J471808

#09-04A Singapore Post Centre Singapore 408600

Engine No

27091031527836

Make/Model

MB/MB GLA 180 (X156) "FACELIFT"

Colour/Trim

027 787 Mountain Gr/ 043 381 MaringaFabr

Account No Date/Time Printed CSE Operator Terms 371 / Go Chee Han WE000073 31/05/2022/ 18:59 CH Credit Unit Price Disc% Amount Qty Description of Goods / Services Z REQUEST Customer Request M BPNSUN POLICY NO/ACC DATE : DMPPHQ22-001571 DRIVE IN/TP VEH NUMBER: 30-5-2022 // DATE IN/DATE SURVEY: DIRECT SETTLEMENT BY: 1440.00 A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH. 960.00 A BPIRES RESPRAY REAR BUMPER 380.00 / 0.10 A BPILAR USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNITY RESET MEMOR IDENTIFICATION STANDARD. NETT 120.00/ A BPILAB CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT 1186.13 1186.13 00.00 1.00 REAR BUMPER 596.27 (Mack) 596.27 00.00 BOTTOM BLACK TRIM BUMPER 1.00 1052.97 00.00 1052.97 1.00 REAR BOTTOM TRIM BUMPER (Chine) 14.00 4.81 00.00 67.34 - nec RIVET 217.60 Cupper cha 00.00 nec 1.00 217.60 FOOT STEP PLATE 66.38 66.38 00.00 1.00 LH/BOTTOM BRACKET BUMPER 66.38 1.00 66.38 00.00 RH/BOTTOM BRACKET BUMPER Sten (LKK) Go Chee Han DID: 6771 4336 HP: 9181 7717 20/6/72, 10.000 Email: chechan.go@cyclecarriage.com.sg Cycle & Carriage Industries Pte Ltd Confirmed & accepted by

Nett

6,153.07 430.71

LKK Auto Consultants hence notify

7% GST on 6153.07

Authorized signatory and company stamp?

**Total Payable** 

6,583.78

the removal of the windscreen.

Validity of this estimate is 14 days from date of quote religious a computer penerated document, no signature is required.

Estimated costs quoted are excluding 651. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. Nowever, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring

y kero(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

and Mercedes Benz are trademarks of Mercedes Benz Group AG

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg

Page 1 of 1





# SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
   This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate
- 4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
- 5. Any felse reporting may be referred to the Police for Investigation,
  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## **ACCIDENT STATEMENT**

Date of Submission Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

30/05/2022 00:16 (SGT) 29/05/2022 17:52 (SGT) Singapore Slip rd of Jurong east st 21 towards Toh guan road Singapore

## **DETAILS OF OWN VEHICLE**

SMP8080C

Vehicle Registration Number

INSURED/POLICYHOLDER

Is company? No Name Of Registered Owner OH BENG PHIO NRIC No S1768080C Email Address benpyh@gmail.com Mobile Phone No (Phone) +65-98769204 Alternative Phone No +65-98769204

VEHICLE PARTICULARS

Manufacturer Mercedes Model Gla180 Variant **URBAN (R18 LED)** Exact purpose for which vehicle was being used at time of Private use accident Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Vehicle Category Private car Transmission Auto CC 2143

INSURANCE COMPANY

EQ Insurance Company Ltd Name of Insurance Company Type of Coverage Comprehensive Fleet Policy No Policy Number DMPPHQ22-001571 Cover Note Number

DRIVER

BENJAMIN PNG YEOW HUI Name of Driver NRIC No S9420965Z

Accident report SA0A225T0005

Page 1 of 20



Date Of Birth Occupation Date Of Driving Pass Driving experience Gender Mobile Number

Indoor 07/07/2015 **6 YEARS AND 10 MONTHS** Male

(Phone) +65-98769204 Alt. Phone Number

benpyh@gmail.com Email Address Caspian, 50 Lakeside Drive BLK 50D Address

10/06/1994

#07-08 Address complement 648315 Postcode No Is the driver the policyholder? Parent

If No, Relationship of the Driver with the Insured No Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Collision - Head to Rear Type of Accident Weather Conditions Clear Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 2 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

PASSENGER 1

Name Angeline Png Xue Ting Gender Female

DETAILS OF POLICE ACTION

Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

My vehicle SMP8080C was stationary along the slip road of Jurong east st 21 towards Toh guan rd. While my vehicle was stationary waiting for the on coming traffic to clear, suddenly I felt an impact coming from my rear bumper and discover that the 3rd party SMM6546E had collided onto my vehicle while I was stationary. I managed to take some photos and exchange particulars with the 3rd party. I also had an in car camera footage of the scene.

ATTACHMENT(S)

Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any audio recorded? No

# **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SMM6546E Vehicle Manufacturer Renault Vehicle Model



Page 2 of 20



Addition continues
Addition continue
Addition continue
Addition
Ad

# NAMES OF TAXABLE PARTY OF TAXABLE PART

Transport was a series of the series of the

Frage Evel dis

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This form must be completed by the Policyholder and/or the Authorised Driver
- information provided must be as <u>truthful</u> and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the loggment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies
  of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident fall insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders

.

Driver's Signature (If driver is not the policyholder) Date & Time: VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER

MUHAMMAD SUMARDI BIN MOHD AFFANDI

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:




Policyholder's Signature

Date & Time

Page 4 of 20





Accident report SA0A225T0005

Page 5 of 20



SKETCH PLAN

REFER TO ATTACHED ACCIDENT DIAGRAM

#### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My vehicle SMP8080C was stationary along the slip road of Jurong east st 21 towards Toh guan rd. While my vehicle was stationary waiting for the on coming traffic to clear, suddenly I felt an impact coming from my rear bumper and discover that the 3rd party SMM6546E had collided onto my vehicle while I was stationary. I managed to take some photos and exchange particulars with the 3rd party. I also had an in car camera footage of the scene.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time: Driver's Signature (if driver is not the policyholder) Date & Time: VERIFY BY AJAX MARS (ARC) REPORTING OFFICER

MUHAMMAD SUMARDI BIN MOHD AFFANDI

Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

2







1 of 4

Report No. T/20220529/7068

Police Station Of Origin:

Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

## REPORT OF A TRAFFIC ACCIDENT

Date/Time 29/05/202		lade:	Vide Report No.:	Station Diary No.:			
Informant	's Particu	ilars					
Name of Informant: Address: BENJAMIN PNG YEOW HUI 50 LAKESIDE D				SINGAPORE 648315			
ID Type / I NRIC NO		5Z	Contact No.: Home/Office:	Mobile: 98769204			
Nationality: SINGAPORE CITIZEN			Email: BENPYH@GMAIL.COM				
Sex: Male	Age: 27	Date of Birth: 10/06/1994	Type of Informant: Driver				
Race: Chinese			Language: English	Institution / School Name:			
Occupation:			Driving Licence Information Class:	Date of Expiry:			

General Inform	mation of the Accid	dent		(A) (A) (A) (A) (A) (A)	BASA!	
Type of Accident:	Injury Others		Drink Drive: No	Date/Time of Accident: 29/05/2022 17:50		Type of Location: Slip Road (Outside of IMM - Toh Guan Road / Jurong East St 21)
Location: JURONG EA	ST STREET 21					
Weather: Clear	,	Road Su	urface:		Road	Speed Limit:
Traffic Flow: One Way		Traffic C	Traffic Control: Not Controlled		Traffic Volume: Moderate	
Type of Collis Between Mov	sion: ving Vehicles - Head	To Rear	- 35	oringida 	Anyo ambu No	ne conveyed by lance:

Details of Vehicle Involved						
Туре	Make	Model	Color	Conditio	No of	
Car			Grey	Slightly Damaged	0	
	Туре	Type Make	Type Make Model	Type Make Model Color	Type Make Model Color Conditio	







Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 2 of 4 Report No. T/20220529/7068

# CONTINUATION OF REPORT

Vehicle No.	Type	Make	Model	Color	Conditio	No of
SMP8080C	Car	MERCEDES BENZ	GLA180	Grey	Slightly Damaged	1

	ehicle Insurance Insurance Company	Insurance No	Effective	Expiry Date
	A STATE OF THE PARTY OF THE PAR		00/00/0000	2010010000
SMP8080C	EQ INSURANCE COMPANY LTD.	DMPPHQ22-	23/02/2022	22/02/2023
Civii Cocco		001571		

Details of Perso	n Involved		7 W		
Any Pedestrian Ir	nvolved: No				
No. of Pedestrian		Use of Pedestrian Crossing: NA			
Driver			ID No.		
Name	GOH YONG LEE				S1815840Z
Related Vehicle	SMM6546E (Car)			ct No.	NIL
Hospital/Clinic	NIL			of g ce &	Class: NIL Date of Expiry: NIL
Date	NIL	Date		NIL	
No. of Days granted Medical Leave NIL De				NIL	
Driver					
Name	BENJAMIN PNG YEOW HUI		ID No		S9420965Z
Related Vehicle	SMP8080C (Car)		Contact No.		98769204
Hospital/Clinic	NIL			of g ce &	Class: NIL Date of Expiry: NIL
Date	NIL	Date	- y thit	NIL	
No. of Days gran	nted Medical Leave NIL	Degree of	ented h	NIL	Leav.





3 of 4

Report No. T/20220529/7068

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

#### CONTINUATION OF REPORT

Passenger									
Name	ANGELINE PNG XUE TING			ID No.	,	S9825217G			
Related Vehicle	SMP8080C (Car)			SMP8080C (Car)			Conta	ct No.	98388339
Hospital/Clinic	CENTRAL MEDICAL GROUP PTE LTD		PTE LTD	Class Driving Licence Expiry	g ce &	Class: NIL Date of Expiry: NIL			
Date	29/05/2022 Date				29/05	5/2022			
No. of Days grant	ed Medical Leave	03	Degree of		Sligh	t			

#### Brief Details.

We had just exited IMM and was at the slip road between Toh Guan Road and Jurong East St 21 waiting for the road to be clear before I drove out. I was rear-ended by the vehicle (Carplate SMM 6546E) and driver Goh Yong Lee (S1815840Z).

We have video-footage of front and back car-camera. Relevant footage has been submitted to the car insurance company.

We have also seen a GP Doctor and received three days MC as well as medication.

Accident did not take place at a pedestrian crossing, it's just after the zebra crossing.





4 of 4

Report No. T/20220529/7068

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

CONTINUATION OF REPORT

SI	100	10	h 1	D)	-	n
	1.851	100		-	100	1.8

Informant is not able to provide sketch

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.				
Signature Of Interpreter: Not applicable	Date/Time: 29/05/2022 21:25	e galekter.			
Officer In Charge Of Case: TP / TPIB / MUHAMMAD NOOR BIN ABDUL RAHMAN Contact No.: 65476219	Classification Of Case:				
ND168					