

REF:

SMRT/ 22005307/KV

C

ASSIGNMENT

11

02/06/2022

1st



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TP

Vehicle No. : SMN2050P

Make & Model : bluecar

Year of Manufacture : 2018

Chassis No. : VL4BCEB4RJT003545

Engine No. :

Policy No. :

Time of Accident :

Ins Company : LIBERTY VS MS FCI

Excess :

Date of Accident : 31/05/2022

Suggested Days of Repair :

In-house Vehicle Assessor

Repair Estimates

Case Owner : PATRICK

Signature :

Parts (a) Cost / List Price Items \$ 2,702.83

Plus/Less 20% \$ 540.57

Total of Cost / List \$ 3,243.40

(b) Nett Price Items \$ -

Less :

Total of Nett Item

(c) Special Nett Items \$ 100.00

Total Parts Cost (Appendix A) \$ 3,343.40

Labour (Appendix B) \$ 2,850.00

Total Repair Cost \$ 6,193.40

Contact No

Frt Counter Operation

Brenda Tel: 63837730 email: brendang@sparkcarcare.com

Rohani tel: 63837890 email: rohanim@sparkcarcare.com

Back-end Operation

Ngo Toh Wee Tel: 63837656 email: ngotw@sparkcarcare.com

Patrick Tel: 63837441 email: patricktia@sparkcarcare.com

Not authorized
 Repair B & paint
 11pm @ 31/05/22

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
 Company : CRIC
 Survey conducted on : 31/5/22 at 11.30am

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor : *Be* Date: 31/5/22

A314-32-C6Z5



Gigabit Ethernet

ComfortDelGro Engineering Pte Ltd

Tel: 63837168 / 63837466 Fax: 62815767

Vehicle No.

Case Owner

PATRICK

Year of Manufacture

2018

IKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62815767

Page 1

Spare Parts

Vehicle No : SMN2050P Case Owner : PATRICK
 Make & Model : bluecar Year Manufacture : 2018
 Chassis No : VL4BCEB4RJT003545 Engine No : 0
 Sales Order : _____ Supplier : _____
 Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposit Surveyo
1	REAR NUMBER PLATE W/CASING	1			<u>B</u>	\$ 50.00	<u>45/2</u>
2	REAR BUMPER	<u>Bn</u> 1	\$ 1,169.60				<u>✓</u>
3	REAR BUMPER RIVET	<u>m</u> 3	\$ 1.20				<u>✓</u>
4	FRONT BUMPER	<u>B</u> 1	\$ 1,143.10				<u>✓</u>
5	FRT NUMBER PLATE W/CASING	1			<u>B</u>	\$ 50.00	<u>45/2</u>
6	FRT BUMPER TOP MESH	<u>sn</u> 1	\$ 35.94				<u>X</u>
7	FRT BUMPER MESH RIVET	<u>m</u> 20	\$ 8.00				<u>X</u>
8	FRT BUMPER INFORCEMENT	<u>R</u> 1	\$ 189.73				<u>X</u>
9	FRT BUMPER SPONGE	<u>sn</u> 1	\$ 155.26				<u>X</u>
10	0	1					
11	0	1					
12	0	1					
13	0	<u>Plus</u> 1	<u>206</u>				
14	0	1					
15	0	1					
16	0	1					
17	0	3					
18	0	1					
19	0	6					
20	0	1					
21	0	1					
22	0	1					
23	0	1					
24	0	1					
25	0	1					
26	0	1					
27	0	1					
28	0	1					
29	0	1					
30	0	1					

If any of the quoted parts are recommended to be repaired, then an additional labour charge charged accordingly under supplementary.

06/2022

5:20 PM