

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Reg. No. 199007	198R GST Reg. No. 19	9-96071	190-K	
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	R	tef:	CS/AGI22005312/Kty3m4	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	D	ate:	24/06/2022	
			C	ode:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	FBK 1848H	Veh. Inspected		SMN 6082X	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C20015619/CD	Excess (\$)		0.00	
	Assign From	MAYBIE CHUA	Assign Date		03/06/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA FIT (A)	c.c		1317	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	GK33417150	Colour		METALLIC BLUE	
	Odometer	67077 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	175/70 R14	BRIDGESTONE		8 mm	
	L/H Front Tyre	175/70 R14	BRIDGESTONE		8 mm	
	R/H Rear Tyre	175/70 R14	BRIDGESTONE		8 mm	
	L/H Rear Tyre	175/70 R14	BRIDGESTONE		8 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	01/06/2022	Inspection Date		08/06/2022	
	Survey held at	rey held at ACCORD AUTO SERVICES PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTO POINT #03-11 SINGAPORE 568047				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

6 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: