



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22005331/Vvy3q2 Date: 19/08/2022	Code: AGI
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SGT 471K	Veh. Inspected	SJU 258U	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10015555 /CH	Excess (\$)	0.00	
Assign From	MAYBIE CHUA	Assign Date	06/06/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	NISSAN QASHQAI	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	SJNFBAJ11U2900292	Colour	WHITE	
Odometer	62487 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/45 R19	PIRELLI	6 mm	
L/H Front Tyre	225/45 R19	PIRELLI	6 mm	
R/H Rear Tyre	225/45 R19	PIRELLI	6 mm	
L/H Rear Tyre	225/45 R19	PIRELLI	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	30/05/2022	Inspection Date	06/06/2022	
Survey held at	25 Kaki Bukit Road 4 #06-53 SYNERGY @ KB			
Repairer	GLOCKEWERKE			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	