

REF:

ASSIGNMENT

Veh No: SMS4191B - Yr Regn: 2020 Feb

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Avante c.c. 1591

Colour Black A/C: Insured / Std / NI / NA

Sp. Reading 17486 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KMH D841 CMLW 029 854

Gen. Cond (Good) / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: ~~In order~~ / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/60 R15

R: 193/65R15.

	
N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Nexen

Front

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A.	D.O.I.	07/06/22
--------	--------	----------

*Survey held at For Motor

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Action / Instruction

TP China.

MV:

PV:

Nett:

701 I

☐: Prel. Report

Days Of Repair:

Final Report

Resurvey No. of Trip:

Add Fee: : Site Insp (\$

Survey Fee:

Transportation:

Photos

Culver

Report Format :