



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI22005336/Uty3e2	
			Date: 15/06/2022	
			Code: UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJC 2333S	Veh. Inspected	SKJ 6912X	
Policy No.		Coverage (\$)	0.00	
Claim No.	M12D18642206	Excess (\$)	0.00	
Assign From	JOSEPHINE WONG	Assign Date	06/06/2022	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN GOLF A7 (A)	c.c	1395	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WVWZZZAUZDW101453	Colour	RED / YELLOW	
Odometer	116928 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	GOODYEAR	6 mm	
L/H Front Tyre	225/40 R18	GOODYEAR	6 mm	
R/H Rear Tyre	225/40 R18	GOODYEAR	6 mm	
L/H Rear Tyre	225/40 R18	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/06/2022	Inspection Date	06/06/2022	
Survey held at	ZOOM AUTOWERKS PTE LTD 130 BEDOK RESERVOIR ROAD, #08-1339,EUNOS SPRING SINGAPORE 470130			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	