

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	06/06/2022
Vehicle Reg. No.:	SHA5383L	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Vehicle Reg. Date:	11/03/2020
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEKU407489	Chassis No:	KMHC851CVLU189571
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	1,886.64
Miscellaneous Items	11.00
Labour	1,170.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,067.64
+ GST 7.00% (S\$)	214.73
Nett Amount (S\$)	3,282.37

This claim is handled by: **CHIANG LIAT CHOON**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Jun 2022)
Parts: 143 HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SHA5383L/07/06/2022 10:12
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	*459.40 FL <i>Ry</i>
2	1		*REAR BUMPER CENTRE MOULDING	20.00	0.00	*451.25 FL <i>de</i>
3	1		*REAR BUMPER REINFORCEMENT BEAM	20.00	0.00	*394.80 FL <i>?</i>
4	2		*REAR BUMPER REINFORCEMENT BEAM TOP BRACKET L/R	20.00	0.00	*276.20 FL <i>?</i>
5	10		*REAR BUMPER CLIPS	20.00	0.00	*22.00 FL <i>re</i>
6	2		*REAR BUMPER SIDE RETAINER -L/R	20.00	0.00	*111.60 FL <i>X</i>
7	1		*REAR BUMPER FOG LAMP	20.00	0.00	*201.50 FL <i>X</i>
8	1		*REAR NUMBER PLATE LIGHT LAMP	20.00	0.00	*85.30 FL <i>X</i>
9	1		*REAR NUMBER PLATE W/HOLDER	0	0.00	*55.00 FS <i>K</i>
10	1		*REAR REVERSE SENSOR	0	0.00	*180.00 FS <i>?</i>
11	1		*REAR BUMPER MAT	0	0.00	*50.00 FS <i>X</i>
Sub Total (S\$)						2,287.05
- List Item Discount on L Items (S\$)						400.41
Total Parts (S\$)						1,886.64

F=Franchise part. S=SpcNett. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHA5383L/07/06/2022 10:12. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			11.00
1	1	OD/TP Case (Insurer)	
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	350 750.00
2	SPRAY PAINTING	New	250 300.00
3	CHECK LIGHTING % WIRING	New	60.00
4	REMOVE/REFIX REVERSE SENSOR	New	30 60.00
Gross Labour Cost (S\$)			1,170.00

ComfortDelGro Engineering Pte Ltd/SHA5383L/07/06/2022 10:12. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanphi 97495749
 WP 7/6/22 @ 345
 p/p Resurvey new parts
 2 days
 Tanphi @ Lkhantoum

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Date/Time: 07.06.2022 09:42 Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4254112


JC NO.305518748

CUSTOMER MR/MS CUSTOMER NO ADDRESS TEL. (R) (P) DISCOUNT CARD NO.	COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (O)	REGN NO: SHA5383L	MILEAGE
		MAKE: HYUNDAI	FUEL E.....1/2.....
		MODEL IONIQ(G3)	DATE/TIME IN 06.06.2022 15:15
		YR OF MANU 11.03.2020	TARGET DATE
		CHASSIS CODE KMHC851CVLU189571	COMPLETION DATE/TIME

JOB DESCRIPTION

Accident Date: 06.06.2022
 NATURE: 3P 06.06.2022

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

acknowledgement Slip

Exit Pass

Name:
 ID No.:
 Vehicle No.: **SHA5383L** **CHIANG**

Vehicle No.: **SHA5383L**

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

To be returned to Service Reception upon collection

To be kept by Security Guard