

## ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

**TP INSURER:** Tokio Marine Insurance Singapore Ltd (HQ)  
**CTPL**

Singapore

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	06/06/2022
Vehicle Reg. No.:	<b>SHA5383L</b>	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Vehicle Reg. Date:	11/03/2020
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEKU407489	Chassis No:	KMHC851CVLU189571
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

**COST OF CLAIMS**

	<b>Amount</b>
Parts	1,886.64
Miscellaneous Items	11.00
Labour	1,170.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>3,067.64</b>
<b>+ GST 7.00% (S\$)</b>	<b>214.73</b>
<b>Nett Amount (S\$)</b>	<b>3,282.37</b>

**This claim is handled by: CHIANG LIAT CHOON**

**R DETAILS**

Reference

Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Jun 2022)

Model: 143 HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)

Source: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHA5383L/07/06/2022 10:12

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	*459.40 FL <i>ly</i>
2	1		*REAR BUMPER CENTRE MOULDING	20.00	0.00	*451.25 FL <i>de</i>
3	1		*REAR BUMPER REINFORCEMENT BEAM	20.00	0.00	*394.80 FL <i>ghn</i>
4	2		*REAR BUMPER REINFORCEMENT BEAM TOP BRACKET L/R	20.00	0.00	*276.20 FL <i>ghn</i>
5	10		*REAR BUMPER CLIPS	20.00	0.00	*22.00 FL <i>me</i>
6	2		*REAR BUMPER SIDE RETAINER -L/R	20.00	0.00	*111.60 FL <i>ghn</i>
7	1		*REAR BUMPER FOG LAMP	20.00	0.00	*201.50 FL <i>ghn</i>
8	1		*REAR NUMBER PLATE LIGHT LAMP	20.00	0.00	*85.30 FL <i>ghn</i>
9	1		*REAR NUMBER PLATE W/HOLDER	0	0.00	*55.00 FS <i>ghn</i>
10	1		*REAR REVERSE SENSOR	0	0.00	*180.00 FS <i>ghn</i>
11	1		*REAR BUMPER MAT	0	0.00	*50.00 FS <i>ghn</i>

Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,287.05
- List Item Discount on L Items (S\$)	400.41
<b>Total Parts (S\$)</b>	<b>1,886.64</b>

ComfortDelGro Engineering Pte Ltd/SHA5383L/07/06/2022 10:12. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

473.25  
20% 378.60

10:12 AM

Estimates on Miscellaneous Items

Qty	Particulars	Amount
<u>Miscellaneous Items</u>		
1	OD/TP Case (Insurer)	11.00
<b>Sub Total (\$)</b>		<b>11.00</b>

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	350 750.00
2	SPRAY PAINTING	New	250 300.00
3	CHECK LIGHTING % WIRING	New	60.00
4	REMOVE/REFIX REVERSE SENSOR	New	30 60.00
<b>Gross Labour Cost (\$)</b>			<b>630 1,170.00</b>

ComfortDelGro Engineering Pte Ltd/SHA5383L/07/06/2022 10:12. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanji 97495749 \$1019.60  
 up 7/6/22 @ 315 \* 2 days.  
 p/p Resurvey new parts  
 2 days  
 tanji@lkk.com

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: