

ASS. REC. BY:

REF: C72/ 220054421Kv

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

I.B.I. %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No: GBL 5049R

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NIS NV200

C.C.

1598

Colour: M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading: 11157

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: JN1YAA M207

0002161

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: 165/80R14

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mm

R/Bal. 9 mm

L/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 6/6/22

D.O.I. 8/6/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐


: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

**CHENG HOE MOTOR PTE LTD**

BK 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761
Tel : 67556142 Fax : 67557719
Email: chmotor@singnet.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
KAL TRANSPORT PTE LTD
Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP/CHINA(CB8487E)
Policy No:	DMB1SNW00003732205	Date of Loss:	06/06/2022
Vehicle Reg. No.:	GBL5049R	Driveable?	
Party At Fault:	UNKNOWN	Driver (Insured):	LI JUNYI
Driver (TP):	AU YUAN RONG		
Make/Model:	NISSAN NV200, 1.6 PETROL (A)	Vehicle Reg. Date:	31/08/2021
Vehicle Colour:	SILVER	Chassis No:	JN1YAAM20Z0002161
Engine No:	HR16188911D		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Remarks:	VEHICEL CURRENTLY LYING ANG MO KIO WORKSHOP.		
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		

*Not authorized
Repair B & paint
7 days*

COST OF CLAIMS	Amount
Parts	3,902.00
Miscellaneous Items	290.00
Labour	2,010.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	6,202.00
+ GST 7.00% (\$)	434.14
Nett Amount (\$)	6,636.14

This claim is handled by: SHARON CHIONG BENG CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 08 Jun 2022)
Parts: N/A NISSAN NV200 1.6 PETROL (A) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GBL5049R)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC REAR BUMPER	0.00	0.00	*390.00 F
2	1		*1 PC REAR BUMPER SPONGE	0.00	0.00	*95.00 F
3	1		*6 PCS REAR BUMPER CLIPS @2/PC	0.00	0.00	*12.00 F
4	1		*1 PC TAILGATE	0.00	0.00	*1,250.00 F
5	1		*1 PC TAILGATE INNER LOCK	0.00	0.00	*55.00 F
6	1		*1 PC TAILGATE INNER RUBBER	0.00	0.00	*100.00 F
7	1		*1 PC TAILGATE LOGO	0.00	0.00	*65.00 F
8	1		*1 PC TAILGATE EMBLEM (NV200)	0.00	0.00	*65.00 F
9	1		*1 PC TAILGATE EMBLEM (VANETTE)	0.00	0.00	*65.00 F
10	1		*1 PC TAILGATE OUTER GARNISH	0.00	0.00	*195.00 F
11	1		*1 PC REAR END PANEL (OUTER)	0.00	0.00	*150.00 F
12	1		*1 PC REAR END PANEL (INNER)	0.00	0.00	*490.00 F
13	1		*1 PC REAR END PANEL INNER TOP GARNISH	0.00	0.00	*90.00 F
14	1		*4 PCS REAR END PANEL INNER TOP GARNISH CLIPS @5/PC	0.00	0.00	*20.00 F
15	1		*1 PC REAR FLOOR BOARD	0.00	0.00	*860.00 F
Total Parts (\$\$)						3,902.00

F=Franchise part.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
1	1	1 PC TAILGATE STICKER - 70KM/H	10.00
2	1	1 SET REVERSE SENSOR	200.00
3	1	1 UNIT REAR END PANEL SEALANT	40.00
4	1	1 UNIT REAR WINDSCREEN GLASS SEALANT	40.00
Sub Total (\$\$)			290.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Estimates on Labour

No	Particulars	Lab.Type	Amount
1	REMOVE & REFIX REAR WINDSCREEN GLASS	New	120.00
2	REMOVE & REFIX REAR BUMPER & ATTACHMENT, TAIL LAMP'S, TAILGATE & ATTACHMENTS, CUT, WELD & RENEW REAR END PANEL OUTER & INNER, REAR FLOORBOARD AND REALIGN THE SAME	New	1,000.00
3	PUTTY & RESPRAY TAILGATE, REAR END PANEL OUTER & INNER, REAR FLOORBOARD AND ALL AFFECTED AREAS	New	800.00
4	RUSTPROOFING	New	90.00
Gross Labour Cost (\$\$)			2,010.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please provide correct details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be managed by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the completion of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 07/06/2022 10:43 (SGT)
Date of Accident 06/06/2022 15:23 (SGT)
Exact Location of Accident Singapore
Additional Location Information WHITLEY RD TWDS DUNEARN RD
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBL5049R

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner EVERGREEN CLEANING & LANDSCAPING SERVICE
Company Reg No 5XXXX855C
Email Address sales@evergreenlandscape.com.sg
Mobile Phone No (Phone) +65-65553811
Alternative Phone No (Office) +65-65553811

VEHICLE PARTICULARS

Manufacturer Nissan
Model Nv200
Variant -
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Commercial vehicle
Transmission Auto
CC 1600

INSURANCE COMPANY


Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd.
Type of Coverage Comprehensive
Fleet Policy No
Policy Number DMCVSNW00104692100
Cover Note Number 31/08/2021 - 30/08/2022

DRIVER

Name of Driver AU YUAN RONG
NRIC No SXXXX741G

Sketch Plan

Dunearn Rd




A: GBL5049R
(alone)

B: (B 8487E
(w/ school kids))

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle No: GBL5049R (China)
Date & Time: 06/06/2022 @ 1523 (clear/dry)

refer to police notice of reporting.



Note: Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the following particulars are true in every respect.



Policyholder's Signature
Date & Time:

Yuan Kang
Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Policyholder's Signature
Name: (AMK)
NRIC/FIN No.:

- () Claim Own Policy () Claim Third Party () Reporting Only
() Claim OD/TP at other workshop