

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive, Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305518857
Date : 14.06.2022

FINALIZATION FORM

To : LKK
Attn : THEVAN
Vehicle Reg No : SH 9418C

Fax :
Date of Accident : 08.06.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- The repair job shall bill to: HL ASSURANCE --- SDN1225R
- The finalized amount shall be:
 - (a) Spare Parts after List discount _____
 - (b) Labour Charges (Include advertisement stickers etc, if any) _____
 - Total for Part-By-Part Repair Cost _____
 - (c) Lumpsum Repair (if applicable) _____
 - Total for Lumpsum repair cost after Less: 20% \$3,050.00
 - Final Lumpsum Repair cost \$3,050.00
- Estimated normal period for repairs: 3 working days.
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
- Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : Lim J
Name : LIM TS
Tel : 62148398
Fax : 65468156

Signature : csee folder
Name : THEVAN
Date : _____

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49 /\$2.00	Y		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks: _____