

ASS. REC. BY:

REF:

CS/INC22005465/Any3

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. MT/1170829-002

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SFQ6016E Yr Regn: 2010 JulyType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Bmw 523 c.c. 2497Colour: Black A/C: Insured / Std / NI / NASp. Reading: 191889 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WBAFP32070C544981Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 245/45 R18R: 245/45 R18BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. \_\_\_\_\_ D.O.I. 08/06/22Survey held at HDDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP INCCOE Expiry: 28/07/30

22/09/22 Adrian confirmed lump sum: \$6900 and 6 days

MV : (red, 19036.04, 73%)

PV :

Nett :

Date/Time, File Pass to?

1) 22/09/22

Date/Time, File Return to?

2)

Report Format :

1. Number, 2. Name, 3. P.P. 1. 2. 3.

6900



: Preli. Report



: Final Report

Days Of Repair: 6Resurvey No. of Trip: 2

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

|  |
|--|
|  |
|  |
|  |
|  |
|  |
|  |