



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI22005472/Any3q2 Date: 04/10/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJL 7972S	Veh. Inspected	SLP 294S
Policy No.		Coverage (\$)	0.00
Claim No.	C10015719 /CD	Excess (\$)	0.00
Assign From	MAYBIE CHUA	Assign Date	08/06/2022
2. Vehicle Particulars & Condition			
Make & Model	MAZDA 3	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6BN22A8H0151225	Colour	SILVER
Odometer	267140 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	DAVANTI	6 mm
L/H Front Tyre	205/60 R16	DAVANTI	6 mm
R/H Rear Tyre	205/60 R16	DAVANTI	6 mm
L/H Rear Tyre	205/60 R16	DAVANTI	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/06/2022	Inspection Date	09/06/2022
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	