1 KAKI BUKIT AVE 6 #02-06 AUTOBAY@KAKI BUKIT SINGAPORE 417883 TEL: 67477636, 67473005 FAX: 67485071 Email: kangcar@singnet.com.sq Co. Reg. No. 201300201N GST Reg. No. 201300201N

Our Ref: KCR0520223005CTI

Your Ref: GBF3347A

Date

28.02.2023

WITHOUT PREJUDICE

China Taiping Insurance (Singapore) Pte Ltd C/O LKK Auto Consultant Pte Ltd

51 Ubi Ave 1

#01-25 Paya Ubi Industrial Pk

Singapore 408913

Attention: Motor Claim Department

Dear Sirs,

## Accident involving SLH3005H and GBF3347A on 30.05.2022 along Blk 614A Woodlands Ave 4 MSCP.

We refer to the above accident. On our record showed that you are the insurer of motor vehicle GBF3347A.

We are instructed that the accident was caused by your insured's negligent driving and/or management of his vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense.

On behalf of and as authorized by Ms Teo Hui Yin, the owner of motor-vehicle no: SLH3005H, we submit his claim to you:

Cost of repairs (Inclusive of 8% GST) \$4,158.00 Loss of Use  $(3days \times \$).00$ 240.00 GIA search fee 2.00

\$ 4,400.00

Enclosed herewith are copies of the following documents in support of our client's claim:

- 1) Tax invoice no: KCR-INV2300054
- 2) GIA report of SLH3005H
- 3) GIA search fee and invoice

We hope to receive your early reply soon.

Thank you.

Yours faithfully.

KANG CAR REPAIRERS PTE LTD



1 KAKI BUKIT AVE 6 #02-06 AUTOBAY@KAKI BUKIT SINGAPORE 417883 TEL: 67477636, 67473005 FAX: 67485071 Email: kangcar@singnet.com.sg Co. Reg. No. 201300201N GST Reg. No. 201300201N

M/S: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 ANSON ROAD

FAX: 62247175

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

TEL: 63896111

ATTN: Motor Claim Department

Your Ref No: Claim Type: Third Party Accident Date: 30/05/2022

**GBF3347A** 

TP Veh Reg No: GBF3347A

Final No: KCR-INV2300054

Claim No: EST2200182

Date: 08 Feb 2023

Policy No: 5125053344 Veh Reg No: **SLH3005H** 

Make/Model: BMW X1 SDRIVE 18I

M SPORT AT LED NAV

Chassis No: WBAHS120605F02420 Engine No:

F026H294B38A15A

Reg. Date:

28/10/2016

## Tax Invoice to Vehicle No :SLH3005H

Description	Quantity   List	Price Amount
•		CC CC
		22

As recommended by surveyor to proceed repair at total cost/lumpsum cost

S\$ 3,850.00

Add GST @ 8%

308.00

Total Amount payable

S\$ 4,158.00

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND ONE HUNDRED FIFTY EIGHT ONLY

For Kang Car Repairers Pte Ltd

E. & O. E.

AUTHORISED SIGNATURE

SK0M225V0004 / KANG CAR REPAIRERS PTE LTD ENTRY DATE & TIME: 31/05/2022 18:44 (SGT) SUBMITTED BY: ALICE TNG VERSION: 1 (31/05/2022 18:44 (SGT))



## SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- . This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible, Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **ACCIDENT STATEMENT**

Date of Submission

Date of Accident

**Exact Location of Accident** 

Additional Location Information

Country/State of Loss

31/05/2022 18:44 (SGT) 30/05/2022 23:12 (SGT)

Singapore

Blk 614A Woodlands Avenue 4 multi-storey carpark

Singapore

### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number

SLH3005H

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

NRIC No.

**Email Address** 

Alternative Phone No

Mobile Phone No

No

Teo Hui Yin SXXXX488B

danielle.thy83@gmail.com

(Phone) +65-90736885

+65-90736885

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category

Transmission

CC

**BMW** 

X1

Private use

No - Claiming third party

Private car

Auto

1600

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage

Fleet Policy Policy Number

Cover Note Number

NTUC Income Insurance Co-operative Ltd

Comprehensive

No

5125053344

DRIVER

Name of Driver NRIC No

Teo Hui Yin SXXXX488B



Date Of Birth

Occupation

Date Of Driving Pass

Driving experience

Gender

Mobile Number

Alt. Phone Number

**Email Address** 

Address

Address complement

Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions

Road Surface

Collided into Parked Vehicle

Clear Dry

No

No

Yes

1

No

2

13/05/1983

24/10/2008

+65-90736885

13 YEARS AND 7 MONTHS

(Phone) +65-90736885

danielle.thy83@gmail.com

Blk 610 Woodlands Avenue 4 #10-437

Outdoor

Female

730610

Yes

No

OTHER INFORMATION

Was any foreign vehicle involved in the accident?

Number of vehicles involved in the accident

Was anybody injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any other vehicle or property damaged?

Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

DETAILS OF POLICE ACTION

Was the accident reported to the police?

Was notice of intended Prosecution given?

If yes, against whom?

No No

CIRCUMSTANCES OF ACCIDENT

I had parked my vehicle SLH3005H in the parking lot at Blk 614A Woodlands Ave 4 multi-storey carpark. I had just stepped out of my vehicle when I saw the vehicle GBF3347A reversing to park into the opposite lot and his vehicle's front left portion hit onto my vehicle's front left portion, causing damage.

ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Was there any audio recorded?

Yes Nο

No

### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

Vehicle Manufacturer

Vehicle Model

Vehicle Variant

Vehicle Colour

Vehicle Category

Name of Driver

NRIC No

**GBF3347A** Nissan Cabstar

Commercial vehicle

Ng Kian Hong

SXXXX435G



Page 2 of 20

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Rease report correctly the details of the accident to speed up the claims process
- 2 This Formmust be completed by the Policyholder and/or the Authorised Oriver
- 3 Information provided must be as <u>truthful and accurate as possible</u>. Any wiful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
- 7 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer . my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquines by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail peckages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the 'Purposes')

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

31 05 86.12 pm

PolicyHolder's Signature / Date

Driver's Signature (If driver is not the policyholder) / Date

& Time

Sketch Plan

Wilnessed by Reporting

Personnel

B) GBF 3347A

Describe Circumstances of the Accident
I had parked my reliable SLH3005H in the Parking
lot at BIK 614A Woodlands Ave 4 multi-storey
carpark. I had just stepped out of my reliede when
I saw the relicle GBF 3347A reversing to park
into the opposite parking lot and his vehicle's front
Teft portion hit onto my reliale's front left portion,
causing danage.

## Declaration

IWe declare the foregoing particulars are true in every respect

Driver's Signature of driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

## INSURER ENQUIRY

## **Find** insurer

Vehicle reg. no.

GBF3347A

**Date of Accident** 

30/05/2022 🛗

Reset

## % RESULT & RECEIPT

# **TP Insurer Enquiry** Insurance China Taiping Insurance (Sing... Period of Insurance 17/09/2021 - 16/09/2022 Requested By ...... ALICE TNG (KANG CAR REPAIR...

## Payment details

Request Amount: **\$\$1.87** GST Amount: \$\$0.13

Total Amount Due (GST Inclusive): \$\$2

## **General Insurance Association**

**Records Management Centre** GST Registration No: M400017735