(08/11/13) wef

ASS. REC. BY: Rosm

REF: CS3/ASM 21008928/RVC-1

Reinspection

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: YQ 2538S

at Workshop m/s Borneo motor

of 2, Pandan Crescent

Insured: ASM

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value:

IDAC Accident Rport: Consistent? : **Yes** or **No**

GIA / PR Seen: Consistent? : **Yes** or **No**

Est. Repairs: days Res.: **Yes** or **No**

Lum Sum: % 3 Val.: **Yes** or **No**

CA / REV / REP. / 24 HRS

Vehicle: **IN / OUT**

Date: Person Contacted:

Veh No: YQ 2538S Yr Regn: 2020 / SEP

Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer** or

Make: Hino XZU710R-HKFS-ST c.c 4009

Colour WHITE A/C: **Insured / Std / NI / NA**

Sp.Reading – T/Radio: **Insured / Std / NI / NA**

Eng/No:

C/No: JHHUCW2F60K033745

Gen. Cond **Good / Fair / Poor / Burnt**

Steering: **Inorder / Jammed / Leaked / Burnt** or

Brake: **Inorder / Jammed / Leaked / Burnt** or

Modi : **Nil / S/Rim / STD A/Rim** or

Tyre Size: F: 215/75R17.5

R: " D/D

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or TRIANGLE

Front		Rear	
R/Bal.	7 mm	R/Bal.	7/7 mm
L/Bal.	7 mm	L/Bal.	7/7 mm
D.O.A.	11/08/21	D.O.I.	22/06/22

Survey held at Borneo

Des. of Damages: **Frt / Rear / O/S / N/S / U/C / Rooftop** or

The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : **Preli. Report**

1) ☐ : **Final Report**

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

___S + RS, ___SI

Photos

Others

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)