SS. REC. BY: TayM REF: C53/ ASM 22.	00 3361 Tvy3-1
ASS	IGNMENT
rom: Date:	Ven No: SLG 2259Y Yr Regn: 2016. 1
stimated Cost:	Type: M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
D / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
o Inspect Vehicle No:	Make: Joyota Hamer c.c. 1986
Workshop m/s	Colour Mayou A/C: Insured / Std / NI / NA
	Sp.Reading — T/Radio: Insured / Std / NI / NA
sured:	Eng/No:
PN	C/No: ZSM600070203*
laims No.	Gen. Cond: Good / Fair / Poor / Burnt
ım Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inordier / Jammed / Leaked / Burnt or
ake of Veh:	Modi: Nil / S/Fim / STD A/Rim or
No.	Tyre Size: F: 225/55R\8
Policy Condition)	R: v. v.
emark: The veh had commenced its N/S O/S	BS DUN / EXNOVA / GY /-FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	
al. or Market Value:	Front Rear
AC Accident Rport: Consistent? : Yes or No	R/Balmm R/Balmm
IA / PR Seen: Consistent? : Yes or No	L/Bal mm L/Bal cl. 10.2
st. Repairs: days Res.: Yes or No	D.O.A. D.O.I. 15/6/22
ım Sum: % 3 Val.: Yes or No	Survey held at Yeou Koun Mustor.
A / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OU	
ate: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
	-
	1
· · · · · · · · · · · · · · · · · · ·	
Date/Time, File Pass, 10? : Preli. Report	Days Of Repair:
i) Final Report	Resurvey No. of Trin: Survey Fee:

Date/Time, File Return to? Transportation: Add Fee: :Site Insp (\$ _S + RS.__ : Interview (\$ Photos Representate: :Tech. Invs (\$ Others Lump Sum / LBJ: 75 : Weekend (\$ TOTAL