

(08/11/13) wef
ASS. REC. BY: asm

REF:

CS/ASM 22005539/RK

8150

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLZ 7212E

at Workshop m/s J & E Automobile

of 9002, TRAMPING ST 93 #01-44

Insured: asm

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 96K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLZ 7212E Yr Regn: 2018 / AIR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA CAMRY 2.0 A c.c. 1998

Colour: GRAY A/C: Insured / Std / NI / NA

Sp. Reading: 53976 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRO53DKJ100112979

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16
R: 2.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 09/06/22 D.O.I. 13/06/22

Survey held at J & E Automobile

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt o/p

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 48K

confirm final fig: \$5800 and 6 days

(red, \$5506.07, 49%)

Date/Time, File Pass to?

1) 04/08/22

Date/Time, File Return to?

2) _____

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$) S + RS, SI

☐ : Interview (\$) Photos

☐ : Tech. Invs (\$) Others

☐ : Weekend (\$) _____

Report Format : tp

Lump Sum / I.B.I.: (\$ 5800)

J & E Automobile Services

Blk 9002, Tampines Street 93, #01-44, Tampines Industrial Park A S(528836)

Business Reg No: 53309545W

Tel: 6783 2909/ Fax:

E-Mail: chautomobile@yahoo.com.sg

To: Motor Claims Department

Date: 10/06/2022

Vehicle No: SLZ7212E

Model: Toyota Camry

Date of Accident: 09/06/2022 @ 12:00hrs / Location: Blk 34, Whampoa West Carpark

Damaged Area: Front Right Side Portion

Estimated Repair Cost For SLZ7212E (Toyota Camry)

QTY	Parts	Amount
1	Front bumper <i>sc</i>	\$ 1,108.20
1	Front bumper side retainer o/s ?	\$ 98.60
1	Front bumper bracket o/s ?	\$ 94.20
1	Front bumper sponge X	\$ 283.50
1	Front bumper reinforcement X	\$ 427.90
1	Front bumper centre air-grille ?	\$ 198.50
1	Front bumper chrome <i>cut</i>	\$ 228.20
1	Front bumper side garnish o/s <i>cut</i>	\$ 155.20
1	Front bumper fog lamp o/s X	\$ 266.90
1	Front bumper angle sensor o/s <i>sc</i>	\$ 385.50 <i>5/12 200</i>
1	Headlamp assy W/Chrome garnish o/s <i>cm</i>	\$ 2,221.70
1	Headlamp lower bracket o/s ?	\$ 112.20
1	Headlamp top support panel o/s <i>repair</i>	\$ 201.70
1	Radiator grille ?	\$ 599.10
1	Radiator grille logo ?	\$ 72.80
1	Radiator grille top centre garnish <i>de</i>	\$ 296.80
1	Bonnet assy <i>st</i>	\$ 1,347.20
1	Bonnet chrome ?	\$ 170.40
1	Support panel X	\$ 613.40
1	Front fender o/s <i>bm</i>	\$ 961.40
1	Front fender emblem o/s <i>re</i>	\$ 68.50
1	Front fender inner shield o/s ?	\$ 196.20
1	Front door o/s X	
		Repair
Parts Sum:		\$ 10,108.10
Parts Less 25% :		\$ 2,527.02
Parts Total:		\$ 7,581.07

Special Nett Items

1	Front bumper clips <i>re</i>	\$ 50.00 30
1	Radiator grille clips <i>re</i>	\$ 30.00 20
1	Radiator grille top garnish clips	\$ 20.00
1	Front fender inner shield clips	\$ 50.00 30
1	Front number plate w/garnish	\$ 55.00 X
Special Nett Items Total:		\$ 225.00

Labour & Misc Charges

Description	Amount
To Remove, Replace, Re-align & Install affected Damaged Areas (\$300.00 per day)	\$ 1,200.00 <i>700</i>
To Putty, Prep & Re-spray on affected Damaged Areas (\$300.00 per panel)	\$ 1,500.00 <i>700</i>
(Frt Door, Ctr Door Pillar, Front Fender, Front Bumper, Bonnet, Support Panel)	
To Remove, Install, Condenser amd Charge up AC Gas	\$ 120.00 X

To Remove & Install Radiator Assy, Conduct Pressure Test to Check For Leakage.
To Remove & Re-connect all electrical wirings to Facilitate Repairs
To Re-set Engine Management Fault-Code & Re-Programme (Calibration Angle Sensor, Focus Headlamp)
To Apply Undercoating on the Affected Damaged Areas

\$	120.00	X
\$	60.00	30
\$	250.00	100
\$	250.00	80

Labour Charges Total: \$ 3,500.00

Parts Total:	\$ 7,581.07
Special Nett Items Total:	\$ 225.00
Labour Charges Total:	\$ 3,500.00
Total Cost Of Repair:	\$ 11,306.07

(Non-Inclusive of GST)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul

Hp 90010068

6 days

L/S

13/06/22 @ 1545

Resurvey after repair

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any delay reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	10/06/2022 10:45 (SGT)
Date of Accident	09/06/2022 12:00 (SGT)
Exact Location of Accident	Whampoa, Singapore
Additional Location Information	BLK 34 WHAMPOA WEST CARPARK
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLZ7212E
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	GRACE MARIE GAN AH SIM
NRIC No	S0032815D
Email Address	GRACETUONGMIN@ICLOUD.COM
Mobile Phone No	(Phone) +65-96160676
Alternative Phone No	+65-96160676

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Camry
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1998

INSURANCE COMPANY

Name of Insurance Company	MSIG Insurance (Singapore) Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	B300550612QMY
Cover Note Number	-

DRIVER

Name of Driver	GRACE MARIE GAN AH SIM
NRIC No	S0032815D

Date Of Birth	26/07/1952
Occupation	Indoor
Date Of Driving Pass	05/12/1974
Driving experience	47 YEARS AND 6 MONTHS
Gender	Female
Mobile Number	(Phone) +65-96160676
Alt. Phone Number	+65-96160676
Email Address	GRACETUONGMIN@ICLOUD.COM
Address	105 JALAN RAJAH
Address complement	06-76
Postcode	320105
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collided into Parked Vehicle
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	LING TUONG MIN
Gender	Male

PASSENGER 2

Name	SERENE
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

AS PER SKETCH PLAN ATTACHED

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN5886H
Vehicle Manufacturer	-

Vehicle Registration Number YN5886H
 Vehicle Manufacturer -

 Accident report **SF0G226A0001**

Page 2 of 8

Vehicle Model -
 Vehicle Variant -
 Vehicle Colour -
 Vehicle Category Commercial vehicle
 Name of Driver CHOKKALINGAM PANDIYAN
 Work Permit No G650292Q
 Contact Number (Phone) +65-85397301
 Address -
 Address complement -
 Postcode -
 Insurance Company Name -
 Nature Of Damage -
 Details of property damaged in accident -
 No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

1. The **CRP** report **correctly** the details of the accident to speed up the claims process.
2. The **CRP** form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The **True and acceptance** of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **An ☒ Yes reporting may be referred to the Police for investigation**.
6. This report will be forwarded by the insurers of the **GIA Records Management Centre** established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the **submission** of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, in knowledge, agree and consent that:
(a) My **Plaintiff**, my workshop and the General Insurance Association of Singapore (**GIA**) may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or provided by my insurer (collectively the **Personal Information**) and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the **Insurers**), the Insurers' law partner firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/postal packages), and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the **Purposes**);
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law partner firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law partner firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan




A) SLZ 7212 E
B) YN 5886 H

Describe Circumstances of the Accident

At 12:00 noon I parked my vehicle in the carpark
lot and off the car engine.
Before I could get out of the car, I
heard a loud noise coming from the right side
of my car. The front of my right side had
been cut from the carpark lot.
When the heavy door closed and turned
to the left side to drive out of the carpark
lot, it hit my parked vehicle.

Declaration

I/We declare the foregoing particulars are true in every respect


Policyholder's Signature / Date &
Time


Driver's Signature (If driver is not the policyholder) / Date
& Time


Witnessed by Reporting Centre
Personnel



Toyota Camry 2.0A

Overview

Financial

Accessories

Similar

Research

Photos

Map



PRIME MOTOR & LEASING



(CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES)

• PRIME CAR RENTAL & TAXI SERVICES PTE LTD • SECTION CREDIT & MOTOR LEASING PTE LTD • BEST PETROL AND DIESEL SUPPLY PTE LTD • BEST ELECTRICITY SUPPLY PTE LTD

Price	\$101,000		
Depreciation	\$13,720 /yr View models with similar depre	Reg Date	15-Aug-2018 (6yrs 2mths COE left)
Mileage	N.A.	Manufactured	2018
Road Tax	\$1,210 /yr	Transmission	Auto
Dereg Value	\$44,576 as of today (change)	OMV	\$29,032
COE	\$32,551	ARF	\$32,645
Engine Cap	1,998 cc	Power	123.0 kW (164 bhp)
Curb Weight	1,480 kg	No. of Owners	1

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	815D
Vehicle No.:	SLZ7212E
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Jun 2022
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.0 AUTO
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	6ARP387391
Chassis No.:	MR053DK5100112979
Maximum Power Output:	123.0kW (164 bhp)
Open Market Value:	\$29,587.00
Original Registration Date:	30 Apr 2018
First Registration Date:	30 Apr 2018
Transfer Count: -	0
Actual ARF Paid:	\$33,422.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Apr 2028
PARF Rebate Amount:	\$25,066.00
COE Expiry Date:	29 Apr 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$39,001.00
COE Rebate Amount:	\$22,913.00
Total Rebate Amount:	\$47,979.00

The information contained herein is correct as at 14 Jun 2022

OK