





## Case Details

Case Reference Number : TAX/06/22/2011  
 Type of Repair : Accident Repair  
 Vehicle Registration Number : SHB1270A

Company Type : Strides Taxi Pte Ltd  
 Estimation ID : EST-18482-ID  
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd  
 Accident Date and Time : 05/06/2022 03:15 AM  
 Vehicle Age(In Months) : -

## Documents / Photographs

View Documents / Photographs

Total Documents: 0

## Estimation Details

### Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Approval			Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)		Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			FASCIA-RR BPR	1	758.48	758.48	10.00	682.63	Replace	0	0.00	Not Give	Xm
One Time Key In	Main			BRACKET-RR BPR FASCIA SI MTG - RH	1	46.08	46.08	10.00	41.47	Replace	0	0.00	Not Give	Xm
One Time Key In	Main			PANEL-BODY SI OTR RR FENDER - RH	1	977.08	977.08	10.00	879.37	Replace	1	0.00	Repair	R
One Time Key In	Main			STICKER ELECTRIC ( LOGO )	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	nm
One Time Key In	Main			LINER ASM-RR W/H PNL -RH	1	85.48	85.48	10.00	76.93	Replace	0	0.00	Not Give	Xm
One Time Key In	Main			WINDOW ASM-QTR - RH	1	251.48	251.48	10.00	226.33	Replace	0	0.00	Not Give	Xm
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	0	0.00	Not Give	Xm
One Time Key In	Main			DOOR ASM-RR SI -RH	1	2,185.04	2,185.04	10.00	1,966.54	Replace	1	0.00	Repair	R
One Time Key In	Main			CHECK ASM-RR S/D -RH	1	21.00	21.00	10.00	18.90	Replace	0	0.00	Not Give	Xm

Total Spare Part Cost 4,510.97

Surveyor Total 21.60

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0.00

Final Spare Part Cost 4,510.97

Final Sur Total 21.60

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			HINGE ASM-RR S/D UPR-RH	1	46.90	46.90	10.00	42.21	Replace	0	0.00	Not Give	Xm
One Time Key In	Main			HINGE ASM-RR S/D LWR-RH	1	47.22	47.22	10.00	42.50	Replace	0	0.00	Not Give	Xm
One Time Key In	Main			HANDLE ASM-FRT S/D O/S - RH	1	36.92	36.92	10.00	33.23	Replace	1	0.00	Repair	R
One Time Key In	Main			COVER-RR S/D LK CYL-RH	1	14.88	14.88	10.00	13.39	Replace	0	0.00	Not Give	Xm
One Time Key In	Main			STRIKER-FRT S/D LK	1	16.74	16.74	10.00	15.07	Replace	0	0.00	Not Give	Xm
One Time Key In	Main			REGULATOR ASM-RR S/D WDO-RH	1	265.30	265.30	10.00	238.77	Replace	0	0.00	Not Give	Xm
One Time Key In	Main			LATCH ASM-RR S/D -RH	1	139.98	139.98	10.00	125.98	Replace	0	0.00	Not Give	Xm
One Time Key In	Main			MOLDING ASM-RR S/D WDO UPR RVL-RH	1	54.50	54.50	10.00	49.05	Replace	0	0.00	Not Give	Xm
<b>Total Spare Part Cost</b>									<b>4,510.97</b>	<b>Surveyor Total</b>		<b>21.60</b>		
<b>Lump Sum Discount (%)</b>									<b>0.00</b>	<b>Lump Sum Dis (%)</b>		<b>0.00</b>		
<b>Final Spare Part Cost</b>									<b>4,510.97</b>	<b>Final Sur Total</b>		<b>21.60</b>		

**Labour's Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION RH	3,600.00	200.00	
<b>Total:</b>			<b>3,600.00</b>	<b>200.00</b>	

**Spray Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY RH REAR DOOR	428.00	220.00	
2	Main	TO RESPRAY REAR FENDER RH	428.00	220.00	
3	Main	TO RESPRAY REAR BUMPER	428.00	0.00	Xm
<b>Total:</b>			<b>1,284.00</b>	<b>440.00</b>	

**Other Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00	Xm
2	Main	TO TRANSFER DOOR MECHANISM	120.00	0.00	Xm
3	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	150.00	
4	Main	ISOLATED OF (EV) (NET)	150.00	150.00	
5	Main	TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0.00	Xm
6	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00	Xm
<b>Total:</b>			<b>965.00</b>	<b>300.00</b>	

**Summary**

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	4,510.97	21.60
Total Labour Cost	3,600.00	200.00
Total Spray Painting	1,284.00	440.00
Other	965.00	300.00
<b>Overall Total</b>	<b>10,359.97</b>	<b>961.60</b>
Lump Sum Repair Option	<input type="checkbox"/>	<input type="checkbox"/>
Lump Sum Total	0.00	961.60
Surveyor Approved Amount		961.60
No of Repair Days*	6	3

Remarks

Surveyor Name

Signature

Survey Date

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

RESURVEY AFTER REPAIR

Rasul



Save Clear

08/06/2022

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 08/06/2022 14:40 (SGT)  
Date of Accident ..... 05/06/2022 11:15 (SGT)  
Exact Location of Accident ..... Near 128 Bukit Merah View, Block 128, Singapore 150128  
Additional Location Information ..... LOWER DELTA ROAD  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SHB1270A

### INSURED/POLICYHOLDER

Is company? ..... Yes  
Name Of Registered Owner ..... STRIDES TAXI PTE LTD  
Company Reg No ..... 1XXXXX369K  
Email Address ..... Auto-Svcs-TARC@smrt.com.sg  
Mobile Phone No ..... (Phone) +65-68662671  
Alternative Phone No ..... (Office) +65-68662672

### VEHICLE PARTICULARS

Manufacturer ..... MG  
Model ..... MG5  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... -  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Taxi  
Transmission ..... Auto  
CC ..... 0

### INSURANCE COMPANY

Name of Insurance Company ..... MS First Capital Insurance Ltd  
Type of Coverage ..... ThirdParty  
Fleet Policy ..... Yes  
Policy Number ..... D-22099115MFSH  
Cover Note Number ..... -

### DRIVER

Name of Driver ..... JAHFRI BIN ABDULLAH  
NRIC No ..... SXXXX382D



**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	SMR2791M
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-



SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes



Policyholder's Signature / Date & Time

*[Handwritten Signature]*

6/6/22 0837

Driver's Signature (if driver is not the policyholder) / Date & Time

*[Handwritten Signature]* Jun 6, 2022

Witnessed by Reporting Centre Personnel

Sketch Plan





**SINGAPORE  
POLICE FORCE**



T/20220606/7002

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3

Report No. T/20220606/7002

**CONTINUATION OF REPORT**

<b>Driver</b>			
Name	JAHFRI BIN ABDULLAH	ID No.	S8330382D
Related Vehicle	SHB1270A (Car)	Contact No.	82189111
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL	Date	NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL

Brief Details.

I was driving with my 2 passengers at the back seat in the middle lane, when suddenly this car(was in my blind spot) drifting to the left and hit on the passenger side. And he kept honking as if it was my fault. So i put on my hazard light and tried to stop at the side road, but the car SMR2791M just change lane to right and move off. Luckily my passenger manage to take a picture of the car and whatsapp me later on when i arrive at their destination.



**SINGAPORE  
POLICE FORCE**



T/20220606/7002

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

3 of 3

Report No. T/20220606/7002

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report: Not applicable
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / TPIB / SUFYAN BIN KHAIRI Contact No.: 65476148

Signature Of informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Date/Time: 06/06/2022 08:48
Classification Of Case:

NP188

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	762E
Vehicle No.:	SKV3326U
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Jun 2022
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS GS450H AUTO SUPER LUX
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	2GR8663570
Chassis No.:	JTHBC96SX05018598
Maximum Power Output:	218.0 kW (292 bhp)
Open Market Value:	\$67,520.00
Original Registration Date:	05 Mar 2009
First Registration Date:	05 Mar 2009
Transfer Count:	2
Actual ARF Paid:	\$40,512.00

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

COE Expiry Date:	04 Mar 2024
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$16,509.00
COE Rebate Amount:	\$5,728.00
Total Rebate Amount:	\$5,728.00

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 09 Jun 2022

OK