



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                         |  |                                   |                           |            |
|---|--|-----------------------------------|---------------------------|------------|
| STRIDES AUTOMOTIVE SERVICES PTE LTD<br>60 WOODLANDS INDUSTRIAL PARK<br>E4SINGAPORE 757705 |  |                                   | Ref: CS/SMR22005702/Rncm4 |            |
|   |  |                                   | Date: 05/07/2022          |            |
|   |  |                                   | Code: SMR                 |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>   |  |                                   |                           |            |
|   | Insured Veh.   | SG 5701R                          | Veh. Inspected            | SMB 1562Z  |
|   | Policy No.   |                                   | Coverage (\$)             | 0.00       |
|   | Claim No.  | BUS/06/22/5012                    | Excess (\$)               | 0.00       |
|   | Assign From  | HUA YEN                           | Assign Date               | 15/06/2022 |
| <b>2. Vehicle Particulars &amp; Condition</b>   |  |                                   |                           |            |
|   | Make & Model   | MAN NL 320F (A22)                 | c.c                       | 10518      |
|   | Engine No.   | HIDDEN                            | Year of Reg.              | 2014       |
|   | Chassis No.  | WMAA22ZZ7F7002522                 | Colour                    | MULTI      |
|   | Odometer   | 612797 KM                         | Steering                  | IN ORDER   |
|   | Brakes   | IN ORDER                          | Modification              | NIL        |
|   | General  | FAIR                              |                           |            |
| <b>3. Conditions of Tyres</b>   |  |                                   |                           |            |
|   |  | Size                              | Make                      | Balance    |
|   | R/H Front Tyre   | 275/70 R22.5                      | MICHELIN                  | 8 mm       |
|   | L/H Front Tyre   | 275/70 R22.5                      | MICHELIN                  | 8 mm       |
|   | R/H Rear Tyre  | 275/70 R22.5 (D/D)                | MICHELIN                  | 8/8 mm     |
|   | L/H Rear Tyre  | 275/70 R22.5 (D/D)                | MICHELIN                  | 8/8 mm     |
| <b>4. Description of Damages</b>  |  |                                   |                           |            |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.<br>DAMAGES SEE DETAILS.   |                                   |                           |            |
| <b>5. General Information</b>   |  |                                   |                           |            |
|   | Accident Date  | 13/06/2022                        | Inspection Date           | 15/06/2022 |
|   | Survey held at   | 310 MANDAI RD SINGAPORE 779404    |                           |            |
|   | Repairer   | TOWER TRANSIT SINGAPORE PTE. LTD. |                           |            |
| <b>5a. Remarks</b>  |  |                                   |                           |            |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                   |                           |            |
| <b>5b. Estimate Days of Repair</b>  |  |                                   |                           |            |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR:  |                                   | 5 Working Days            |            |