

$\{E\}$

ASSIGNMENT

Veh No: G1BL934T Yr Regn: 2021, March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace C.C 2982

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading 136886 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: J1FH1021500251494

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ~~In order~~ / Jammed / Leaked / Burnt or

Brake: ~~inorder~~ / Jammed / Leaked / Burnt or

Modi: (Nil) / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15 C
R: 195 R15 C

	
N/S	O/S

Front Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 16/06/22

Survey held at Automobile Hq.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Allianz.
	MV :
	PV :
	Nett:
	811H.

☐: Preli. Report

□: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$

☐	Site Insp	(\$
☐	Interview	(\$
☐	Tech. Invs	(\$
☐	Waste	(\$

Survey Fee:

Transportation:

3-ES, SI

Photos

 $\lambda \in \mathbb{C}$