

09/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT1 22005758/UCY3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMD3134C

at Workshop m/s CRL Wh,

of

Insured: XD9822L

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 668k.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 1.3.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted: LTA 831101

Veh No: SMD3134C Yr Regn: 27/08/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: KIA Cerato EX c.c 1591

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 51405 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KNATF3416MK5012595

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or roodstone

Front Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 15/06/22 D.O.I. 4/07/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/5 Body
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 13/7/22 PIP 811009 : Informed Rep. (Red. 5209, 22?)

Date/Time, File Pass to?

☐ : Preli. Report

☒ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format : TP

Lump Sum / I.B.I. (\$) 11,009

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	863J
Vehicle Details	
Vehicle No.:	SMD3134C
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Jul 2022
Vehicle Make:	KIA
Vehicle Model:	CERATO 1.6(A) EX
Primary Colour:	Grey
Manufacturing Year:	2018
Engine No.:	G4FGJH702740
Chassis No.:	KNAF3416MK5012595
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$13,788.00
Original Registration Date:	27 Aug 2018
First Registration Date:	27 Aug 2018
Transfer Count:	0
Actual ARF Paid:	\$13,788.00 6894
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Aug 2028
PARF Rebate Amount:	\$10,341.00
Intended COE Rebate Details	
COE Expiry Date:	26 Aug 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$33,798.00
COE Rebate Amount:	\$20,760.00
Total Rebate Amount:	\$31,101.00

The information contained herein is correct as at 04 Jul 2022

OK



New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



Post an Advertisement
Sell it yourself! Advertise it at just
\$68 until it's SOLD!

Post an Ad


Advertiser Login

Ways of Selling

02/2009 Toyota Axio \$53800, \$608 Monthly At 2.99%.



\$608 Monthly Only! 2.99% By
GV Cars Financing, \$0
Downpayment, PHV/Z10
Welcome,
GV Automobile Centre StarAd



« Back (1 2) Next »

Sort by 20 results/page

34 vehicles



Kia Cerato

Any Category

Advanced Search



Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

Search Selection

Kia Cerato

Any

Any

2018

Any

Any

Any

Available

**Kia Cerato 1.6A LX****\$75,888**

\$11,120 /yr

29-Oct-2018

1,591 cc

37,337 km

Sedan

Available

New model Kia Cerato k3, low mileage, 1 owner, 100% loan available, call us now!

Posted: 04-Jul-2022

**Kia Cerato K3 1.6A****\$68,900**

\$10,700 /yr

28-May-2018

1,591 cc

43,000 km

Sedan

Available

New Arrived Stock Unit! For Your Desire Selection, Affordable Parf Family Car With Wallet-friendly Depreciation! This Unit Is Presented In...

Car World Automobile Pte Ltd

Posted: 04-Jul-2022

PREMIUM AD

**Kia Cerato K3 1.6A****\$66,800**

\$11,060 /yr

08-Jan-2018

1,591 cc

59,524 km

Sedan

Available

1 owner only! Low mileage done! Engine fully maintained by C&C! 100% in house loan scheme available here with hassle free procedure...

Benefit Auto Enterprise Pte Ltd

Posted: 04-Jul-2022

**Kia Cerato K3 1.6A****\$67,500**

\$10,690 /yr

16-Apr-2018

1,591 cc

69,900 km

Sedan

Available

Eye-catching design for all angle, innovative and stylish compact sedan for daily drive! Nice looking metallic dark blue in colour, with wall...

Car World Automobile Pte Ltd

Posted: 03-Jul-2022

PREMIUM AD

**Kia Cerato K3 1.6A****\$71,800**

\$10,840 /yr

31-Jul-2018

1,591 cc

27,733 km

Sedan

Available

Agent serviced. Very well taken care, super low mileage done. All stock condition. Spacious, smooth and super efficient fuel consumption...

Ka-Hup Vehicles Trading

Posted: 03-Jul-2022

PREMIUM AD

**Kia Cerato 1.6A EX (OPC)****\$70,800**

\$10,060 /yr

07-Nov-2018

1,591 cc

17,870 km

Sedan

Available

Non OPC Asking Price S\$81,800. Popular Family's Sedan EX Model. 100% No Accident. Well Maintained As Like New Car + Regular Serviced....

Ka-Hup Vehicles Trading

Posted: 03-Jul-2022

PREMIUM AD

**Kia Cerato K3 1.6A****\$74,800**

\$11,600 /yr

13-Jun-2018

1,591 cc

80,000 km

Sedan

Available

100% loan approval! 1.88% offer! Responsive engine performance with fuel efficiency mode. 1 careful owner. Pristine condition. Financi...

✓ This car comes with 6-mth Sgcarmart Warranty - the best protection for your car. Learn More

Car House Pte Ltd

Posted: 03-Jul-2022

**Kia Cerato K3 1.6A SX Sunroof****\$72,800**

\$11,700 /yr

26-Jan-2018

1,591 cc

89,984 km

Sedan

Available

Simply A Beauty Not To Be Missed, K3 1.6A (Highest Specs SX Model With Sunroof), Equipped With Loads Of High Tech Features! Fully...

Lake View Credit Pte Ltd

Posted: 02-Jul-2022

PREMIUM AD

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	16/06/2022 09:49 (SGT)
Date of Accident	15/06/2022 16:55 (SGT)
Exact Location of Accident	Punggol Way, Singapore
Additional Location Information	Near Bus Stop B03
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMD3134C
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	KOH WEE YON
NRIC No	SXXXX863J
Email Address	kohweeyon@gmail.com
Mobile Phone No	(Phone) +65-91549451
Alternative Phone No	(Home) +65-91549451

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Cerato
Variant	EX
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1591

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1800097821-02
Cover Note Number	-

DRIVER

Name of Driver	KOH WEE YON
NRIC No	SXXXX863J

Date Of Birth	13/05/1990
Occupation	Indoor
Date Of Driving Pass	25/06/2010
Driving experience	12 YEARS
Gender	Male
Mobile Number	(Phone) +65-91549451
Alt. Phone Number	(Home) +65-91549451
Email Address	kohweeyon@gmail.com
Address	Blk 228A Punggol Field #14-110 Singapore
Address complement	-
Postcode	821228
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Change/cross lane
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	CHEN JIAMIN
Gender	Female

PASSENGER 2

Name	JOIE KOH YU TING
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO THE ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD9829L
Vehicle Manufacturer	Scania

Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	QI YUNFEI
Passport No/FIN	GXXXX992W
Contact Number	(Phone) +65-98693024
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :


(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.


(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

 16/06/2022
9.11 am
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan



While I am driving along Punggol way, a truck with car plate number XD 9829 L tried to keep left onto my lane without checking his blind spot and he hit my car on the right just before Punggol way ~~road~~ bus stop BGS. The incident happened around 4.30pm to 5pm on 15/06/2022

We declare the foregoing particulars are true in every respect.

Witnessed by Reporting Centre
Personnel



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



Movement that inspires

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name /Mr Koh Wee Yon Reg No/Reg Date SMD3134C*KC17P / 27/08/2018 Date In/Mileage 02/07/2022/ 51405 Chassis No KNAF3416MK5012595 Engine No G4FGJH702740 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim ABT / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
F0000018	Credit	08/07/2022/ 09:40	DS	303 / Renemer	30888			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount	
S	MIPNT88088	DIAGNOSTIC/SCANNING						250.00
S	MIPNT88088	TO CHECK ALL LIGHTING/WIRING SYSTEM ON RHS ACCIDENT AFFECTED AREAS						80.00
S	MIPNT88088	TO TRANSFER RHF & RHR DOOR COMPONENTS & MECHANISM PARTS						640.00
S	MIPNT88088	TO APPLY SEALANT KIT ON NEW & REPAIR PANELS						100.00
S	MIPNT88088	TO REPLACE RHF FENDER,RH SIDE MIRROR,RHF & RHR DOOR, BLACK TAPE,DOOR MLDG,BUMPER CLIPS, -TO REPAIR RHR FENDER STRAIGHTEN,REFORM,ALIGN ON RHS ACCIDENT-AFFECTED AREAS						1600.00
S	MIPNT98088	SPRAY PAINTING ON RHS ACCIDENT AFFECTED AREAS (RH SIDE MIRROR,RHF FENDER,RHF & RHR DOOR,RHR FENDER,RR BUMPER)						2750.00
S	MIPNT88088	WHEEL BALANCING						50.00
S	MIPNT88088	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT						180.00
X	KS 66321 M6 000	RH PANEL-FENDER	1.00	593.00	0.00	593.00		
X	KS 76523 M6 000	RH BLACK TAPE-FR DR	1.00	13.00	0.00	13.00		
X	KS 76004 M6 000	RH PANEL ASSY-FR DOO	1.00	1377.00	0.00	1377.00		
X	KS 83860 M6 000	RH MLDG ASSY-RR DR F	1.00	44.00	0.00	44.00		
M	KS 77521 M6 000	RH BLACK TAPE-RR DR	1.00	13.00	0.00	13.00		
X	KS 77523 M6 000	RH BLACK TAPE-RR DR	1.00	8.00	0.00	8.00		
X	KS 77004 M6 000	RH PANEL ASSY-RR DOO	1.00	1445.00	0.00	1445.00		
X	KS 87620 M6 240	RH MIRROR ASSY-OUTSI	1.00	559.00	0.00	559.00		
X	KS 0G032 50 037A	FASTERNER- BUMPER	10.00	2.00	0.00	20.00		
X	WYHIS8004	K3 NEW RIM	1.00	1250.00	0.00	1250.00		
X	KS 82860 M6 000	RH MOULDING ASSY-FRT	1.00	37.00	0.00	37.00		
Z	NOTES							
ACCIDENT ON 15/06/2022 ALONG PUNGGOL WAY NEAR BUS STOP B03								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



Movement that inspires

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name	/Mr Koh Wee Yon
	Reg No/Reg Date	SMD3134C*KC1/ 27/08/2018
	Date In/Mileage	02/07/2022/ 51405
	Chassis No	KNAF3416MK5012595
	Engine No	G4FGJH702740
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	ABT / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000018	Credit	08/07/2022/ 09:40	DS	303 / Renemer	30888

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
OWNER CLAIMING THIRD PARTY LOSS OF RENTAL (R.A 22887) TP#: XD9829L TP INS: CHINA TAIPING Z NOTES FINALIZATON (NO. OF TOTAL REPAIR DAYS - 6 DAYS) ATTENTION TO: MR. MARCUS CHUA				
Estimate				

Confirm & accepted by

Authorized signatory and company stamp

Parts	5,359.00
Labour	0.00
Standard Menu	0.00
Specialist Job	5,650.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	11,009.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

CYCLE & CARRIAGE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



Movement that inspires

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info														
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	<table> <tr> <td>Cust No/Name</td><td>/Mr Koh Wee Yon</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMD3134C*KC17P / 27/08/2018</td></tr> <tr> <td>Date In/Mileage</td><td>16/06/2022/ 51362</td></tr> <tr> <td>Chassis No</td><td>KNAF3416MK5012595</td></tr> <tr> <td>Engine No</td><td>G4FGJH702740</td></tr> <tr> <td>Make/Model</td><td>KIA/CERATO 1.6 A EX G333</td></tr> <tr> <td>Colour/Trim</td><td>ABT / WK</td></tr> </table>	Cust No/Name	/Mr Koh Wee Yon	Reg No/Reg Date	SMD3134C*KC17P / 27/08/2018	Date In/Mileage	16/06/2022/ 51362	Chassis No	KNAF3416MK5012595	Engine No	G4FGJH702740	Make/Model	KIA/CERATO 1.6 A EX G333	Colour/Trim	ABT / WK
Cust No/Name	/Mr Koh Wee Yon														
Reg No/Reg Date	SMD3134C*KC17P / 27/08/2018														
Date In/Mileage	16/06/2022/ 51362														
Chassis No	KNAF3416MK5012595														
Engine No	G4FGJH702740														
Make/Model	KIA/CERATO 1.6 A EX G333														
Colour/Trim	ABT / WK														


Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000018	Credit	16/06/2022/ 11:05	DS	303 / Renemer	30888
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
S MIPNT88088	DIAGNOSTIC/SCANNING				250.00
S MIPNT88088	TO CHECK ALL LIGHTING/WIRING SYSTEM ON RHS ACCIDENT AFFECTED AREAS		80		100.00
S MIPNT88088	TO TRANSFER RHF & RHR DOOR COMPONENTS & MECHANISM PARTS		640		1280.00
S MIPNT88088	TO APPLY SEALANT KIT ON NEW & REPAIR PANELS		100		300.00
S MIPNT88088	TO REPLACE RHF FENDER, FENDER INSULATOR, RH SIDE MIRROR, RHF & RHD DOOR, DOOR HINGE, BLACK TAPE, DOOR MLDG, DOOR W/STRIP, UPR REAR BUMPER, CLIPS, ETC -TO REPAIR RHR FENDER STRAIGHTEN, REFORM, ALIGN ON RHS ACCIDENT AFFECTED AREAS		1600		3840.00
S MIPNT98088	SPRAY PAINTING ON RHS ACCIDENT AFFECTED AREAS (HOOD, RH SIDE MIRROR, RHF FENDER, RHF & RHR DOOR, RHR FENDER, RR BUMPER)		2750		3850.00
S MIPNT88088	WHEEL BALANCING (RHR TYRE & RIM)				50.00
S MIPNT88088	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT				180.00
S MIPNT88088	205/60 R16 TYRE ROAD STONE				128.00
S MIPNT88088	CERATO 16' RIM				1250.00
M KS 66321 M6 000	RH PANEL-FENDER	1.00	593.00	0.00	593.00
M KS 84126 M6 000	RH INSULATOR-FENDER	1.00	27.00	0.00	27.00
M KS 82860 M6 000	RH MLDG ASSY-FR DR F	1.00	37.00	0.00	37.00
M KS 82220 M6 000	RH W/STRIP ASSY-FR D	1.00	64.00	0.00	64.00
M KS 76523 M6 000	RH BLACK TAPE-FR DR	1.00	13.00	0.00	13.00
M KS 76004 M6 000	RH PANEL ASSY-FR DDO	1.00	1377.00	0.00	1377.00
M KS 79320 2V 000	RH UPR HINGE ASSY-FR	1.00	30.00	0.00	30.00
M KS 79325 1Y 300	RH LWR HINGE ASSY-FR	1.00	27.00	0.00	27.00
M KS 83860 M6 000	RH MLDG ASSY-RR DR F	1.00	44.00	0.00	44.00

Confirm & accepted by

not Arthur
Lee norany
Wheeler before party
4/7/22 6 days

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

CYCLE & CARRIAGE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



Movement that inspires

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info														
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	<table> <tr> <td>Cust No/Name</td><td>/Mr Koh Wee Yon</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMD3134C*KC1/ 27/08/2018</td></tr> <tr> <td>Date In/Mileage</td><td>16/06/2022/ 51362</td></tr> <tr> <td>Chassis No</td><td>KNAF3416MK5012595</td></tr> <tr> <td>Engine No</td><td>G4FGJH702740</td></tr> <tr> <td>Make/Model</td><td>KIA/CERATO 1.6 A EX G333</td></tr> <tr> <td>Colour/Trim</td><td>ABT / WK</td></tr> </table>	Cust No/Name	/Mr Koh Wee Yon	Reg No/Reg Date	SMD3134C*KC1/ 27/08/2018	Date In/Mileage	16/06/2022/ 51362	Chassis No	KNAF3416MK5012595	Engine No	G4FGJH702740	Make/Model	KIA/CERATO 1.6 A EX G333	Colour/Trim	ABT / WK
Cust No/Name	/Mr Koh Wee Yon														
Reg No/Reg Date	SMD3134C*KC1/ 27/08/2018														
Date In/Mileage	16/06/2022/ 51362														
Chassis No	KNAF3416MK5012595														
Engine No	G4FGJH702740														
Make/Model	KIA/CERATO 1.6 A EX G333														
Colour/Trim	ABT / WK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000018	Credit	16/06/2022/ 11:05	DS	303 / Renemer	30888

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M KS 83220 M6 000 RH W/STRIP ASSY-RR D	1.00	60.00	0.00	60.00
M KS 77521 M6 000 RH BLACK TAPE-RR DR	1.00	13.00	0.00	13.00
M KS 77523 M6 000 RH BLACK TAPE-RR DR	1.00	8.00	0.00	8.00
M KS 77004 M6 000 RH PANEL ASSY-RR DDO	1.00	1445.00	0.00	1445.00
M KS 79420 D8 000 RH UPR HINGE ASSY-RR	1.00	33.00	0.00	33.00
M KS 79320 2E 000 RH LWR HINGE ASSY-FR	1.00	26.00	0.00	26.00
M KS 87620 M6 240 RH MIRROR ASSY-OUTSI	1.00	559.00	0.00	559.00
M KS 84167 M6 000 RH FILM-ANTI CHIPP	1.00	27.00	0.00	27.00
M KS 86611 M6 000 UPR COVER-RR BUMPER	1.00	651.00	0.00	651.00
M KS 0G032 50 037A FASTENER- BUMPER	10.00	2.00	0.00	20.00
M KS 86652 M6 000 RH UPR SIDE BRACKET	1.00	31.00	0.00	31.00
M KS 86651 M6 000 LH UPR SIDE BRACKET	1.00	25.00	0.00	25.00

Z NOTES

ACCIDENT ON 15/06/2022 ALONG PUNGGOL WAY NEAR BUS STOP B03
 OWNER CLAIMING THIRD PARTY
 REQUIRED REPLACEMENT VEHICLE
 TP#: XD9829L TP INS: CHINA TAIPING

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after survey printing
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Confirm & accepted by

Parts	5,110.00
Labour	0.00
Standard Menu	0.00
Specialist Job	11,228.00
Others (Lub, etc)	0.00
Sundry	0.00
Total (w/o GST)	16,338.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.