

CS/AIS22005768/Aqy3

ASSIGNMENT

Veh No: SMU 9067 Yr Regn: 2316 / OCT.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 318i C.C 1499.

Colour: Red. A/C: Insured / Std / NI / NA

Sp. Reading 57581 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WB A8E36030N U 32174

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55 R17

R: 725/50R47. BS

TOYO / YOKO or

Front

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 17/08/22

Survey held at Auto Mega Mall
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Alliaz
	LS \$3800, 4 days. (Red \$3556.80, 48%)
	MV :
	PV :
	Nett :
	00211.

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: : Site Insp (\$

1: Interview (\$

Photos

Tech. Invs (3)

Others