Surveyor:

REF: CS3/ASM22003909/ Evy3 -1

Special Instruction: LS $13000F

ASSIGNMENT (Office)

From (Person): Winnie Ho of AXA Date/Time: 14/6/2022

Estimated Cost: Bill to:

Third Parties:

Claimant: Owner

Surveyor: Precise Auto.

Workshop: JCM

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SLN 5560B Insured: SDX 55T

at Workshop m/s JCM Rental Tel:

of 1 Bukit Batok Crescent #02-03.

Policy No: Claim No: S2M037H2.

Sum Insured: Excess:

Make of Veh: D.O.A. 25/4/2022

(Client's Record)

15/6/2022 1pm - 1.30pm

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig , days (Red $ / %; Original days)

Date/Time: Submit Final Fig , days (Red $ / %; Original days)

Date/Time	Action/Instruction
	SLN 5560B-X
	SDX 55T-X

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : *NC*)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/ Evaluated by:

Fee Charged:	*Date:*
Basic & Add	
Transport	
Photos	
Others	
Total	

1) Date/Time File Pass to 2) Date/Time File Return to

3) Date/Time File Pass to 4) Date/Time File Return to

5) Date/Time File Pass to 6) Date/Time File Return to