



Service Request Details

Claim

S2M03ZH2

Reference

CS3/ASM22003909/Evy3-1 

Loss Date

25 April 2022

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

26 Apr 2022 3:55:12 PM

Request Date

14 June 2022

Due Date

17 June 2023

Services

Re-inspection

Actions

Next Step

Finish the work

Complete Work

Vehicle Information

Incident Vehicle Registration #
SLN5560B

Make
TPVD SUZUKI

Model
SX4

Service Address

, , ,

Primary Contact/Insured

MIC PLASTICS PTE LTD
9 TAGORE LANE, #01-14 (9 @ TAGORE), 787472, Singapore
64594057
RAYMOND@MICPLSTICS.COM.SG

Claim Handler

HO Winnie

winnie.ho@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message