



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS/SPF22005793/Eqy3m4
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1		Date:	17/08/2022
HEMMANT ROAD SINGAPORE 438675			
ATTN: HAFIZUL FARHAN		Code:	SPF
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	GBH 7198B	Veh. Inspected	SLE 3755S
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2022/032	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	17/06/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	HONDA VEZEL	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU31121357	Colour	BLACK
Odometer	138129 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	215/70 R16	GOODYEAR	4 mm
L/H Front Tyre	215/70 R16	GOODYEAR	4 mm
R/H Rear Tyre	215/70 R16	GOODYEAR	4 mm
L/H Rear Tyre	215/70 R16	GOODYEAR	4 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.			
DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	09/06/2022	Inspection Date	21/06/2022
Survey held at	MOVA AUTOMOTIVE PTE LTD 15 FAN YONG ROAD SINGAPORE 629792		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	