

Steve

CS/SPF 22005793/eqy3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

CIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLK 3755S Yr Regn: 19/7/16
 Type: M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Honda Vezel c.c. 1496
 Colour: Black A/O: Insured / Std / Nil / NA
 Sp. Reading: 138129 T/Radio: Insured / Std / Nil / NA
 Eng/No: _____
 C/No: RUB 21857
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/70R16
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZ / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Front Rear
 R/Bal. 4 mm R/Bal. 0 mm
 L/Bal. 4 mm L/Bal. 4 mm
 D.O.A. 9/6/22 D.O.I. 21/6/22
 Survey held at Mova
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Front RH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MY-36K</u>

Date/Time, File Pass to?

☐ : Prel. Report

1)

Date/Time, File Return to?

☐ : Final Report

2)

Report Format: _____

Lump Sum / I.B.f. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL

Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

582A

Vehicle Details

Vehicle No.:

SLE37555

Vehicle to be Exported:

No

Intended Deregistration Date:

10 Jun 2022

Vehicle Make:

HONDA

Vehicle Model:

VEZEL 1.5X HYBRID CVT ABS D/AIRBAG 2WD

Primary Colour:

Black

Manufacturing Year:

2016

Engine No.:

LEB5071374

Chassis No.:

RU31121357

Maximum Power Output:

112.0 kW (150 bhp)

Open Market Value:

\$23,664.00

Original Registration Date:

19 Jul 2016

First Registration Date:

19 Jul 2016

Transfer Count:

3

Actual ARF Paid:

\$5,000.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

18 Jul 2026

PARF Rebate Amount:

\$3,500.00

Intended COE Rebate Details

COE Expiry Date:

18 Jul 2026

COE Category:

B - Car above 1600cc or 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$49,156.00

COE Rebate Amount:

\$20,177.00

Total Rebate Amount:

\$23,677.00

The information contained herein is correct as at 10 Jun 2022

OK



Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088884-2

Estimate

15/06/2022

SPF ACCIDENT CLAIM SECTION
No. 1 Mount Pleasant Rd
Blk 8 Old Police Academy
Singapore 298333.

Attention :- XA066

Page # :- 1

Veh # :- SLE3755S

Veh Model :- HONDA VEZEL 1.5X

Estimate# :- CK423505

Claim # :-

ACC. Date :- 09/06/22

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	HEADLAMP ASSY RH <i>BR ?</i>	1 PC	1,952.40	1,952.40
2.	HEADLAMP BRACKET RH	1 PC	39.20	39.20
3.	RADIATOR GRILLE <i>X</i>	1 PC	899.60	899.60
4.	FRONT BUMPER <i>00</i>	1 PC	489.20	489.20
5.	FRONT BUMPER RETAINER RH & LH <i>BR X</i>	1 PC	17.60	35.20
6.	FRONT BUMPER REINFORCEMENT (REPAIR) <i>CR4</i>	1 PC		
7.	FRONT BUMPER LOWER GARNISH	1 PC	391.00	391.00
8.	FRONT BUMPER CLIPS <i>116</i>	10 PC	3.50	35.00
9.	FOG LAMP ASSY RH <i>X</i>	1 PC	357.40	357.40
10.	FOG LAMP CHROME GARNISH RH <i>?</i>	1 PC	45.90	45.90
11.	WASHER TANK <i>?</i>	1 PC	78.90	78.90
12.	FRONT FENDER ARCH MOULDING RH <i>BR</i>	1 PC	278.40	278.40
13.	FRONT FENDER RH (REPAIR) <i>X R</i>	1 PC		
LIST TOTAL S\$				4,602.20
20% DISCOUNT S\$				-920.44
				3,681.76
SPECIAL NET ITEMS :				
1.	FRONT BUMPER LOWER GARNISH CHROME LH	1 PC	285.00	285.00
SPECIAL NET TOTAL S\$				285.00
LABOUR :				
TO KNOCK & STRAIGHTEN FRONT FENDER RH, HEADLAMP PANEL. REMOVE & REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION				300 500.00
SP RAY PAINT FRONT BUMPER, HEADLAMP PANEL, FRONT FENDER RH				400 500.00
CHECK WIRING & FOCUS HEADLIGHT				30.00
LABOUR TOTAL S\$				1,030.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved by LKK Auto Consultants
- Final settlement is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Main Office:
Mova Building
No. 22, Jalan Klang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

15/06/2022

SPF ACCIDENT CLAIM SECTION
No. 1 Mount Pleasant Rd
Blk 8 Old Police Academy
Singapore 298333.

Attention :- XA066

Page # :- 1 145742

Veh # :- SLE3755S

Veh Model :- HONDA VEZEL 1.5X

Estimate# :- CK423505

Claim # :-

ACC. Date :- 09/06/22

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 4,996.76

GST @ 7 % 349.77

AMOUNT DUE S\$ 5,346.53

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD