



## Case Details

Case Reference Number : TAX/06/22/2027  
Type of Repair : Accident Repair  
Vehicle Registration Number : SHB1196G

Company Type : Strides Taxi Pte Ltd  
Estimation ID : EST-18498-ID  
Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd  
Accident Date and Time : 08/06/2022 12:58 AM  
Vehicle Age(In Months) : 55

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

## Estimation Details

### Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				Remarks
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.6	Replace	Done ✓
Standard	Main			SUPPORT, FR BUMPER RH	1	76.90	76.90	25.00	57.68	Replace	0	0	Check	?
Standard	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	0	0	Not Give	Xm
Standard	Main			COVER, FR BUMPER RH	1	28.10	28.10	25.00	21.08	Replace	0	0	Not Give	Xm
Standard	Main			COVER, FR BUMPER LH	1	28.10	28.10	25.00	21.08	Replace	0	0	Not Give	Xm
Standard	Main			BRACKET, FR BUMPER	1	99.80	99.80	25.00	74.85	Replace	0	0	Not Give	Xm
Standard	Main			NUMBER PLATE	1	35.00	35.00	0.00	35.00	Replace	0	0	Not Give	Xm
Standard	Main			NUMBER PLATE FRAME	1	25.00	25.00	0.00	25.00	Replace	0	0	Not Give	Xm
Standard	Main			REINFORCEMENT FRONT UPPER	1	691.10	691.10	25.00	518.33	Replace	0	0	Not Give	Xm
Standard	Main			ABSORBER, FR BUMPER	1	70.30	70.30	25.00	52.72	Replace	0	0	Not Give	Xm
Standard	Main			EXTENSION SUB-ASSY, LH	1	116.30	116.30	25.00	87.23	Replace	0	0	Not Give	Xm
Standard	Main			EXTENSION SUB-ASSY, RH	1	116.30	116.30	25.00	87.23	Replace	0	0	Not Give	Xm
Total Spare Part Cost										Surveyor Total		3,896.56		
Lump Sum Discount (%)										Lump Sum Dis (%)		20.00		
Final Spare Part Cost										Final Sur Total		3,117.25		



Standard	Main	Portion	Material Number	Part Name	Qty	List Price	List Price (\$)	Dis (%)	Final Price (\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price (\$)	Repair/Replace	Remarks
BOM	Costing	Main		ABSORBER, BUMPER LOWER	1	117.00	25.00	87.75	Replace	0	0	0	Not Give	Xm
Standard	Main			SEAL, HOOD TO FR END	1	24.40	24.40	25.00	18.30	Replace	0	0	Not Give	Xm
Standard	Main			EMBLEM ASSY FRONT	1	87.10	87.10	25.00	65.32	Replace	1	65.32	Replace	ne
Standard	Main			GRILLE, RADIATOR	1	165.00	165.00	25.00	123.75	Replace	0	0	Not Give	Xm
Standard	Main			GRILLE SUB-ASSY	1	335.60	335.60	25.00	251.70	Replace	0	0	Not Give	Xm
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	ne
Standard	Main			RETAINER, FR BUMPER, LH & RH	1	8.50	8.50	25.00	6.38	Replace	0	0	Not Give	Xm
Standard	Main			COVER ASSY, ENGINE	1	180.10	180.10	25.00	135.08	Replace	0	0	Not Give	Xm
Standard	Main			COVER, ENGINE UNDER SIDE RH	1	76.90	76.90	25.00	57.68	Replace	0	0	Check	?
Standard	Main			LAMP ASSY, FOG, RH	1	910.20	910.20	10.00	819.18	Replace	1	819.1	Replace	ca
Standard	Main			UNIT, HEADLAMP, RH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	1	2,303	Replace	ca
Standard	Main			COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	1	486.40	486.40	10.00	437.76	Replace	0	0	Not Give	Xm
Standard	Main			SUPPORT S/A UPPER,	1	364.90	364.90	25.00	273.67	Replace	0	0	Not Give	Xm
Standard	Main			SUPPORT S/A RH	1	237.00	237.00	25.00	177.75	Replace	0	0	Not Give	Xm
Standard	Main			SUPPORT, RADIATOR UPPER RH	1	76.70	76.70	25.00	57.53	Replace	0	0	Not Give	Xm
Standard	Main			WIPER WASHER INLET	1	55.40	55.40	25.00	41.55	Replace	0	0	Check	?
Standard	Main			WIPER WASHER JAR	1	183.60	183.60	25.00	137.70	Replace	1	137.7	Replace	de

Standard	Main			MOTOR AND PUMP ASSY, WINDSHIELD WASHER	1	245.00	245.00	10.00	220.50	Replace	0	0	Not Give	Xm
Standard	Main			FENDER SUB-ASSY, FR, RH	1	933.10	933.10	25.00	699.83	Replace	1	0	Repair	R
Standard	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.68	Replace	1	39.67	Replace	ne
Standard	Main			LINER, FR FENDER, RH	1	198.40	198.40	25.00	148.80	Replace	1	148.8	Replace	de
Standard	Main			PAD FR WHFFI	1	57.70	57.70	25.00	43.28	Replace	-	-	-	Xm
					Total Spare Part Cost		7,749.88		Surveyor Total		3,896.56			
					Final Spare Part Cost		6,165.28		Final Sur Total		3,117.25			

RH SMRT Recommendation															0	0	Not Given
															Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price	Total Price	Spare Part Price	Discount (%)	Final Price	Repair/ Replace	Surveyor Quantity	Surveyor Final Price	Surveyor Replace	Remarks		
						Per Lump Sum Unit(\$)				20.00				20.00			
Final Spare Part Cost										6,165.28		Final Sur Total		3,117.25			

#### Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT RH PORTION	845.00	300.00	
Total:			845.00	300.00	

#### Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	378.00	200.00	
2	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00	XM
3	Main	TO RESPRAY FRONT FENDER RH	378.00	200.00	
Total:			936.00	400.00	

#### Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	56.00	0.00	? provide receipt
2	Main	TO WASH AND VACUUM	60.00	0.00	XM
3	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	40.00	
4	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00	XM
5	Main	TO REPLACE SUNDRY PARTS	100.00	0.00	XM
Total:			436.00	40.00	

## Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	6,165.28	3,117.25
Total Labour Cost	845.00	300.00

	Estimator Assessment(\$)	Surveyor Assessment(\$)
otal Spray Painting	936.00	400.00
Other	436.00	40.00
Overall Total	8,382.28	3,857.25
Lump Sum Repair Option	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	8,400.00	3,850.00
Surveyor Approved Amount		3,850.00
No of Repair Days*	6	3
Remarks	-	resurvey after repair lum sum
Surveyor Name		Rasul
Signature		
Survey Date	09/06/2022	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	09/06/2022 13:28 (SGT)
Date of Accident	08/06/2022 08:58 (SGT)
Exact Location of Accident	Bedok Ave, Singapore
Additional Location Information	BEDOK AVE
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB1196G
-----------------------------	----------

### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	198905369K
Company Reg No	XXXXXXXXXXXXXXXXXXLtd
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Mobile Phone No	(Phone) +65-68662671
Alternative Phone No	(Office) +65-68662672

### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1800

### INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	D-22099115MFSH
Cover Note Number	-

### DRIVER

Name of Driver	HO KIAN HOCK
NRIC No	SXXXX924F



Date Of Birth	05/01/1960
Occupation	Outdoor
Date Of Driving Pass	04/01/1980
Driving experience	42 YEARS AND 5 MONTHS
Gender	Male
Mobile Number	(Phone) +65-68662672
Alt. Phone Number	-
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Address	11
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

ON 08/06/22 AT ABOUT 0858HRS. I WAS TRAVELLING ALONG BEDOK AVE. WHEN I MAKE A LEFT TURN INTO BEDOK AVE SUDDENLY A VEHICLE CUT INTO MY LANE AND HIT ONTO THE FRONT RIGHT PORTION OF MY VEHICLE.

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE TOO BIG
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJH2900D
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	LIM HIANG LAN
Contact Number	-

Address  
Address complement  
Postcode  
Insurance Company Name  
Nature Of Damage  
Details of property damaged in accident  
No. Of Passenger (Including Driver)



## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (# driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel


### Sketch Plan



A-S4B1196G  
B-SJ12900D

[illegible]

I/We declare the foregoing particulars are true in every respect.



3

A



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	369K
Vehicle No.:	SHB1196G
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jun 2022
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZRS102744
Chassis No.:	JTDKB3FU403573822
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	28 Nov 2017
First Registration Date:	28 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Nov 2025
PARF Rebate Amount:	\$3,750.00
COE Expiry Date:	27 Nov 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$33,596.00
COE Rebate Amount:	\$14,546.00
Total Rebate Amount:	\$18,296.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 10 Jun 2022

OK