

ASS. RECD. BY:

REF: LPC /Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: \$ 93k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 18 days

Res.: Yes or No

Lum Sum: 1.81 %

3 Val.: Yes or No

CA / RE / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: YQ 4703TYr Regn: 10, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: ToyotaC.C. 2758Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 20129

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMA GV 4630K 001236Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: _____

R: _____

S / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 5 mmR/Bal. 55 mmL/Bal. 5 mmL/Bal. 55 mmD.O.A. 14/6/22D.O.I. 20/6/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation

Add Fee: ☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Invs (\$)

☐

Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$)

TOTAL

YQ 4703T
OD/LOWPAC

Make: 2001 SA Weight: 11,210
 Truck / Trailer or Van / Lorry / Taxi / Prime Mover / 07

NOT Withheld
Revery B4 point
Ex @ 600k
16 days

FAX: 62963767

Claim No: ES2290603
Estimate No: ES2290603/YISHUN
Date: 18 Jun 2022
Policy No: Z/21/VC00/112764
Veh Reg No: YQ4703T
Make/Model: TOYOTA TOYOTA
 DYNA 150 5MT

Chassis No: JHHAGV4630K001236

Engine No: 1GD8811614

Reg. Date: 27/10/2021

Optima

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Cost Plus				
1 FRONT BUMPER	230.00	1 PC	230.00	✓
2 FRONT BUMPER LH BRACKET	105.00	1 PC	105.00	?
3 FRONT BUMPER LH FOG LAMP GARNISH	38.00	1 PC	38.00	?
4 HEADLAMP LH	310.00	1 PC	310.00	✓
5 FRONT GRILLE	250.00	1 PC	250.00	✓
6 FRONT GRILLE LOGO	40.00	1 PC	40.00	✓
7 FRONT PANEL	280.00	1 PC	280.00	✓
8 FRONT PANEL EMBLEM (DYNA)	42.00	1 PC	42.00	✓
9 FRONT WIPER PANEL	145.00	1 PC	145.00	✓
10 FRONT LH CORNAL PANEL	118.00	1 PC	118.00	✓
11 FRONT WINDSCREEN GLASS RUBBER	95.00	1 PC	95.00	✓
12 FRONT LH SIDE MIRROR	195.00	1 PC	195.00	✓
13 FRONT LH SIDE MIRROR MOTOR	250.00	1 PC	250.00	?
14 FRONT LH SIDE MIRROR ROUND	75.00	1 PC	75.00	✓
15 FRONT WIPER TANK	120.00	1 PC	120.00	?
16 AIR-CON CONDENSER WITH MOTOR	540.00	1 PC	540.00	✓
17 FRONT LH WINDSCREEN PILLAR OUTER	200.00	1 PC	200.00	✓
18 FRONT LH WINDSCREEN PILLAR INNER	210.00	1 PC	210.00	✓
19 FRONT LH WINDSCREEN PILLAR LOWER INNER	160.00	1 PC	160.00	✓
20 FRONT LH WINDSCREEN PILLAR STEP PANEL LOWER	58.00	1 PC	58.00	✓
21 FRONT LH WINDSCREEN PILLAR STEP PANEL LOWER SIDE	75.00	1 PC	75.00	✓
22 FRONT LH DOOR	550.00	1 PC	550.00	✓
23 FRONT LH DOOR GLASS	220.00	1 PC	220.00	✓
24 FRONT LH DOOR GLASS REGULATOR	105.00	1 PC	105.00	✓
25 FRONT LH DOOR GLASS REGULATOR MOTOR	215.00	1 PC	215.00	✓
26 FRONT LH DOOR OUTER MOULDING	60.00	1 PC	60.00	✓
27 FRONT LH DOOR TOP HINGE	40.00	1 PC	40.00	✓
28 FRONT LH DOOR BOTTOM HINGE	40.00	1 PC	40.00	✓
29 FRONT LH DOOR INNER LOCK	120.00	1 PC	120.00	✓
30 FRONT LH DOOR INNER RUBBER	80.00	1 PC	80.00	✓
31 FRONT LH DOOR INNER TRIM BOARD	310.00	1 PC	310.00	✓
32 FRONT LH DOOR CHECKER	65.00	1 PC	65.00	✓
33 FRONT LH DOOR TRAY	55.00	1 PC	55.00	✓
34 CABIN REAR LH PILLAR OUTER	290.00	1 PC	290.00	✓
35 FRONT LH WHEEL ARP PANEL TOP GARNISH	105.00	1 PC	105.00	✓
36 DASHBOARD LH AIR-BAG	1,300.00	1 PC	1,300.00	?
37 DASHBOARD LH UNDER COVER GARNISH	140.00	1 PC	140.00	?
38 FRONT LH STEP TRAY	120.00	1 PC	120.00	?
39 AIR-CON BLOWER	1,600.00	1 PC	1,600.00	?

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : LONPAC INSURANCE BERHAD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

TEL: 62507388 FAX: 62963767
ATTN: Motor Claim Department

WS Ref: OD/LONPAC
Claim Type: Own Damage
Accident Date: 14/06/2022

Claim No: ES2290603
Estimate No: ES2290603/YISHUN
Date: 18 Jun 2022
Policy No: Z/21/VC00/112764
Veh Reg No: YQ4703T
Make/Model: TOYOTA TOYOTA
DYNA 150 5MT
Chassis No: JHHAGV4630K001236
Engine No: 1GD8811614
Reg. Date: 27/10/2021

Estimate Repair Cost to Vehicle No : YQ4703T

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
40 FRONT LH WHEEL ARP PANEL LOWER RUBBER	28.00	1 PC	28.00	
41 FRONT LH DOOR FRAME RUBBER	95.00	1 PC	95.00	
			9,074.00	
	Add 15%		1,361.10	10,435.10
Labour				
42 REMOVE AND REFIX FRONT WINDSCREEN GLASS	60.00	1 LA	60.00	
43 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	
44 REMOVE & REFIX DASHBOARD,METER ASSY AND CHECK WIRING	280.00	1 LA	280.00	250
45 REMOVE & REFIX TOP ROOF LINING,SEAT,CARPET,ETC	100.00	1 LA	100.00	
46 REMOVE & REFIX FRT BUMPER ASSY,HEADLAMP,FRT GRILLE,FRT LH DOOR & ATTACHMENT,TO STRAIGHTEN,CUT,WELD & RENEW FRT LH W/SCREEN PILLAR,REAR LH CORNAL PILLAR OUTER,FRT LH WHEEL ARP PANEL,FRT PANEL,FRT LH STEP PANEL,TO BE CONTINUED	2,800.00	1 LA	2,800.00	2400
47 KNOCK & REPAIR FLOOR BOARD PANEL,CABIN REAR PANEL AND REALIGN CABIN STRUCTURE INCLUDING REMOVE & REFIX CABIN,REPLACE CABIN MOUNTING AND CABIN POSITION	0.00	1 LA	0.00	
48 PUTTY & RESPRAY ON FRT LH DOOR,FRT LH W/SCREEN PILLAR,WHEEL ARP PANEL,REAR LH PILLAR,FRT FLOOR PANEL,FRT BUMPER GRILLE,CABIN REAR PANEL,WIPER APNEL AND ALL AFFECTED AREAS	1,400.00	1 LA	1,400.00	1200
49 REMOVE & REFIX FRT LH DOOR GLASS	60.00	1 LA	60.00	
				4,800.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Total S\$ 15,235.10
Add GST @ 7% 1,066.46
Total Amount payable S\$ 16,301.56

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

YQ4703T
OD/10/11/22
Lampac

Vehicle Owner Particulars

Owner ID Type: Business

Owner ID: 378A

Vehicle Details

Vehicle No.: YQ4703T

Vehicle to be Exported: Yes

Intended Deregistration Date: 14 Jun 2022

Vehicle Make: TOYOTA

Vehicle Model: DYNA 150 5MT

Primary Colour: Silver

Manufacturing Year: 2021

Engine No.: 1GD8811614

Chassis No.: JHHAGV4630K001236

Maximum Power Output: -

Open Market Value: \$31,609.00

Original Registration Date: 27 Oct 2021

First Registration Date: 27 Oct 2021

Transfer Count: 0

Actual ARF Paid: \$1,581.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 26 Oct 2031

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$31,406.00

COE Rebate Amount: \$25,124.00

Total Rebate Amount: \$25,124.00

The information contained herein is correct as at 14 Jun 2022

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 14/06/2022 18:58 (SGT)
Date of Accident 14/06/2022 10:00 (SGT)
Exact Location of Accident Singapore
Additional Location Information PIE TOWARDS LORNIE RD(SLIP RD)
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number YQ4703T

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner CHAI HOE CONSTRUCTION
Company Reg No 5XXXX378A
Email Address scyconstruction@hotmail.com
Mobile Phone No (Phone) +65-91094670
Alternative Phone No +65-91094670

VEHICLE PARTICULARS

Manufacturer Toyota
Model DYNA 150 5MT
Variant -
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Commercial vehicle
Transmission Manual
CC 2755


INSURANCE COMPANY

Name of Insurance Company Lonpac Insurance Bhd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number Z/21/VC00/112764
Cover Note Number 27/10/21-26/10/22

DRIVER

Name of Driver SELVAMANI LOGANATHAN
Passport No/FIN GXXXX115T

Sketch Plan



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At the slip road in front vehicle (SMH 704G) suddenly e brake.
So when I brake my vehicle my vehicle can't stop in time and hit onto
"said vehicle rear portion and cause damage. But no injury on
both party.

Note : Please note that your insurer may have 14 days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/we declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

☒ Claim Own Policy ☐ Claim Third Party ☐ Reporting Only
☐ Claim OD/TP at other workshop ()