

REF:

## ASSIGNMENT

Veh No: SMJ793SA Yr Regn: 2017, March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mit Atrage. C.C. 1193

Colour Red. A/C: Insured / Std / NI / NA

Sp. Reading 42074 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MMRSTA13AKH\*001147

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: in order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim STD A/Rim or

Tyre Size: F: 185/55R15

R. 185/55R15.

PS / SUM / EXNOVA / CY / ES / LIZA / MIC / OUTSH / RIR / SUM /

TOYO / YOKO or

| Front               | Rear                |
|---------------------|---------------------|
| R/Bal. <i>ob</i> mm | R/Bal. <i>ob</i> mm |


L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 14/06/22

Survey held at TK

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

|   |     |
|---|-----|
|  |     |
| N/S   | O/S |
|   |     |

| Date / Time | Action / Instruction |
|-------------|----------------------|
|             | TP AIG.              |
|             |                      |
|             |                      |
|             | MV :                 |
|             | PV :                 |
|             | Nett :               |
|             |                      |
|             | 687Z.                |

☐ : Prel. Report  
☐ : Final Report

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$ ) \$ + RS \$☐ Interview (\$ ) Photos

|  |                 |        |
|--|-----------------|--------|
|  | Tech. Invs (\$) | Others |
|--|-----------------|--------|

1. *Journal of the American Medical Association*, 1964; 191: 1000-1001.