

REF:

ASSIGNMENT

Veh No: SNA 63074. Yr Regn: 2020 / Jan

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Vellfire C.C 2494

Colour White . A/C: Insured / Std / NI / NA

Sp. Reading 71060 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTNGF3DH4280x2465

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ~~In order~~ / Jammed / Leaked / Burnt or

Brake: inorder / Jammed / Leaked / Burnt or

Modif: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/50R18.

R: 235/50 R18

R: 235/50 R18

BS / (DUN) EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO/YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 15/06/22

Survey held at S.M.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Recd n/c

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]

Preli. Report

Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: : Site Insp (\$

1: Site Insp (\$

$$) \quad \underline{\hspace{1cm}} S + PS, \quad \underline{\hspace{1cm}} S$$

Photos

1. *Chier*

Report Formed :

Lamin 2000 / L2E 60