



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CYNTHIA			Ref: CC4/ASM22005839/Upa3q2 Date: 02/11/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XE 776J	Veh. Inspected	XD 8981K	
Policy No.	GA569088	Coverage (\$)	0.00	
Claim No.	S2M040NK	Excess (\$)	0.00	
Assign From		Assign Date	20/06/2022	
2. Vehicle Particulars & Condition				
Make & Model	SCANIA P310	c.c	9291	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	YS2P4X20005344282	Colour	WHITE	
Odometer	885880 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	BRIDGESTONE	5 mm	
L/H Front Tyre	295/80 R22.5	BRIDGESTONE	5 mm	
R/H Rear Tyre	295/80 R22.5 (D)	BRIDGESTONE	5/5 mm	
L/H Rear Tyre	295/80 R22.5 (D)	BRIDGESTONE	5/5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/05/2022	Inspection Date	22/06/2022	
Survey held at	MAH LIAN MOTOR VEHICLE REPAIRER 38 DEFU LANE 9 SINGAPORE 539278			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	