ASS. REG. BY:	22003844 1kg
Kouseel	SSIGNMENT
Estimated Cost: OD/ TP / WS / TP RES / OD RES / EVA / INV / MV	Veh No: SLL 5425U Yr Regn: 1015 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover / Truck / Trailer or
To Inspect Vehicle No: at Workshop m/s of Insured: Policy No. Claims No.	Make: Land Rove Range Rove 1998 Colour White AC: Insured / Std / NI / NA Sp.Reading / G4/24 T/Radio: Insured / Std / NI / NA Eng/No: C/No: SALVA 2AG 3514 048158 Gen. Cond: Good/ Fair / Poor / Burnt
Sum Insured: Excess: 250L (Client's Record) Make of Veh;	Steering: Inorder / Jammed / Leaked / Burnt or Brake: Inorder / Jammed / Leaked / Burnt or Modi: Nii / S/Rim / STD A/Rim or Tyre Size: F:
(Policy Condition) Remark: The veh had commenced its repair at the time of Inspection. Bal. or Market Value: 8/0/K IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est. Repairs: 0/4 days Res.: Yes or No Lum Sum: /-Bi/ % 3 Val.: Yes or No	R: 235/60R18 BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/ TOYO/YOKO or Cartinuma/ Front Rear R/Bal. 4 mm R/Bal. 5 mm L/Bal. 4 mm L/Bal. 5 mm D.O.A. 15/6/22 D.O.I. 21/6/2022
CA / REV. / REP. / 24 HRS Date: Person Contacted: Vehicle: IN / OUT Date / Time Action / Instruction	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or N/S / S/ The U/C / Chassis frame / Body Structure affected due to collision.
I Floring	Survey Fee: Transportation Site Insp (\$) _ \$ + RS _ \$I Interview (\$) Final S Tech Invs (\$) Others
	Weekend (\$

Lai Huat (Meng Kee) Motor Pte Ltd 160 Sin Ming Drive, #04-01, #04-02 & #07-03, Sin Ming Autocity 575722

Insurer Reference:

Repairer Reference: 72775

Date calculated: 20/06/2022 3:20 PM

Full Report

Registration: SLL 5425U

Printed: 20/06/2022 3:21 PM

Summary Information

Claim

Location:

Singapore (SG)

Jenny Lim

Work Provider:

China Taiping Insurance

(Singapore) Pte Ltd

SGD

15/06/22

Printed by:

Claim Reference:

Estimated Repair Time: Actual Repair Days:

6

Date of Incident:

Currency:

Hire Car Start: Hire Car End:

Vehicle Details

Vehicle

Manufacturer:

Model:

Sub Model:

Model Sheet Number:

Registration:

VIN number:

Odometer:

Model Specs

FROM VIN ..FH000001 MIRROR WITH LIGHT

FOG LAMPS

ELECT SEAT ADJUST 6X KEYLESS ENTRY/START DOOR MOULD BRUNEL 2.0 LTR 179/180KW WHEELS 8J X 18 ALU SILL PANEL UPP LIGHT

SLL 5425U

LAND ROVER

EVOQUE (LV)

DYNAMIC

33 22 02

SALVA2AG3FH046158

RAIN SENSOR

DOOR MIRROR MEM/HEAT HEADLAMP WASHERS DRIVER'S MEMORY PACK AUDIO SYSTEM GAMA FR PARK DIST CONTROL EXH TAIL PIPE OVAL

DYN STABILITY CONTR

TIPTRONIC

IND HEATER W/REM CON START & STOP SYSTEM HEADLAMP LEVELLING RAD GRILLE BRUNEL WING GRILLE BRUNEL **ELECTRIC TAILGATE** CRUISE CONTROL REAR ARMREST

BASECOAT CLEAR

INT MIRROR AUTODIP **BI-XENON HEADLAMPS ELECT SEAT ADJUST 8X ELECT LUMBAR ADJUST** T/GATE MOULD BRUNEL LEATHER TRIM TYRES 235/60 R18..H 5-DOOR (HATCHBACK)

Not Notherial

Menny Bepany

Ex & 15 dh

Eday

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Pade 1 of 5

PRINT DATE 20/06/2022

Audatex System Using Manufacturer Times


Vehicle Condition

Vehicle Status

Pre-Accident Damage: Date of Inspection:

Damage Areas

All Underbody



Tyres Condition

Tyre Brand

Tread (Left Middle), Tread (Left Outer), Tread (Left Inner), Tread (Right Inner), Tread (Right Outer), Tread (Right

Condition

mm

mm

mm

mm

mm

Middle), mm

Spare Tyre Brand

Tread (Spare), mm

Labour

Code Description WU Price SG 02.02.02 ADDITIONAL TIME FOR SEPARATE WORKSHOP PRESENTATION 2.0 8.4 76.22.72.99 R + R FRONT BUMPER INCLUDES: WHEELHOUSE LINER, FRONT WHEELS AND REQUIRED TRIMS REMOVE AND REFIT 6.0 25.2 76.22.72) RENEW FRONT BUMPER COVER (FRONT BUMPER TRIM REMOVED) INCLUDES: R + R ATTACHED PARTS 7.0 29.4 76.55.03 R + R RADIATOR GRILLE NO NUMBER R + R FRONT BUMPER WIRING HARNESS 3.0 12.6 86.40.02) R + R LEFT HEADLAMP 2.0 8.4 86.40.17 ADD WORK FOR H-LAMP LEVEL CONTROL 1.0 4.2 NO NUMBER R + R BONNET 7.0 29.4 76.16.01) RENEW BONNET (REMOVED) 7.0 29.4 NO NUMBER ALIGN W/O ADJUST FRONT VEHICLE 5.0 21.0	Labour			22.22.11
02.02.02 ADDITIONAL TIME FOR SEPARATE WORKSHOP PRESENTATION 76.22.72.99 R + R FRONT BUMPER INCLUDES: WHEELHOUSE LINER, FRONT WHEELS AND REQUIRED TRIMS REMOVE AND REFIT 76.22.72) RENEW FRONT BUMPER COVER (FRONT BUMPER TRIM REMOVED) INCLUDES: R + R ATTACHED PARTS 76.55.03 R + R RADIATOR GRILLE NO NUMBER R + R FRONT BUMPER WIRING HARNESS 86.40.02) R + R LEFT HEADLAMP 2.0 8.4 86.40.017 ADD WORK FOR H-LAMP LEVEL CONTROL NO NUMBER R + R BONNET 76.16.01) RENEW BONNET (REMOVED) NO NUMBER ALIGN W/O ADJUST FRONT VEHICLE 77.28.29) R + R L/F WING		Time Base 10 WU/h		
PRESENTATION 76.22.72.99 R + R FRONT BUMPER INCLUDES: WHEELHOUSE LINER, FRONT WHEELS AND REQUIRED TRIMS REMOVE AND REFIT 76.22.72) RENEW FRONT BUMPER COVER (FRONT BUMPER TRIM REMOVED) INCLUDES: R + R ATTACHED PARTS 76.55.03 R + R RADIATOR GRILLE NO NUMBER R + R FRONT BUMPER WIRING HARNESS 86.40.02) R + R LEFT HEADLAMP 86.40.17 ADD WORK FOR H-LAMP LEVEL CONTROL NO NUMBER R + R BONNET 76.16.01) RENEW BONNET (REMOVED) NO NUMBER ALIGN W/O ADJUST FRONT VEHICLE 77.28.29) R + R L/F WING 6.0 25.2 25.2 25.2 25.2 25.2 26.0 25.2 26.0 26.0 27.0 29.4 29.4 20.0 20.0 21.0 20.0	Code	Description	WU	Price SGD
INCLUDES: WHEELHOUSE LINER, FRONT WHEELS AND REQUIRED TRIMS REMOVE AND REFIT 76.22.72) RENEW FRONT BUMPER COVER (FRONT BUMPER TRIM REMOVED) INCLUDES: R + R ATTACHED PARTS 76.55.03 R + R RADIATOR GRILLE NO NUMBER R + R FRONT BUMPER WIRING HARNESS 86.40.02) R + R LEFT HEADLAMP 86.40.17 ADD WORK FOR H-LAMP LEVEL CONTROL NO NUMBER R + R BONNET 76.16.01) RENEW BONNET (REMOVED) NO NUMBER ALIGN W/O ADJUST FRONT VEHICLE 77.28.29) R + R L/F WING INCLUDES: WHEELHOUSE LINER, FRONT WHEELS AND REMOVED 7.0 29.4 4.2 4.2 5.0 21.0 7.0 29.4	02.02.02		2.0	8.40
(FRONT BUMPER TRIM REMOVED) INCLUDES: R + R ATTACHED PARTS 76.55.03 R + R RADIATOR GRILLE 1.0 4.2 NO NUMBER R + R FRONT BUMPER WIRING HARNESS 3.0 12.6 86.40.02) R + R LEFT HEADLAMP 2.0 8.4 86.40.17 ADD WORK FOR H-LAMP LEVEL CONTROL 1.0 4.2 NO NUMBER R + R BONNET 5.0 21.0 76.16.01) RENEW BONNET (REMOVED) 7.0 29.4 NO NUMBER ALIGN W/O ADJUST FRONT VEHICLE 5.0 21.0 77.28.29) R + R L/F WING 11.0 46.2	76.22.72.99	INCLUDES: WHEELHOUSE LINER, FRONT WHEELS AND REQUIRED TRIMS	6.0	25.20
NO NUMBER R + R FRONT BUMPER WIRING HARNESS 3.0 12.6 86.40.02) R + R LEFT HEADLAMP 2.0 8.4 86.40.17 ADD WORK FOR H-LAMP LEVEL CONTROL 1.0 4.2 NO NUMBER R + R BONNET 5.0 21.0 76.16.01) RENEW BONNET (REMOVED) 7.0 29.4 NO NUMBER ALIGN W/O ADJUST FRONT VEHICLE 5.0 21.0 77.28.29) R + R L/F WING 11.0 46.2	76.22.72)	(FRONT BUMPER TRIM REMOVED)	7.0	29.40
86.40.02) R + R LEFT HEADLAMP 2.0 8.4 86.40.17 ADD WORK FOR H-LAMP LEVEL CONTROL 1.0 4.2 NO NUMBER R + R BONNET 5.0 21.0 76.16.01) RENEW BONNET (REMOVED) 7.0 29.4 NO NUMBER ALIGN W/O ADJUST FRONT VEHICLE 5.0 21.0 77.28.29) R + R L/F WING 11.0 46.2	76.55.03	R + R RADIATOR GRILLE	1.0	4.20
86.40.17 ADD WORK FOR H-LAMP LEVEL CONTROL 1.0 4.2 NO NUMBER R + R BONNET 5.0 21.0 76.16.01) RENEW BONNET (REMOVED) 7.0 29.4 NO NUMBER ALIGN W/O ADJUST FRONT VEHICLE 5.0 21.0 77.28.29) R + R L/F WING 11.0 46.2	NO NUMBER	R + R FRONT BUMPER WIRING HARNESS	3.0	12.60
86.40.17 ADD WORK FOR H-LAMP LEVEL CONTROL 1.0 4.2 NO NUMBER R + R BONNET 5.0 21.0 76.16.01) RENEW BONNET (REMOVED) 7.0 29.4 NO NUMBER ALIGN W/O ADJUST FRONT VEHICLE 5.0 21.0 77.28.29) R + R L/F WING 11.0 46.2	86.40.02)	R + R LEFT HEADLAMP	2.0	8.40
76.16.01) RENEW BONNET (REMOVED) 7.0 29.4 NO NUMBER ALIGN W/O ADJUST FRONT VEHICLE 5.0 21.0 77.28.29) R + R L/F WING 11.0 46.2		ADD WORK FOR H-LAMP LEVEL CONTROL	1.0	4.20
76.16.01) RENEW BONNET (REMOVED) 7.0 29.4 NO NUMBER ALIGN W/O ADJUST FRONT VEHICLE 5.0 21.0 77.28.29) R + R L/F WING 11.0 46.2	NO NUMBER	R + R BONNET	5.0	21.00
NO NUMBER ALIGN W/O ADJUST FRONT VEHICLE 5.0 21.0 77.28.29) R + R L/F WING 11.0 46.2			7.0	29.40
77.28.29) R + R L/F WING 11.0 46.2			5.0	21.00
		R + R L/F WING	11.0	46.20

76.34.01.99 76.58.07) 76.11.92) NO NUMBER NO NUMBER NO NUMBER NO NUMBER 57.65.04 1000	INCLUDES: R + R INNER WING PROTECT: R + R LEFT FRONT DOOR TRIM R + R LEFT FRONT OUTER DOOR HANDLE R + R LEFT MIRROR REFIT RIM AND/OR L/FR TYRE R + R FRONT PARKING AID SENSORS AD R + R FRONT FOG LAMPS (ADD/WORK) R + R HEADLAMP WASHER (ADD/WORK) ALIGN FRONT AXLE WHEEL L/R		20	2.0 3.0 2.0 3.0 2.0 2.0 2.0 8.0 3 0 :0*	12.60 8.40
	Labour Cost Panel / Mechanical Labour Alignment Measuring Work		Hrs 9.10 1.30	WU 91.0	382.20 54.60
	Total of Labour		2100	1010	436.80
					430.00
Paint Work	SYSTEM A	7T	Tin	ao Pacie	10 WU/h
Code	Description - BASECOAT CLEAR	21	1111		Price SGD
	BONNET NEW PART PAINTING L/R LAMP BRACKET SURFACE PAINT FRONT BUMPER NEW PART PAINT K1R L/F WING NEW PART PAINT K1R L/FR WHEEL REPAIR PAINTING >50% LEFT FRONT DOOR SURFACE PAINT			27.0 4.0 12.0 5.0 12.0 9.0	
Paint Material	Per Part				
Code	Description				Price SGD
0471 0549 0283 0741 7201 1481	BONNET NEW PART PAINTING L/R LAMP BRACKET SURFACE PAINT FRONT BUMPER NEW PART PAINT K1R L/F WING NEW PART PAINT K1R L/FR WHEEL REPAIR PAINTING >50% LEFT FRONT DOOR SURFACE PAINT				89.78 1.25 61.01 14.76 7.90 24.90
	Labour Cost - Paint Factor	42.00 SGD/h	Hrs	WU	Price SGD
	Time Paint Preparation Main Work Metal Preparation Comp. Work Plastic	72.00 300/11	2.10 0.50	69.0 21.0 5.0	88.20 21.00
	Total	10 WU/h	9.50	95.0	399.00

Description

Code

WU Price SGD

Material Cost - Paint	
New Part Painting	
New Part Painting - Plastic K1R	
Repair Painting	
Surface-/Blend Paint	
Material-constant Metal	
Material-constant Plastic	
Total	

Price SGD 89.78 75.77 7.90 26.15 18.10 9.00 226.70

Spare Parts

Code	Description	Part Number	Part Soi	urce	prices as at 2001-01-01 Price SGD
0420	DADGE IIDANGEII				
0438	BADGE "RANGE"	LR026394			0.00
0471	BONNET	\$1850.00 LESS20%	Used		Br ~ 1,480.00
0437	BONNET BADGE "ROVER"	LR026395			0.00
0283	FRONT BUMPER	\$1220.00 LESS20%	Used	•	CM - 976.00
9582	FRT BUMPER W- HARNESS	LR065077	Original		₹ ∠ 350.00
0637	L/F FOG LAMP	LR077888	Original	400	MIY 450.00
7227	L/FR TYRE	235/60 R 18 H	Original		Pn 2 250.00
0305	L/F UPPER GRILLE	LR057397	Original	60	111 - 40.00
0787	L/F W-ARCH MOULDING	LR036053	Original	135	mil _ 115.00
0741	L/F WING	\$660.00 LESS20%			cm - 528.00
0307	L/LOWER TRIM GRILLE	LR026546	Original		40.00
0549	L/R LAMP BRACKET	LR001538	Original		√ × 50.00
0561	LEFT HEADLAMP ASSY	\$1360.00 LESS20%	Used		cm - 1,088.00
f: OEM Parts	Savings				0.00
n: Non-OEM Parts	Subtotal				5,367.00
u: Used parts	Fixed Sundry Parts F	Price			100.00
	Total			=	5,467.00

Extras

= > < C : C : C : C : C : C : C : C : C : C		
Code	Description	Price SGD
1001	CHK/CLR FAULT CODES DIAGNOSTIC	√120.00*
	Total Extras	120.00

Final Calculation

	SGD	SGD
Parts	5,367.00	
Fixed Sundry Parts Price	100.00	
Total Parts		5,467.00
Labour Time Base 10 WU/h		
Total 91.0 WU X 42.00 SGD/h Alignment	382.20	
Measuring Work	54.60	
Total of Labour		436.80
Total Of Extras		120.00
Paint Work Time Base 10 WU/h		
Labour Cost 95.0 WU X 42.00 SGD/h	399.00	
Material Cost	226.70	
Total Paint Including Material		625.70
Repair Cost Excludes GST		6,649.50
GST (+7.0%)		465.47
Repair Cost Included GST		7,114.97

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

lease report correctly the details of the accident to speed up the claims process

2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

17/06/2022 17:13 (SGT) 15/06/2022 11:20 (SGT) Balestier Rd, Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SLL5425U

Singapore

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner NRIC No **Email Address** Mobile Phone No Alternative Phone No

VEHICLE PARTICULARS

Manufacturer Model Variant Exact purpose for which vehicle was being used at time of accident Are you claiming under your own insurance policy for repair to your vehicle? Vehicle Category Transmission CC

INSURANCE COMPANY

Name of Insurance Company Type of Coverage Fleet Policy Policy Number Cover Note Number

DRIVER

Name of Driver NRIC No

No Eng Cher Suah SXXXX752D engchersuah@gmail.com (Phone) +65-98191507 +65-98191507

LandRover Evoque

Private use

Yes Private car Auto 2000

China Taiping Insurance (Singapore) Pte. Ltd. Comprehensive No DMPCSNW00187612101

Eng Cher Suah SXXXX752D

Date Of Birth Occupation

Date Of Driving Pass Driving experience

Gender

Mobile Number Alt. Phone Number **Email Address**

Address

Address complement

Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions

Road Surface

OTHER INFORMATION

Was any foreign vehicle involved in the accident?

Number of vehicles involved in the accident Was anybody injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any other vehicle or property damaged? Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s)

soliciting/offering accident claims assistance?

DETAILS OF POLICE ACTION

Was the accident reported to the police?

Police Station Name Police Station Phone No Alt. Police Station Phone No Police Station Address

Was notice of intended Prosecution given?

If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

Please refer to the sketch plan/police report no: T/20220617/7026.

ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Was there any audio recorded?

Yes

09/05/1962

41 YEARS AND 5 MONTHS

(Phone) +65-98191507

Collided into Property

engchersuah@gmail.com 411 Pasir Ris Drive 6 #07-389

+65-98191507

Outdoor 07/01/1981

Male

510411

Yes

No

Clear

Dry

No

No

Yes

1

No

Yes

Traffic Police

(Phone) +65-65470000

10 Ubi Avenue 3 Singapore 408865

(Fax) +65-65474900

No

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Manufacturer

Vehicle Model

Vehicle Variant Vehicle Colour

Vehicle Category

NA / Unknown

Accident report SL03226H0007

Page 2 of 17

Name of Driver Contact Number Address Address complement Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver)

Road sign broken

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- 2 This Formmust be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GM Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
- 7. By the ladgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 Consent under the Personal Data Protection Act (PDPA).

Lunderstand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the clams.
- (ii) investigating the accident and/or my claims
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
- (v) complying with applicable law in administering processing handling and/or dealing with my claims

(collectively the 'Purposes')

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms may/are permitted to collect use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents findluding their law yers/law firms), which may be sited outside of Singapore for one or more of the above Purposes

Policyholder's Signature / Date &

17 JUN 2022 Sketch Plan

Driver's Signature (if driver is not the policyholder) / Date

Witnessed by Repo Jenny Lim Personnel

Accident report SL03226H0007

Page 4 of 17

		ces of the						
			report		-	1		·
<u> </u>	Der	price	1000m	NO. }	1 >022	0617	1079	
	i	<u> </u>	V			12.	2	
						71	6	
					The	ankon		
~								
				b the same			7.77	
11.	OF The Party of th					-		
	*		-	-		·		

- Contract	-							
teritoria de la comoción de la comoc	-		2					
	ST. SIF HARMAN							
			-					
					· · · · · · · · · · · · · · · · · · ·			

			All sames and the					
		AT 1						
		Nicesus Augusta						
7.								
	- Service -							
10.000								
						The second secon	- 31515-401	

Declaration

We declare the foregoing particulars are true in every respect

Policyholder's Signature / Date &

Time 17 JUN 2022

Orver's Signature of driver is not the policyholder; / Date & Time

Witnessed by Reporting Centre Personnel Jenny Lim



REPORT OF A TRAFFIC ACCIDENT



Date of Expiry:

22.001111.0220

Police Station Of Origin: Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

Occupation:

Report No. T/20220617/7026

Station Diary No. Vide Report No .: Date/Time Report Made: 17/06/2022 15:17 Informant's Particulars Name of Informant: ENG CHER SUAH 411 PASIR RIS DRIVE 6 #07-389 SINGAPORE 510411 Contact No. ID Type / ID No. Home/Office: Mobile: 98191507 NRIC NO / \$1566752D Nationality: ENGCHERSUAH@GMAIL.COM SINGAPORE CITIZEN Sex: Age: Date of Birth: Type of Informant: 09/05/1962 Driver Male Institution / School Name: Race: Language: Chinese English

Driving Licence Information:

Class: 3

Type of	Non-Injury	Drink tv Drive:	Date/Time of Accident:	Type of Location Straight Road
Accident:	Government Proper	No Drive:	15/06/2022 23:20	Straight Noau
Location:				
BALESTIER	ROAD			
Westher		Poad Surface		Road Speed Limit
		Road Surface Dry		Road Speed Limit:
Weather: Clear Traffic Flow: One Way				Road Speed Limit: Traffic Volume: Moderate

Vehicle No.	Type	Make	Model	Color	Conditio	No of
SLL5425U	Car	LAND ROVER	RANGE ROVER EVOQUE 2.0 TSS	White	Seriously Damaged	

Details of V	ehicle Insurance			
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

Report No. T 202205*7-7026

CONTINUATION OF REPORT

Details of Vehicle Insurance							
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date			
SLL5425U	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	DMPCSNW001876 12101	27/10/2021	26/10/2022			

Details of Perso		137-1772-1744			
Any Pedestrian I					
No. of Pedestriar Driver	ns Injured: NIL	Use of Pedestrian Crossing: NA			
Name	ENG CHER SUAH		ID No.	S1566752D	
Related Vehicle	SLL5425U (Car)		Contact No.	98191507	
Hospital/Clinic	NIL		Class of Driving Licence & Explry	Class: 3 Date of Expiry: NII	
Date	NIL	Date	NIL		
No. of Days gran	ted Medical Leave NIL	Degree of			

Brief Details.

On 15/06/2022 at about 2320 hrs, While I was driving along Balestier Road filter lane to Moulmein Road. Suddenly i felt a car on my right very close to me and i steer my steering to the left and i went up the road kerb and hit the road sign. My car front left portion damaged.



Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000



3 of 3 Report No. T/20220617/7026

CONTINUATION OF REPORT

Informant is	not	able	to	provide	sketc

Sketch Plan

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required. Date/Time: 17/06/2022 15:17				
Signature Of Interpreter: Not applicable					
Officer In Charge Of Case: TP / TPIB / TAY CHUN KEEN Contact No.: 65476436	Classification Of Case:				



Motor Private Car

MX1F

R SN

AN0014A

Cov. Type:C

CERTIFICATE OF INSURANCE

tor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 Road Transport Act. 1987 (Malaysia) Motor Vehicles (Third-Party Risks) Rules. 1959 (Malaysia)

CERTIFICATE No.

DMPCSNW00187612101

Engine No: 090614051842204PT

Index Mark and Registration

Number of Vehicle

Cha. No.:SALVA2AG3FH046158

Date of Expiry of Insurance

SLL5425U

Name of Policy Holder

ENG CHER SUAH

Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment

27/10/2021 (00:00:00)

Named Drivers Ex Sect. I

\$\$750.00

26/10/2022

Additional Ex Other than Named Drivers:

\$\$3,000.00

Ex Sect. I - Age <= 25 Ex Sect. I - Age >= 26

\$\$500.00

* Age as at date of accident

EX ON WINDSCREEN .

\$\$100.00

Persons or Classes of Persons entitled to drive

(a) The Policyholder.

(b) Any other person who is driving on the Policyholder's order or with his permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use:*

Use for social, domestic and pleasure purposes and for the Policyholder's business. The policy does not cover use for hire or reward tuition driving test racing pace-making, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

Excess whichever is applicable for losses occurring outside Singapore (Constructive Total Loss/Theft)

One time Waiver of Excess for the first S\$500 will apply to the Insured and Named Drivers in the event of Own Damage Claim at our Authorised Workshops for each Policy Year

HIRE PURCHASE CO.: STANDARD CHARTERED BANK(S)LIMITED

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please see-reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Issued By:

ASOKA INVĖSTMENT PTE LTD Authorised Officer

Authorised Signatory

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 752D

Vehicle Details

Vehicle No.: SLL5425U

Vehicle to be Exported: Yes

Intended Deregistration Date: 17 Jun 2022

Vehicle Make: LAND ROVER

Vehicle Model: RANGE ROVER EVOQUE 2.0 TSS

Primary Colour: White Manufacturing Year: 2015

Engine No.: 090614051842204PT
Chassis No.: SALVA2AG3FH046158

Maximum Power Output: 177.0 kW (237 bhp)

Open Market Value: \$53,679.00
Original Registration Date: 27 Oct 2015

First Registration Date: 27 Oct 2015

Transfer Count: 1

Actual ARF Paid: \$68,623.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 26 Oct 2025
PARF Rebate Amount: \$44,604.00

Intended COE Rebate Details

COE Expiry Date: 26 Oct 2025

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$61,010.00
COE Rebate Amount: \$20,484.00

Total Rebate Amount: \$65,088.00

The information contained herein is correct as at 17 Jun 2022