



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
GREAT AMERICAN INSURANCE COMPANY 3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Ref: CS/GAI22005850/Uqy3e2 Date: 20/07/2022  Code: GAI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	GBF 551X	Veh. Inspected	VDU 7375
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVC000004184	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	20/06/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	NISSAN X-TRAIL (A)	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	PN8JAAT32TCA51266	Colour	BROWN
Odometer	86315 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	225/65 R17	MICHELIN	7 mm
L/H Front Tyre	225/65 R17	MICHELIN	7 mm
R/H Rear Tyre	225/65 R17	MICHELIN	7 mm
L/H Rear Tyre	225/65 R17	MICHELIN	7 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	16/06/2022	Inspection Date	22/06/2022
Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	