



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22005853/Kqy3e2	Date: 08/08/2022
			Code: AGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SJM 7687K	Veh. Inspected	SKX 1965C
	Policy No.		Coverage (\$)	0.00
	Claim No.	C10015901 /JT	Excess (\$)	0.00
	Assign From	MAYBIE CHUA	Assign Date	20/06/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	HONDA FIT (A)	c.c	1498
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	JHMGK5850GX201139	Colour	METALLIC MAROON
	Odometer	84522 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195/50 R16	BRIDGESTONE	4 mm
	L/H Front Tyre	195/50 R16	BRIDGESTONE	4 mm
	R/H Rear Tyre	195/50 R16	BRIDGESTONE	7 mm
	L/H Rear Tyre	195/50 R16	BRIDGESTONE	7 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	17/06/2022	Inspection Date	21/06/2022
	Survey held at	SIN MING AUTOCARE BFG PTE LTD 176, SIN MING DRIVE #02-05 SIN MING AUTOCARE COMPLEX . SINGAPORE 575721		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	