



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22005854/Evy3e2	
			Date: 15/08/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGU 2378D	Veh. Inspected	SMM 8770K	
Policy No.	D22MTPV01007463	Coverage (\$)	0.00	
Claim No.	CMTD2202105	Excess (\$)	0.00	
Assign From	MELVIN YE	Assign Date	20/06/2022	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E200	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WDD2130422A322786	Colour	GREEN	
Odometer	52894 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/35Z R19	MICHELIN	5 mm	
L/H Front Tyre	275/35Z R19	MICHELIN	5 mm	
R/H Rear Tyre	275/35Z R19	MICHELIN	5 mm	
L/H Rear Tyre	275/35Z R19	MICHELIN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/06/2022	Inspection Date	01/08/2022	
Survey held at	CYCLE & CARRIAGE INDUSTRIES PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	