

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 199607198R GST Reg. No. 19-9607198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Re	ef: CS/AGI22005856/Uvy3m4	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Da	ate: 04/07/2022	
			Co	ode: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SKZ 6851D	Veh. Inspected	SME 1201A	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10015914 /CD	Excess (\$)	0.00	
	Assign From	MAYBIE CHUA	Assign Date	20/06/2022	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA SHUTTLE (A)	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2020	
	Chassis No.	GK82101011	Colour	WHITE	
	Odometer	84622 KM	Steering	AFFECTED	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	205/45 ZR17	HABILEAD	6 mm	
	L/H Front Tyre	205/45 ZR17	HABILEAD	6 mm	
	R/H Rear Tyre	205/45 ZR17	HABILEAD	6 mm	
	L/H Rear Tyre	205/45 ZR17	HABILEAD	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT UNDERCARRIAGE.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	17/06/2022	Inspection Date	20/06/2022	
	Survey held at	FASTECH AUTO PTE LTD			
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a.	5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	b. Estimate Days of Repair				

2 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: