

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No. _____
 at Workshop m/s _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 37k
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SNA3394Y Yr Regn: 28/5 114
 Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Volvo 560 D2 c.c 1560
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 102678 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: XVIFS84ABE2302334
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: NII / S/Rim / STD A/Rim or
 Tyre Size: F: 245/40ZM8
 R: 245/40ZM8
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front 6 mm Rear 6 mm
 R/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 18/6/22 D.O.I. 21/6/22 1700
 Survey held at Sin Auk
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MU: 37k
	rebate: 23800
	NW: 13200
	OP: excess TBC
	not economical to repair, recommend total lose

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report
 1) _____
 Date/Time, File Return to?
 2) _____
 Report Format : _____
 Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____
 Resurvey No. of Trip: _____
 Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)
 Survey Fee: _____
 Transportation: _____
 S + RS, SI
 Photos
 Others
 TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	964F
Vehicle Details	
Vehicle No.:	SNA3394Y
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Jun 2022
Vehicle Make:	VOLVO
Vehicle Model:	S60 D2
Primary Colour:	Silver
Manufacturing Year:	2013
Engine No.:	D4162T2710352
Chassis No.:	YV1F584ABE2302334
Maximum Power Output:	84.0 kW (112 bhp)
Open Market Value:	\$32,298.00
Original Registration Date:	28 May 2014
First Registration Date:	28 May 2014
Transfer Count:	2
Actual ARF Paid:	\$22,218.00 11109
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 May 2024
PARF Rebate Amount:	\$12,219.00
Intended COE Rebate Details	
COE Expiry Date:	27 May 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$60,002.00
COE Rebate Amount:	\$11,581.00
Total Rebate Amount:	\$23,800.00

The information contained herein is correct as at 22 Jun 2022

OK

dp: 13.5

$T_2 = 1125$

14.5 11/23

$1125 \times 2^3 = 25875$

$25875 + 11109 = 36984$

$37k - 23800 = 37k$

$= 13200$

