



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22005902/Kqy3e2	
			Date: 10/08/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBK 1774L	Veh. Inspected	SMQ 466X	
Policy No.	D22MTPCVE000170	Coverage (\$)	0.00	
Claim No.	CMTD2202126/GPL	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	21/06/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	RU11319150	Colour	METALLIC PURPLE	
Odometer	57123 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	2 mm	
L/H Front Tyre	215/60 R16	DUNLOP	2 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	3 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	3 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/06/2022	Inspection Date	21/06/2022	
Survey held at	160 SIN MING DRIVE AUTOCITY #07-17			
Repairer	CAR TIMES AUTOLUTION PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	