

ASS. REC. BY:

REF:

262/22005918/K9y3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

CDMPG22001185

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 90467

Yr Regn:

11, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

c.c

1798

Colour

M.P. White 1Pul

A/C:

Insured / Std / NI / NA

Sp. Reading

403931

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FUH03076032

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder? / Jammed / Leaked / Burnt or

Brake: Inorder? / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

195/65R15

R: Sailun

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8 mm

R/Bal.

9 mm

L/Bal.

8 mm

L/Bal.

5 mm

D.O.A.

18/6/22

D.O.I.

22/6/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

C/S M

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

24/06/22 @ 12.24pm revised to ERGO via Merimen.

Date/Time, File Pass to?

☐

: Prel. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

Fines

Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9046T*Not Withheld
1/1/2022***AAD2206-076**

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

22 JUN 2022**SHD9046T**

JTDKB3FUX03076032

200303878K

TOYOTA

PRIUS

18/06/2022

SMR3785A/ ERGO.

01/11/2018

PART

- 1 PANEL SUB-ASSY, FRONT DOOR, RH
- 1 HINGE ASSY, FRONT DOOR, LOWER RH
- 1 HINGE ASSY, FRONT DOOR, UPPER RH
- 1 TAPE, BLACK OUT, NO.1 FRT RH
- 1 TAPE, BLACK OUT, NO.2 FRT RH
- 1 TAPE, BLACK OUT, NO.3 FRT RH
- 1 WEATHERSTRIP, FRONT DOOR, RH
- 1 FENDER SUB-ASSY, FRONT LH
- 1 LINER, FRONT FENDER, LH
- 1 RIM
- 1 HUB CAP
- 1 ABSORBER ASSY, SHOCK, FRONT RH
- 1 KNUCKLE, STEERING, RH
- 1 ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 RH

LIST

\$	<i>na</i>	1,300.70	X
\$	<i>na</i>	110.60	X
\$	<i>na</i>	97.50	X
\$	<i>na</i>	13.30	X
\$	<i>na</i>	43.50	X
\$	<i>na</i>	26.30	X
\$	<i>na</i>	231.30	X
\$	<i>na</i>	977.80	✓
\$	<i>na</i>	210.30	✓
\$	<i>na</i>	1,900.10	X
\$	<i>na</i>	211.50	X
\$	<i>na</i>	472.30	X
\$	<i>na</i>	663.40	X
\$	<i>na</i>	760.10	X
TOTAL		\$ 1,823.20	
25%		\$ 455.80	
		\$ 1,367.40	

Special Nett

- 1 CLIP(FOR FRONT DOOR TRIM BOARD)
- 1 FRT DOOR STICKER 'TRANSCAB'
- 1 FRT DOOR ADVERTISEMENT
- 1 TYRE
- 1 FENDER LINER CLIP

\$	<i>na</i>	65.00	X
\$	<i>na</i>	100.00	X
\$	<i>na</i>	200.00	X
\$	<i>na</i>	350.00	X
\$	<i>na</i>	65.00	✓
TOTAL		\$ 780.00	

TOTAL PARTS \$ 2,147.40

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9046T**AAD2206-076****LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	301
Putty And Spray Painting Of The Affected Portion.	\$	1,800.00	4401
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	101
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,800.00	2001
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of rear fender panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
TOTAL	\$	4,790.00	
Over All Total	\$	6,937.40	

(PART-BY-PART) Repair Days~~20 Days~~
2 days**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	19/06/2022 18:21 (SGT)
Date of Accident	18/06/2022 15:53 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	Exit balmoral plaza
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD9046T
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Company Reg No	2XXXXX878K
Email Address	claims@transcab.com.sg
Mobile Phone No	(Phone) +65-62876666
Alternative Phone No	(Office) +65-62876666

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	5DR HATCHBACK (AUTO)
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1767

INSURANCE COMPANY


Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	VFX/P2413997
Cover Note Number	NA

DRIVER

Name of Driver	ONG CHEE MING
NRIC No	SXXXX577E

ACCIDENT DIAGRAM

Ver. 30042021



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

VERIFIED BY AJAX MARS (ARC)
REPORTING OFFICER
MOHAMED SAIFULLAH S/O SYED MASOOD

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: