



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: CS/SMO22005960/Kvy3e2 Date: 02/08/2022 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YN 6226G	Veh. Inspected	PA 928D
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2202131/RUC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	22/06/2022
2. Vehicle Particulars & Condition			
Make & Model	VOLVO B11R	c.c	10837
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	YV3T2T126DA160829	Colour	GREY / GREEN
Odometer	458693 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	295/80 R22.5	BRIDGESTONE	9 mm
L/H Front Tyre	295/80 R22.5	BRIDGESTONE	9 mm
R/H Rear Tyre	295/80 R22.5 (D/D)	BRIDGESTONE	9/9/9/9 mm
L/H Rear Tyre	295/80 R22.5 (D/D)	BRIDGESTONE	9/9/9/9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND FRONT WINDSCREEN CRACKED. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	17/06/2022	Inspection Date	05/07/2022
Survey held at	SC AUTO INDUSTRIES (S) PTE LTD 51, SENOKO ROAD SINGAPORE 758133		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	