

ASS. REC. BY: TherayREF: CS / CTI 2200596 / VVY3**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 95k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SK6859AYr Regn: 2411 / 17Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda odysseyc.c 2356Colour: purple

A/C: Insured / Std / NI / NA

Sp. Reading: 154921

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 541MRC1890GC207574Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/55 R17R: 215/55 R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 21/6/22D.O.I. 22/6/22 1700Survey held at Prompt motorsDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

mv: 95krebate: 49794mv: 45206

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

____ S + RS, ____ SI

Photos

Others

TOTAL

PROMPT MOTORS PTE.LTD.

BLK 8 KAKI BUKIT AVENUE 4 #02-16

PREMIER @ KAKI BUKIT

SINGAPORE 415875

UEN: 202214492N

Vehicle number: SLK6859A

Make & Model: Honda Odyssey

Chassis number: JHMRC1890GC207574

No.	Description of spare parts	Qty	Amount S\$	
		1	\$ 1,098.60	DT
1	Tailgate	1set	\$ 113.80	n/c
2	Tailgate windscreen glass rubber moulding	1	\$ 27.80	n/c
3	Tailgate centre emblem	1	\$ 405.60	CRG
4	Tailgate RH lamp assy	1	\$ 405.60	CRG
5	Tailgate LH lamp assy	1	\$ 168.70	n/c
6	Tailgate centre "Odyssey"	1	\$ 180.10	DLS
7	Tailgate number plate lower chrome moulding	1	\$ 165.70	SCR
8	Tailgate number plate garnish	1	\$ 190.30	3ab
9	Tailgate lock	1	\$ 28.50	CR
10	Tailgate lock catch	1	\$ 211.70	Cur
11	Tailgate inner trim board	1set	\$ 60.00	Bonec
12	Tailgate inner trim board clips	1	\$ 10.70	KSIC
13	Tailgate inner pull handle	1	\$ 120.60	Cur
14	Tailgate weatherstrip	1	\$ 108.00	SCR
15	Tailgate switch opener	1	\$ 73.20	SCR
16	Tailgate RH hinge	1	\$ 73.20	SCR
17	Tailgate LH hinge	1	\$ 168.80	SCR
18	Tailgate RH absorber stay	1	\$ 168.80	SCR
19	Tailgate LH absorber stay	1	\$ 734.60	SCR
20	Tailgate reverse camera	1	\$ 557.90	CLP
21	Rear bumper	1	\$ 101.20	SCR
22	Rear bumper RH lower spoiler	1	\$ 101.20	SCR
23	Rear bumper LH lower spoiler	1set	\$ 70.00	Bonec
24	Rear bumper clips	1	\$ 78.90	SCR
25	Rear bumper RH upper cover	1set	\$ 30.00	Bonec
26	Rear bumper RH upper cover clips	1	\$ 78.90	SCR
27	Rear bumper LH upper cover	1set	\$ 30.00	Bonec
28	Rear bumper LH upper cover clips	1	\$ 46.50	CRG
29	Rear bumper RH reflector	1	\$ 46.50	CRG
30	Rear bumper LH reflector	1	\$ 22.30	n/c
31	Rear bumper RH side retainer	1	\$ 22.30	n/c
32	Rear bumper LH side retainer	1	\$ 22.30	n/c

33	Rear bumper RH side reverse sensor	1	\$	267.80	} Rodut
34	Rear bumper RH centre reverse sensor	1	\$	267.80	
35	Rear bumper LH centre reverse sensor	1	\$	267.80	
36	Rear bumper LH side reverse sensor	1	\$	267.80	
37	Rear bumper reverse sensor retainer lock	4	\$	167.20	x 1144
38	RH taillamp assy	1	\$	859.80	x 1145
39	LH taillamp assy	1	\$	859.80	x 1146
40	End panel	1	\$	472.80	x 1147
41	End panel inner garnish	1	\$	106.30	x 1148
42	End panel inner garnish clips	1 set	\$	50.00	x 1149
43	End panel inner garnish centre cover	1	\$	63.00	x 1150
44	Rear buzzer sensor	1	\$	67.70	x 1151
45	Rear smart antenna sensor	1	\$	63.40	x 1152
46	Rear RH radar sensor	1	\$	1,123.60	x 1153
47	Rear RH radar sensor bracket	1	\$	46.80	x 1154
48	Rear LH radar sensor	1	\$	46.80	x 1155
49	Rear LH radar sensor bracket	1	\$	1,123.60	x 1156
50	Rear compartment panel	1	\$	46.80	x 1157
51	Rear compartment panel insulator	1	\$	356.80	x 1158
52	Rear compartment panel top cover board	1	\$	40.70	x 1159
53	Rear RH fender	1	\$	378.10	x 1160
54	Rear RH fender inner trim	1	\$	893.80	x 1161
55	Rear RH fender inner trim clips	1	\$	756.60	x 1162
56	Rear RH fender inner aircon blower	1 set	\$	60.00	x 1163
57	Rear RH fender glass rubber moulding	1	\$	828.60	x 1164
58	Rear LH fender	1	\$	19.80	x 1165
59	Rear LH fender inner trim	1	\$	893.80	x 1166
60	Rear LH fender inner trim clips	1	\$	756.60	x 1167
61	Rear LH fender glass rubber moulding	1 set	\$	60.00	x 1168
62	Exhaust silencer	1	\$	19.80	x 1169
63	Exhaust silencer gasket	1	\$	692.80	x 1170
				45.00	x 1171
			\$	17,624.40	
			Parts less 20%	\$	3,524.88
			Total	\$	14,099.52

5	Rear RH fender glass sealant	1	\$	60.00	* NW
6	Rear RH fender glass inner seal	1	\$	35.00	* NW
7	Rear LH fender joint sealant	1	\$	75.00	* NW
8	Rear LH fender glass sealant	1	\$	60.00	* NW
9	Rear LH fender glass inner seal	1	\$	35.00	* NW
10	Rear compartment panel joint sealant	1	\$	80.00	* NW
11	Rear number plate	1	\$	70.00	* NW BT
			Total:	\$	680.00

No.	Labour and painting	Amount S\$	
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 2,200.00	700
2	Spray painting on affected areas and panels	\$ 1,800.00	600
3	Check wiring and lighting system on affected areas	\$ 100.00	30
4	Apply rust coating chemical on affected areas and panels	\$ 120.00	30
5	Remove and reinstall tailgate windscreen glass to assist repair	\$ 250.00	120
6	Remove and replace tailgate reverse camera to assist repair	\$ 180.00	30
7	Remove and replace rear bumper reverse sensors to assist repair	\$ 120.00	30
8	Remove and replace rear inner trims, garnish and boards to assist repair	\$ 320.00	100
9	Remove and replace exhaust silencer and gasket to assist repair	\$ 150.00	* NW
10	Remove and reinstall rear RH fender glass to assist repair	\$ 150.00	* NW
11	Remove and reinstall rear LH fender glass to assist repair	\$ 150.00	* NW
12	Remove and replace aircon blower and pipes to assist repair. Refill aircon gas	\$ 450.00	* NW
13	Remove and reinstall roof lining, seats, carpet and seat belts to assist repair	\$ 320.00	* NW
14	Reset and calibration radar unit and fault code after repair	\$ 280.00	* NW

--	--

Total: \$ 6,590.00

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Spare Parts: \$ 14,099.52

Special Nett: \$ 680.00

Labour: \$ 6,590.00

Total Amount: \$ 21,369.52

Thavan Chhanta for

82235764

22/6/22 1700

L/S 5 days swp

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

442A

Vehicle Details

Vehicle No.:

SLK6859A

Vehicle to be Exported:

Yes

Intended Deregistration Date:

21 Jun 2022

Vehicle Make:

HONDA

Vehicle Model:

ODYSSEY 2.4 EXV-S CVT SR

Primary Colour:

Purple

Manufacturing Year:

2016

Engine No.:

K24W72013342

Chassis No.:

JHMRC1890GC207574

Maximum Power Output:

129.0 kW (172 bhp)

Open Market Value:

\$32,594.00

Original Registration Date:

24 Jan 2017

First Registration Date:

24 Jan 2017

Transfer Count:

0

Actual ARF Paid:

\$37,632.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

23 Jan 2027

PARF Rebate Amount:

\$26,342.00

Intended COE Rebate Details

COE Expiry Date:

23 Jan 2027

COE Category:

B - Car above 1600cc or 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$51,109.00

COE Rebate Amount:

\$23,452.00

Total Rebate Amount:

\$49,794.00

The information contained herein is correct as at 21 Jun 2022

OK

SK0L226L0005 / KAN FOOK SING MOTOR WORKSHOP [539147]
ENTRY DATE & TIME: 21/06/2022 15:24 (SGT)
SUBMITTED BY: LEK YEE KHENG
VERSION: 1 (21/06/2022 15:24 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	21/06/2022 15:24 (SGT)
Date of Accident	21/06/2022 09:20 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	AYE TOWARDS MCE BEFORE PORTSDOWN AVE EXIT
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLK6859A

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	WAH SIEW GUAN
NRIC No	S1688442A
Email Address	XDETOX32@GMAIL.COM
Mobile Phone No	(Phone) +65-97429339
Alternative Phone No	(Home) +65-97429339

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Odyssey
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2400

INSURANCE COMPANY

Name of Insurance Company	Great Eastern General Insurance Limited
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	2022-V0115057-VDP-R001
Cover Note Number	-

DRIVER

Name of Driver	WAH SIEW GUAN
NRIC No	S1688442A

Date Of Birth	24/11/1965
Occupation	Indoor
Date Of Driving Pass	16/08/2000
Driving experience	21 YEARS AND 10 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97429339
Alt. Phone Number	(Home) +65-97429339
Email Address	XDET0X32@GMAIL.COM
Address	10 BOON LAY DRIVE #13-30 S649929
Address complement	-
Postcode	-
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	WAH KAI LIN KELLY
Gender	Female

PASSENGER 2

Name	WONG KWEE YING
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER ATTACHED REPORT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SML1318K
Vehicle Manufacturer	-

Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	-
Name of Driver	Private car
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJN9773B
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	WAH KAI LIN KELLY
Gender	Female
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	UNKNOWN
Injured person in which vehicle?	SLK6859A
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

INJURED 2

Name of injured person	WONG KWEE YING
Gender	Female
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	UNKNOWN
Injured person in which vehicle?	SLK6859A
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"); the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

X

Policyholder's Signature / Date & Time

Sketch Plan

X

Driver's Signature (If driver is not the policyholder) / Date & Time

21/6/2022
1500 hrs

Witnessed by Reporting Centre Personnel

AYE towards MCE
before ports down AVE
exit

↑ ↑ ↑ ↑

A
B
C

A: SLK6859 A

B: SML1316 K

C: SJN9773 B

AYE Towards MCE Before ports down AVE Exit.

Describe Circumstances of the Accident

In the above stated date and time, I was traveling along ATE
 towards ACE Parking Ports down ave. I was traveling straight when suddenly
 vehicle I collided into vehicle B causing vehicle B to collide onto my
 vehicle rear portion.


Declaration

We declare the foregoing particulars are true in every respect.


X


 Policyholder's Signature / Date &
 Time

X


 Driver's Signature (if driver is not the policyholder) / Date
 & Time 21 / 6 / 2022
 1500 hrs.




 Witnessed by Reporting Centre
 Personnel

