

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

MS FIRST CAPITAL INSURANCE LTD Ref: CS/FCI22005963/Rqy 36 ROBINSON ROAD Date: 15/09/2022 #16-01 CITY HOUSESINGAPORE 068877 Code: FCI2 1. Policy Particulars: - THIRD PARTY CLAIM Insured Veh. YN 9563M Veh. Inspected XE 4551P Policy No. D22099240 Coverage (\$) 0.00 Claim No. D22001876MFCV Excess (\$) 0.00 Assign From HARMINDER KAUR Assign Date 22/06/2022 2. Vehicle Particulars & Condition Make & Model UD TRUCKS GKB5ALDHCQA c.c 10836 Engine No. HIDDEN Year of Reg. 2018 Chassis No. JNCMBP0A7KU038392 Colour BLUE Odometer 212668 KM Steering IN ORDER Brakes IN ORDER Modification NIL	3m4
#16-01 CITY HOUSESINGAPORE 068877 Code: FCI2 1.	
1. Policy Particulars:- THIRD PARTY CLAIM Insured Veh. YN 9563M Veh. Inspected XE 4551P Policy No. D22099240 Coverage (\$) 0.00 Claim No. D22001876MFCV Excess (\$) 0.00 Assign From HARMINDER KAUR Assign Date 22/06/2022 2. Vehicle Particulars & Condition Make & Model UD TRUCKS GKB5ALDHCQA c.c 10836 Engine No. HIDDEN Year of Reg. 2018 Chassis No. JNCMBP0A7KU038392 Colour BLUE Odometer 212668 KM Steering IN ORDER Brakes IN ORDER Modification NIL	
Insured Veh. YN 9563M Veh. Inspected XE 4551P	
Policy No. D22099240 Coverage (\$) 0.00 Claim No. D22001876MFCV Excess (\$) 0.00 Assign From HARMINDER KAUR Assign Date 22/06/2022 2. Vehicle Particulars & Condition Make & Model UD TRUCKS GKB5ALDHCQA c.c 10836 Engine No. HIDDEN Year of Reg. 2018 Chassis No. JNCMBP0A7KU038392 Colour BLUE Odometer 212668 KM Steering IN ORDER Brakes IN ORDER Modification NIL	
Claim No. D22001876MFCV Excess (\$) 0.00 Assign From HARMINDER KAUR Assign Date 22/06/2022 2. Vehicle Particulars & Condition Make & Model UD TRUCKS GKB5ALDHCQA c.c 10836 Engine No. HIDDEN Year of Reg. 2018 Chassis No. JNCMBP0A7KU038392 Colour BLUE Odometer 212668 KM Steering IN ORDER Brakes IN ORDER Modification NIL	
Assign From HARMINDER KAUR Assign Date 22/06/2022 2. Vehicle Particulars & Condition Make & Model UD TRUCKS GKB5ALDHCQA c.c 10836 Engine No. HIDDEN Year of Reg. 2018 Chassis No. JNCMBP0A7KU038392 Colour BLUE Odometer 212668 KM Steering IN ORDER Brakes IN ORDER Modification NIL	
2. Vehicle Particulars & Condition Make & Model UD TRUCKS GKB5ALDHCQA c.c 10836 Engine No. HIDDEN Year of Reg. 2018 Chassis No. JNCMBP0A7KU038392 Colour BLUE Odometer 212668 KM Steering IN ORDER Brakes IN ORDER Modification NIL	
Make & ModelUD TRUCKS GKB5ALDHCQAc.c10836Engine No.HIDDENYear of Reg.2018Chassis No.JNCMBP0A7KU038392ColourBLUEOdometer212668 KMSteeringIN ORDERBrakesIN ORDERModificationNIL	
Engine No. HIDDEN Year of Reg. 2018 Chassis No. JNCMBP0A7KU038392 Colour BLUE Odometer 212668 KM Steering IN ORDER Brakes IN ORDER Modification NIL	
Chassis No. JNCMBP0A7KU038392 Colour BLUE Odometer 212668 KM Steering IN ORDER Brakes IN ORDER Modification NIL	
Odometer 212668 KM Steering IN ORDER Brakes IN ORDER Modification NIL	
Brakes IN ORDER Modification NIL	
General FAIR	
3. Conditions of Tyres	
Size Make Balance	
R/H Front Tyre 295/80 R22.5 GITI 8 mm	
L/H Front Tyre 295/80 R22.5 GITI 8 mm	
R/H Rear Tyre 295/80 R22.5 (D/D) GITI 8/8 mm	
L/H Rear Tyre 295/80 R22.5 (D/D) GITI 8/8 mm	
4. Description of Damages	
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.	
DAMAGES SEE DETAILS.	
5. General Information	
Accident Date 16/06/2022 Inspection Date 23/06/2022	
Survey held at UD TRUCKS SINGAPORE (PTE) LTD	
12 TUAS AVENUE 10, SINGAPORE 639136	
5a. Remarks	
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.	
5b. Estimate Days of Repair	
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days	