





INSURER:

**ECICS Limited (HQ)**

**PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	MPC21B00019900	Date of Loss:	17/06/2022
Vehicle Reg. No.:	SLR3717J	Driveable?	
Driver Age/Info:	35 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LEE MAY LING	Contact No:	+6597686353
Driver:	LEE MAY LING		
Make/Model:	MITSUBISHI SPACE STAR, 1.2 CVT (A)	Vehicle Reg. Date:	14/08/2017
Vehicle Colour:	Green		
Engine No:	3A92UGD8138	Chassis No:	MMCXTA03AGH049754
Odometer:	20032 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	RICARDO AUTO CENTRE PTE LTD (HQ)		

**COST OF CLAIMS**

	Amount
Parts	3,329.70
Miscellaneous Items	0.00
Labour	1,600.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>4,929.70</b>
<b>+ GST 7.00% (S\$)</b>	<b>345.08</b>
<b>Nett Amount (S\$)</b>	<b>5,274.78</b>

This claim is handled by: **GRACE TAN KIAN ANN**

# Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO FOCUS HEADLAMP	New	30.00 ✓
2	TO CUT, WELD & STRAIGHTEN FRONT PORTION OF CAR CAUSED BY ACCIDENT. ADJUST & REPLACE DAMAGE PARTS.	New	<del>650.00</del> 400
3	TO SERVICE AIRCON SYSTEM, VACUUM & TOP UP GAS.	New	120.00 X
4	TO SPRAY PAINT ON REPAIRED AREAS	New	<del>800.00</del> 400
Gross Labour Cost (\$)			1,600.00

Ricardo Auto Centre Pte Ltd/SLR3717J/22/06/2022 16:50. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Rare

Hp 90010068

4 days

L/S

23/06/22

@1415

EXCESS: TBA

Repeat

Resurvey after repair



## PAIR DETAILS

### Reference

**Part Source:** MRM-SG      **Version:** 1.0 (Last Synchronised: 22 Jun 2022)  
**Parts:** 144      **MITSUBISHI SPACE STAR 1.2 CVT (A) (Catalogue:Merimen Singapore 1.0)**  
**Labour:** Repairer's      **(Price-denominated Standard List)**  
**Print Code:** Ricardo Auto Centre Pte Ltd/SLR3717J/22/06/2022 16:50  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*LH FRONT FENDER <i>ht</i>	0.00	0.00	*230.00 F
2	1		*LH FRONT FENDER SHIELD <i>?</i>	0.00	0.00	*65.00 F
3	10		*LH FRONT FENDER SHIELD CLIPS <i>ru</i>	0.00	0.00	*30.00 F
4	1		*BONNET INSULATOR <i>X</i>	0.00	0.00	*90.00 F
5	10		*BONNET INSULATOR CLIPS <i>X</i>	0.00	0.00	*30.00 F
6	1		*HEAD LAMP - LH <i>cm</i>	0.00	0.00	*1,200.00 F
7	1		*FRONT BUMPER <i>cm</i>	0.00	0.00	*450.00 F
8	1		*FRONT BUMPER REINFORCEMENT <i>?</i>	0.00	0.00	*210.00 F
9	10		*FRONT BUMPER CLIPS <i>ru</i>	0.00	0.00	*35.00 F
10	1		*FRONT BUMPER SIDE RETAINER LH <i>cm</i>	0.00	0.00	*10.00 F
11	1		*FRONT BUMPER FOG LAMP LH <i>3 scd</i> (FOG LAMP COVER)	0.00	0.00	*38.00 F
12	1		*FRONT BUMPER FOG LAMP GARNISH SIDE LH <i>scd</i>	0.00	0.00	*68.00 F
13	1		*HEAD LAMP SUPPORT LH <i>?</i>	0.00	0.00	*55.00 F
14	1		*FRONT SUPPORT PANEL <i>X</i>	0.00	0.00	*450.00 F
15	1		*FENDER EMBLEM <i>ru</i>	0.00	0.00	*38.00 F
16	1		*FENDER CHROME GARNISH <i>ru</i>	0.00	0.00	*28.00 F

F=Franchise part.

Sub Total (\$\$)	3,027.00
+ Margin on L,N Items 10.00% (\$\$)	302.70
<b>Total Parts (\$\$)</b>	<b>3,329.70</b>

Ricardo Auto Centre Pte Ltd/SLR3717J/22/06/2022 16:50. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	17/06/2022 18:44 (SGT)
Date of Accident	17/06/2022 12:05 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	ANN SIANG ROAD
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number SLR3717J

### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	LEE MAY LING
NRIC No	SXXXX268J
Email Address	LEEMAYLING87@GMAIL.COM
Mobile Phone No	(Phone) +65-97686353
Alternative Phone No	(Office) +65-91131640

### VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	SPACE STAR
Variant	1.2 CVT
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1193

### INSURANCE COMPANY

Name of Insurance Company	ECICS Limited
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	MPC21B00019900
Cover Note Number	-

### DRIVER

Name of Driver	LEE MAY LING
NRIC No	SXXXX268J

Date Of Birth	10/06/1987
Occupation	Indoor
Date Of Driving Pass	15/08/2006
Driving experience	15 YEARS AND 10 MONTHS
Gender	Female
Mobile Number	(Phone) +65-97686353
Alt. Phone Number	(Office) +65-91131640
Email Address	LEEMAYLING87@GMAIL.COM
Address	BLK 1E CANTONMENT ROAD #41-57
Address complement	-
Postcode	085501
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO SKETCH PLAN

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLT2585T
Vehicle Manufacturer	Toyota
Vehicle Model	Prius
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	CHEW WEI SIONG
Contact Number	-
Address	-
Address complement	-



Postcode  
Insurance Company Name  
Nature Of Damage  
Details of property damaged in accident  
No. Of Passenger (Including Driver)

-  
-  
-  
-  
1

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

*[Signature]*  
Policyholder's Signature / Date & Time

*[Signature]* 17/06/22  
Driver's Signature (If driver is not the policyholder) / Date & Time


*[Signature]*  
Witnessed by Reporting Centre Personnel

**Sketch Plan**

A: SLR3717J

B: SLT2585T

*Kent*



Ann Siang Road

URA Centre East Wing Bldg.



### Describe Circumstances of the Accident


On 17/06/2022, I was driving my vehicle, SLR 3717J, and exiting The URA Centre East Wing carpark on Ann Siang Road. After exiting the carpark gantry, I turned right onto Ann Siang Road. There was only one lane in the direction I was driving. As I turned into the road, a silver Toyota vehicle (SLR 2585T), which I later realised was a Grab car, had come to a ~~stop~~ stop as he was picking up passengers from the kerb side.

I did not realise he would be stopping on the narrow one lane road and my left front bumper hit the right side of his car as there was no space for me to avoid the collision on the narrow road.


There were no passengers in his car at the time of the accident. There was also no injury to the driver or to myself.

### Declaration

We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature / Date & Time  
17/06/22

Driver's Signature (If driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	268J
Vehicle No.:	SLR3717J
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Jun 2022
Vehicle Make:	MITSUBISHI
Vehicle Model:	SPACE STAR 1.2 CVT
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	3A92UGD8138
Chassis No.:	MMCXTA03AGH049754
Maximum Power Output:	59.0 kW (79 bhp)
Open Market Value:	\$14,620.00
Original Registration Date:	14 Aug 2017
First Registration Date:	14 Aug 2017
Transfer Count:	1
Actual ARF Paid:	\$5,000.00
OPC Cash Rebate Eligibility:	No
OPC Cash Rebate Eligibility Expiry Date:	-
OPC Cash Rebate Amount:	-
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Aug 2027
PARF Rebate Amount:	\$3,750.00
COE Expiry Date:	13 Aug 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$27,002.00
COE Rebate Amount:	\$13,871.00
Total Rebate Amount:	\$17,621.00

The information contained herein is correct as at 24 Jun 2022

OK



# Mitsubishi Space Star 1.2A

## Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)**Price****\$81,800****Depreciation** ⓘ

\$9,240 /yr

[View models with similar depre](#)**Reg Date**

22-Jan-2021

(8yrs 6mths 28days COE left)

**Mileage**

13,000 km (9.2k /yr)

**Manufactured** ⓘ

2020

**Road Tax** ⓘ

\$506 /yr

**Transmission**

Auto

**Dereg Value** ⓘ\$38,607 as of today ([change](#))**OMV** ⓘ

\$15,401

**COE** ⓘ

\$40,609

**ARF** ⓘ

\$5,000

**Engine Cap**

1,193 cc

**Power**

59.0 kW (79 bhp)

**Curb Weight** ⓘ

910 kg

**No. of Owners** ⓘ

1

**Type of Vehicle**[Hatchback](#)