



Service Request Details

Claim

S2M044SU

Reference

CS3/ASM22005987/Rqy3 

Loss Date

20 June 2022

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

22 Jun 2022 1:00:36 PM

Request Date

23 June 2022

Due Date

23 June 2023

Services

Pre-Repair Survey

Actions

Next Step

Finish the work

[More ▾](#)

Vehicle Information

Incident Vehicle Registration

FBT2305D

Make

TPVD

Model

Yamaha

Service Address

,,,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

OH Vale

vale.oh@axa.com.sg

Additional Instructions

[Messages2](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)

TYPE 

SENT 27/6/22 3:16 PM

FROM LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT TP PRS IA OF VEHICLE FBT 2305D UPLOADED

BODY Dear Vale, please be informed that the TP PRS IA o...



TYPE 

SENT 23/6/22 2:33 PM

FROM LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT S2M044SU_THANK YOU FOR THE ASSIGNMENT

BODY DEAR VALE, THANK YOU FOR THE ASSIGNMENT. ARRANGE ...

