

(08/11/13) wef

ASS. REC. BY: *Pam*

REF:

C8/CT1220059A3/Rty3

C
961K

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SNE 4902D

at Workshop m/s

my car consultant

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

151K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNE 4902D

Yr Regn:

2022 MAR

Type M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA COROLLA ALTIS HYBRIDELE 1798

Colour:

GREEN

A/C: Insured / Std / NI / NA

Sp. Reading

17932

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR2B Z3BE 200608702

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

21/06/22

D.O.I.

23/06/22

Survey held at

my car consultant

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair Limit - 67K

09/09/2022 Finalise L/S \$7,550.00 ; 10 days (Red \$11,875.00 / 61%)

Date/Time, File Pass to?



Preli. Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1)

Date/Time, File Return to?



Final Report

2)

Add Fee:



Site Insp (\$

) S + RS, SI



Interview (\$

) Photos



Tech. Invs (\$

) Others



Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL