ASSIGNMENT Veh No: SNE 49020 Yr Regn: 2022 MARK Estimated Cost: OD / TP / WS / TP RES / OD RES / EVA / INV / MV To Inspect Vehicle No: SNE 46020 at Workshop m/s MY CAR CONSULTANT of ASSIGNMENT Veh No: SNE 49020 Yr Regn: 2022 MARK Type (M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or Make: TOYOTA COLOUM ALTS HYMADE (E. 1798) Colour GALM A/C: Insured / Std / NI / NA Sp.Reading 7932 T/Radio: Insured / Std / NI / NA	(08/11/13) wef REF: CS/CN2201	05993 Rty3	c abik
From: Estimated Cost: OD / TP / WS / TP RES / OD RES / EVA / INV / MV To Inspect Vehicle No: SNE 4602D at Workshop m/s My Car Consultant Of Veh No: SNE 4902D Yr Regn: 2022 ImmsR Type (M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or Make: Toyota Consultant Colour AITS Hybrid Ede 1798 Colour GRAY A/C: Insured / Std / NI / NA Sp.Reading 17932 T/Radio: Insured / Std / NI / NA		IGNMENT	7013
C/No: MR2B Z3 RF 2006 0 8 762 C/No: MR2B Z3 RF 2006 0 8 762 Gen. Cond: Good (Fair Poor / Burnt Steering: Norder / Jammed / Leaked / Burnt or Brake: Inorder / Jammed / Leaked / Burnt or Modi: Nil S/Rim / STD A/Rim or Tyre Size: F: 225 / 45 R T) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: STD A/Rim or Tyre Size: F: 225 / 45 R T) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: STD A/Rim or Tyre Size: F: 225 / 45 R T) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: STD A/Rim or Tyre Size: F: 225 / 45 R T) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: STD A/Rim or Tyre Size: F: 225 / 45 R T) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: STD A/Rim or Tyre Size: F: 225 / 45 R T) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: STD A/Rim or Tyre Size: F: 225 / 45 R T) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: STD A/Rim or Tyre Size: F: 225 / 45 R T) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: STD A/Rim or Tyre Size: F: 225 / 45 R T) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: STD A/Rim or Tyre Size: F: 225 / 45 R T) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: STD A/Rim or Tyre Size: F: 225 / 45 R T) Remark: The veh had commenced its repair at the time of inspection.	From: Date: Estimated Cost: OD / TP / WS / TP RES / OD RES / EVA / INV / MV To Inspect Vehicle No: SNG 4602D at Workshop m/s MY CAR CONSULTANT of Insured: Policy No. Claims No. Sum Insured: Excess: (Client's Record) Make of Veh: (Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: SNG No Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est. Repairs: days Res.: Yes or No Lum Sum: % 3 Val.: Yes or No A / REV / REP. / 24 HRS Vehicle: IN / OUT ate: Person Contacted:	Veh No: SNG 49 Type M.Car / M.Cycle / Bus / V Truck / Trailer or Make: The Tx Colour Colour Gray Sp.Reading 17 932 Eng/No: C/No: Mr. 25 23 Gen. Cond: Good / Fair Poor / Steering: Morder / Jammed / Lo Brake: Inorder / Jammed / Lo Modi: Nil SRim / STD A/R Tyre Size: F: R: BS (DUN) EXNOVA / GY / FS / TOYO / YOKO or Front R/Bal. mm D.O.A. 21 66 22 Survey held at M. Des. of Damages: Frt (Rear)	AC: Insured / Std / NI / NA T/Radio: Insured / Std / NI / NA T/Radio: Insured / Std / NI / NA BE DOGOS TOD / Burnt eaked / Burnt or eaked / Burnt or Rim or 275/45RT / LIZA / MIC / OHTSU / PIR / SUMI / Bear R/Bal. D.O.I. 23/06/22 4 CAC COUSULTANT
	: Final Report Final Report Final Report File Return to? Add Fee:	Resurvey No. of Trip:	Survey Fee: Transportation:)S +RS,SI) Photos
Resurvey No. of Trip: Survey Fee: Transportation: Add Fee: Site Insp (\$)S+RS,SI	그 아마하는 그림생들은 다. 내 된 프로게 내용되어 보이다. 아마웨어스 회사는 내용하여 어느 전략을 모르게 되었다. 그 사람은	: Tech. Invs (\$) Others
Days Of Repair: Survey Fee: Transportation: Site Insp (\$)S+RS,S Capport Format : Took Inve (\$) Photos)	: Weekend (\$)
Days Of Repair: Survey Fee: Transportation: Add Fee: Site Insp (\$)s+Rs,s			TOTAL

MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE #05-68 S737896

HP: 98888885

Estimation

Date:

24/6/2022

Vehicle:

SNE4902D

Make / Model: Chassis No:

TOYOTA ALTIS CHINA TAIPING

No.	Description	Unit	Ur	nit Price		Amount
	Parts Replacement:	, h.		V 1	1	- 1
1	BOOTLID 51/	1	\$:	1,125.00	\$	1,125.00
2	BOOTLID INNER TRIM 🔨	1	\$	359.00	\$	359.00
3	BOOTLID REFLECTOR C/W CHROME CM	2	\$	456.00	\$	912.00
4	BOOTLID STOPPER No.	4	\$	75.00	\$	300.00
5	BOOTLID TOP LOCK	1	\$	398.00	\$	398.00
6	BOOTLID TOP LOCK COVER &	1	\$	68.00	\$	68.00
7	BOOTLID OUTER CHROME MOULDING CENTRECA	1	\$	312.00	\$	312.00
8	BOOTLID LOWER LOCK 5}	1	\$	39.00	\$	39.00
9	BOOTLID WEATHER STRIP MY	1	\$	220.00	\$	220.00
10	BOOTLID LOGO NA	1	\$	74.00	\$	74.00
11	BOOTLID EMBLEM 'ALTIS' NV	1	\$	65.00	\$	65.00
12	BOOTLID SENSOR CM	1	\$	312.00	\$	312.00
13	BOOTLID EMBLEM 'COROLLA' A	1	\$	65.00	\$	65.00
14	BOOTLID NUMBER PLATE LAMP #	21	\$	62.00	\$	124.00
15	TAILAMP C/W CHROME & CM	2	\$	612.00	\$	1,224.00
	17 11 2 11 11 2 1 1 1 1 1 1 1 1 1 1 1 1		 			644.00

644.00 322.00 | \$ 16 TAILAMP LOWER PANEL 51/ 698.00 \$ 698.00 \$ REAR BUMPER CM 1 17 112.00 | \$ 2 \$ 224.00 REAR BUMPER SIDE RETAINER 🗡 18 REAR BUMPER BRACKET 5 2 \$ 168.00 326.00 19 762.00 S/N200 REAR BUMPER SENSOR AW/ 2 \$ 381.00 | \$ 20 REAR BUMPER SENSOR WIRE HARNESS 🗡 \$ 587.00 | \$ 1 587.00 21 REAR BUMPER REINFORCEMENT \$ 1 395.00 | \$ 395.00 22 REAR BUMPER REFLECTOR

✓ 2 \$ 112.00 \$ 224.00 23 REAR BUMPER UNDERCOVER 🗡 \$ 315.00 1 \$ 315.00 24 \$ AIR VANT 🗲 1 65.00 | \$ 25 65.00 REAR FENDER LH-report \$ 1,024.00 26 \$ 2,048.00 27 REAR FENDER COWLING

✓ 2 \$ 716.00 358.00 REAR FENDER INNER TRIM 28 2 \$ 398.00 796.00 29 REAR WINDSCREEN MOULDING # X \$ 1 112.00 112.00 REAR END PANEL St 30 1 \$ 695.00 695.00 31 END PANEL TOP GARNISH 1 \$ 278.00 \$ 278.00 32 REAR FLOOR PANEL 1 \$ 1,025.00 1,025.00 33 REAR SPARE TYRE TOP BOARD 1 \$ 357.00 357.00 34 REAR SPARE TYRE TOP SPONGE 1 \$ 358.00 \$ 358.00 35 **REAR EXHAUST PIPE HEAT SHIELD** 1 398.00 \$ 398.00 16,620.00 \$ **Less 25%** 4,155.00 **Total** 12,465.00

		_					
	S/Nett items:						7 0
1	REAR NUMBER PLATE	1	\$	50.00	\$	50.00	>>
2	BOOTLID INSULATOR CLIPS No /	1	\$	30.00	\$	30.00	
3	TAILAMP CLIPS SET nu			40.00	\$	20.00	20 A
4	REAR FENDER SEALANT 🗡			150.00	\$	150.00	×
5	REAR FENDER COWLING CLIPS SET 🗡			50.00	\$	30.00	χ 3υ
6	REAR FENDER INNER TRIM CLIPS SET 🗸			50.00	\$	92.00	7 0
7	REAR WINDSCREEN SEALANT 🗡			80.00	\$	80.00	X
8	REAR WINDSCREEN INNER SEAL ★			80.00	\$	00.00	×
9	REAR END PANEL TOP GARNISH CLIPS //	1	\$	30.00	\$	30.00	E. U.
10	REAR END PANEL SEALANT NA /	1	\$	120.00	\$	120.00	40
11	REAR SPARE TYRE PANEL SEALANT	1	\$	150.00	\$	150.00	Y
12	REVERSE CAMERA	1	\$	400.00	\$	400.00	
					\$	3,060.00	13077
	Labour to:					1,600.00 1,600.00	12/22
1	SPRAY PAINTING ON AFFECTED AREAS	1	_	1,600.00	\$	1,600.00	1300
2	PANEL BEATING ON AFFECTED AREAS			1,600.00	\$	1,600.00	60
3	REMOVE AND REFIR REAR BOOTLID MECHANISM		\$	100.00	\$	100.00	~
4	REMOVE AND REFIR REAR EXHAUST SYSTEM		\$	150.00	\$	150.00	1 /2
5	REMOVE AND REFIR REVERSE SENSOR	1	\$	100.00	\$	100.00	60
6	REAR CHASSIS ALIGNMENT	1	\$	200.00	\$	200.00	1 <u>~</u>
7	TO CHECK ELECTRICAL WIRING	1	\$	100.00	\$	100.00	30
8	APPLY ANTI RUST ON AFFECTED AREAS	1	\$	50.00	\$	50.00	
		4	$oxed{oxed}$		\$	3,900.00	
	The second secon				_		1
	Parts Replacement Amount			\$	15,525.00		
	Total A	nount f	or La	abour	\$	3,900.00	
					<u> </u>		1
	Ze	To	tal A	Mount	Ś	19,425.00	1

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Paral Hp 90010068 10 days 4|S 23|66|22 A1610 Ress after repar



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

- 2. This Form must be completed by the Policyholder and/or the Authorised Driver 2. This rount must be a struthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission

Date of Accident

Exact Location of Accident

Additional Location Information

Country/State of Loss

21/06/2022 17:18 (SGT) 21/06/2022 12:00 (SGT)

LUMENS AUTO PTE LTD

kokhow.tay@lumens.sg

(Phone) +65-97360903

(Office) +65-87781765

TPE, Singapore

SLIP ROAD FROM TPE(SLE) TOWARDS CTE(CITY)

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SNE4902D

2XXXXX961K

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

Company Reg No

Email Address

Mobile Phone No.

Alternative Phone No

VEHICLE PARTICULARS

/lanufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of

Are you claiming under your own insurance policy for repair to

your vehicle?

Vehicle Category

Transmission

CC

Toyota

Corolla

ALTIS HYBRID ELEGANCE(AUTO)(2WD)

Private hire

No - Claiming third party

Private hire

ThirdParty

21-MM000794-R00

Yes

Auto

1798

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage

Fleet Policy

Policy Number

Cover Note Number

DRIVER

Name of Driver

NRIC No

POW CHOON PING (BAO CHUNBIN) SXXXX342C

Tokio Marine Insurance Singapore Ltd

Accident report SJ04226L000L

te Of Birth 10/12/1973 ccupation Outdoor nate Of Driving Pass 06/03/1998 **Driving** experience 24 YEARS AND 3 MONTHS Gender Male Mobile Number (Phone) +65-97360903 Alt. Phone Number **Email Address** kokhow.tay@lumens.sg **Address** BLK 303A ANCHORVALE LINK #10-82 Address complement Postcode 541303 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Hirer Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT **Chain Collision** Type of Accident Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No PASSENGER 1 **PASSENGER** Male Gender PASSENGER 2 **PASSENGER** Name Male Gender ASSENGER 3 **PASSENGER** Name Female Gender **DETAILS OF POLICE ACTION** No Was the accident reported to the police?

Was the accident reported to the police?

Was notice of intended Prosecution given?

No
If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

ON 21/06/2022 AT ABOUT 1200HRS, I WAS DRIVING IN VEHICLE A ALONG SLIP ROAD TOWARDS CTE(CITY) /YIO CHU KANG ROAD FROM TPE. AS I WAS DRIVING ON THE RIGHT LANE OF A 2 LANE ROAD, A VEHICLE IN FRONT OF ME APPLIED ITS BRAKES. VEHICLE A THEN APPLIED BRAKES AND SLOWED DOWN. MOMENTS LATER, VEHICLE A WAS REAR ENDED BY VEHICLE B. WHEN I WAS ALIGHTING FROM MY VEHICLE, I NOTICED THAT IT WAS A 6 CAR CHAIN COLLISION INVOLVING VEHICLE C, VEHICLE D, VEHICLE E AND VEHICLE F. NOBODY WAS INJURED AT THE TIME OF ACCIDENT.

ATTACHMENT(S)

Are accident photos available for attachment?

Yes



as there any video captured by Car Camera? vas there any audio recorded?

Yes No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Manufacturer Vehicle Model

Vehicle Variant Vehicle Colour

Vehicle Category Name of Driver

Contact Number

Address

Address complement

Postcode

Insurance Company Name Nature Of Damage

Details of property damaged in accident

No. Of Passenger (Including Driver)

SJR6299C

Private car

ROY

(Phone) +65-92716299

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

Vehicle Manufacturer Vehicle Model

Vehicle Variant

Vehicle Colour Vehicle Category

Name of Driver

Contact Number

Address

Address complement

Postcode

Insurance Company Name Nature Of Damage

Details of property damaged in accident

No. Of Passenger (Including Driver)

SLU2173T

Private car

TERENCE

(Phone) +65-91115268

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

√ehicle Manufacturer

Vehicle Model

Vehicle Variant

Vehicle Colour

Vehicle Category

Name of Driver

Contact Number

Address

Address complement

Postcode

Insurance Company Name

Nature Of Damage

Details of property damaged in accident

No. Of Passenger (Including Driver)

SLZ470Y

Private car

STEVEN

(Phone) +65-92706561

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number

SMU1336K

Vehicle Manufacturer

Vehicle Model

Vehicle Variant

Vehicle Colour

Accident report SJ04226L000L

Page 3 of 21

Incle Category
Inter of Driver
Inter of Driver
Inter of Driver
Inter of Driver
Indices
Insurance Company Name
Insurance Company Name
Insurance Of Damage
Insurance Of Damage
Insurance Company Name
Inter of Damage
Insurance Company Name
Insurance Company

DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number FBQ5627X Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Motorcycle Name of Driver **YAZID** Contact Number (Phone) +65-93361121 Address Address complement Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy hability on the part of the insurance companies
- 5. Any false reporting may be referred to the Police for investigation
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act(PDPA)

l understand, acknowledge, agree and consent that :

- (a) My insurer , my w orkshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) w ho have insured vehicle(s) involved in this accident (all insurer(s) w ho have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of ;
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to
- (i) investigating the accident and/or my claims;
- (ii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, involces, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the increase and/or GIA to their third party service providers or agents for one or more of the above Purposes. (including their law yers/law firms), which may be sit-


FLASH ACCIDENT REPORTING OFFICE FRO LATIFF

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date 21/06/2072

Witnessed by Reporting Centre Personnel

Sketch Plan



> Back to One Motoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Owner ID;	五五天 201K 医自己多类的 中華 中華 里里里里面 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Achicle Na.	SNE4902D
/ehicle to be Exported:	等等表 Nopen 在在在上上,在这里里里的时间,我们们们们
ntended Deregistration Date:	25 Jun 2022
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS HYBRID ELEGANCE(AUTO)(2WD)
Primary Colour:	Silver
Manufacturing Year:	2021
Engine No.:	2ZRY791310
Chassis No.:	MR28Z3BE200000702
Maximum Power Output:	90.0kW (120 Hp)
Open Market Value:	\$26,740.00
Original Registration Date:	18 Mar 2022
First Registration Date:	18 Mar 2022
Transfer Count: -	
Actual ARF Paid:	\$14,436.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Mar 2032
PARF Rebate Amount:	\$10,827.00
COE Expiry Date:	17 Már 2032
COE Category:	B - Car above 1600cc or 97kW (130thp)
COE Period(Years):	10
QP Paid:	\$80,401.00
COE Rebate Amount:	\$78,180.00
Total Rebate Amount:	\$89,007.00

Toyota Corolla Altis Hybrid 1.8A Elegance

Overview

Financial Accessories Similar

Research Photos

Wap



Price

691249251(1)(1)

Depreciation

. 616) <u>(</u> 180) ///[View models with similar depre Reg Date

26-Mar-2021 (8yrs 9mths COE left)

Mileage

10,800 km (8.6k /yr)

Manufactured

2020

Road Tax

\$976 /yr

Transmission

Auto

Dereg Value

\$54,853 as of today (change)

Fuel Type

Petrol-Electric

COE

\$47,001

OMV

\$29,487

Engine Cap 1.798 cc

ARF

\$18,282

OurbWeight -

+1,410 ka

Power

90.0 kW (120 bhb)